

Schedule XLV-Form No. 134

FDR

MB. No. - 62

Year - 2021-22

Milkiya Maya do

Milkiya Maya Road

DIVISION

SUB-DIVISION

Block - Dhany dakh

Measurement Book

Dhamdaha DIVISION

Dhamdaha SUB-DIVISION

mulla'ya Maye tola to mulla'ya
main road

MEASUREMENT BOOK

No. - 82

प्रमाणित किताब है कि इस माप
पुस्तक में 'मुद्रित' 111 50 यत्न है '48'
माप पुस्तक अर्द्ध मध्यम 48/100
अमरावती 5 यत्न किताब किताबाली

Name of Officer

Date of first entry

Executive Engineer

Date of last entry

Rural Works Department

Works Division, Dhamdaha (Pune)

05/10/21

Name to work— 1
 Situation of work—
 Agency by which work is executed—
 Date of measurement—
 No. and date of agreement.
 (These four lines should be reported at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of item
	No.	L.	B.	D.	
NAME of WORK: I. D. P.					
(Mortable & Restoration of Road Milkya Nya Tola to Milkya main Road.					
Agency:-					
(RECORD-ENTRY)					
1/1 Construction of embankment from Borrow Pit					
(a) 4 M x (1.15 + 0.75) M x 45					
		2			

$\times (0.45 + 0.35) M = 1.52 M^3$				
		2		
(b) Edge - 3.20 M x (1.15 + 0.75) M				
			2	
$\times (0.45 + 0.35) M$				
		2		$= 1.22 M^3$
Total = 2.74 M ³				
2 - Providing brick ball including spreading and Laying.				
(a) 4 M x (3.2 + 1.5) x				
(Full)		2		1.
(1.85 + 1.75) M				
		2		$= 17.64 M^3$

Continuation

28-1
Executive Engineer
Rural Works Department
Works Division Dindga (Pune)

[illegible]

Scanned with CamScanner

Particulars	Details of actual measurement				Contents of area
	No.	I.	II.	III.	
NAME OF WORK: J. D. R. Montabla's Restoration of Road Milliya Naya Tolna To Milliya main Road.					
Agency:-					
ABSTRACT OF COST/					
1/1 construction of					
embankment from					
Borrow Pit to Lead					
up to 1000 meter					
2.74 m ³ Qty vide on					
P-01 Item No (01)					
@ Rs - 171.03/m ³					
					B-46920

2/2 Providing Bmckhd					
including, spreading					
and Laying 46.82					
m ³ Qty vide on P-02					
Item No - (02) @					
B 2188 = 35/m ³					

					B. 102459
					B-102,92820
Add 12% C.S.T	(+)	12,35120			
Add 2% Labour cell	(+)	10,2520			
Add S. fee	(+)	49,00200			
					B-121,20420
B-1,21,20420					
23/12/2021					
23/12/2021					
23/12/2021					

Continuation

E-E

Date:- 04-12-2021

Inspection Report for Flood damage work

(Year 2021-22)

1. Name of PIUs- DHAMDABA

2. Name of Block/Road- DHAMDABA

A. For Road - MILKIYA NAYA TOLA TO MILKIYA MAHABAD

1. Damage Location/Chainage: AT CH -

2. Damage Length: 9.0 Mtr

3. Nature of Damage: -

4. Details of Restoration:

i Material being used in Restoration

: Earthwork, Brick bats

ii Equipment/Tools being used in Restoration works:

iii Procedure taken up in Restoration works

iv Restored Length

: Ch 9.0 Mtr.

B. For Bridge

1. Damage Location/Chainage:

2. Damage Length:

3. Nature of Damage:

4. Details of Restoration:

i Material being used in Restoration

ii Equipment/Tools being used in Restoration works:

iii Procedure taken up in Restoration works

iv Restored Length

P. Kumar
04-12-21

Signature of JE/AE/EE

04/12/2021
A.E.

Executive Engineer
Rural Works Department
Works Division Dhamsabai (Pune)

संगोपसद

Signature
Executive Engineer
(Name of Executive Engineer)
PUNE

Scanned with CamScanner

Scanned by CamScanner

Scanned with CamScanner

Scanned with CamScanner

Scanned with CamScanner