

## Inspection Report for Flood Damage Work

Date: .....

1. Name of PIUs – Executive Engineer, R.W.D., Works, Division. Samastipur

2. Name of Block – Samastipur

3. Name of Road/Bridge – T01 to Jitwaspur

A. for Road

1. Damage Location/Chainage : Near 500 Railway X-Jitwaspur

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration Works :

i. Material being used in Restoration works : Brick bats & etc -

ii. Equipments/Tools being used in Restoration Works : Doctor, Roller, JCB,

iii. Procedure taken up in Restoration works :

iv. Restored Length :

B. for Bridge

\_\_\_\_\_ N/A

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration Works :


i. Material being used in Restoration works :

ii. Equipments/Tools being used in Restoration Works :

iii. Procedure taken up in Restoration works :


iv. Restored Length :

N/A

  
20/04/2022  
J.E.

A.E.

N/A  
20.4.22  
Executive Engineer,  
R.W.D. Works Division,  
SAMASTIPUR

  
20/4/22  
Signature  
(Name of Inspector)  
E.C. Baha  
Raj n m s S n s n