



HEAD-FDR

STATE:- BIHAR

DETAILED PROJECT REPORT

DISTRICT :- Madhubani

CIRCLE: - Darbhanga

BLOCK :- Andhrarthari

Estimate for Mortable of the Road from L043-L030 TO GODAM TOLA (VR43) **FDR at Block- Andhrarthari** in Madhubani District.

TOTAL COST FOR MOTORABLE Rs.

52161.00

-5.00940 lac.

Submitted by:

Executive Engineer RWD(W) Division, Jhanjharpur

Inspection Report of Flood Damage Work

Name of PIUs :- RWD Works Division, Jhanjharpur

Name of Block :- And harthari

Name of Road: Loys - Loso to Godam tola (UR 43)

A. For Road

- 1. Damage Location Chainage :- ch. 200 to 400, 600 to 800
- 2. Damage Length
- :- 0.141 Km 3. Nature of Damage :- Shoulder custing,
- 4. Details of Restoration Works Drick bath filing ofy = 22-02 m3
 - Materials being used in restoration works:-
 - ii. Equipment's/Tools being used in Restoration works:- Practor, J.C.B.
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:-

0-141 Km 0.022 KM or 22 m

B. For Bridge

- L. Damage Location Chainage
- 2. Damage Length
- 3. Nature of Damage
- 4. Details of Restoration Works
 - i. Materials being used in restoration works:-
 - ii. Equipment's/Tools being used in Restoration works:-
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:-

C. Requirement Of New CD/ Bridges

- i. Name of Road:-
- ii. Location/ Chainage:-
- iii.Type of CD Work/ Length required:-

Signature of JE/AE

(Name of Inspection)

तकनीकी प्रतिवेदन

पथ का नाम :- LO43 - LO30 To Crodam Tola(VR43)

500940.00 प्राक्कित राशि :- 423442-54

प्रमण्डल का नाम:- झंझारपुर

अंचल का नाम :- दरभंगा

योजना का नाम :- F.D.R-2245

प्रस्तुत प्राक्कलन विभागीय स्तर से कराये गये कार्य के आलोक LOU3-1030 ि कि वाढ एवं अतिवृष्टि के कारण हुए कटाव/ जलजमाव/ Wave Cut के कारण क्षतिग्रस्त हो गया था जिसके कारण आवागमन बाधित हो गया था । फलतः ग्रामीणों को काफी कठिनाईयों का सामना करना पड

यह प्राक्कलन सचिव महोदय, ग्रामीण कार्य विभाग, पटना बिहार के पत्रांक— मु०अ०— 4 (मु०) विविध (कार्य)— 23 — 60 / 2020— 1937 पटना, दिनांक— 07.07.2021 के आदेश के आलोक में तैयार किया गया है ।

इस प्राक्कलन में क्षतिग्रस्त हुए पथांश को ईंट के टुकड़े/मिट्टी/स्थानीय बालु से भरकर उसका संपीडन किये जाने का प्रावधान करते हुए कार्य संपादित किया जा चुका है ।

प्रस्तुत प्राक्कलन संपादित कार्य के समय लागू अनसूचित दर (संवेदक लाभांश छोड़कर) पर तैयार किया गया है । यह कार्य लोकहित एवं जनहित में अत्यावश्यक है । अतः इस प्राक्कलन की स्वीकृति अपेक्षित है ।

(22 MI) 5)

कनीय अभियंता

सहायक अभियंता

कार्यपालक अभेग्रेजा ग्रामीण कार्य विभाग, कार्य प्रमण्डल, झंझारपुर

Estimate for Motorability of road damaged by flood from L043-L030 TO GODAM TOLA (VR43) For Year 2021

ead :- FDR 2245

Length :- 1.024 km

SI No.	Item No.	Name of Item		Quantity As per Appendix - 1	Rate	Amount
1		Providing and filling brick bats in ditches/ damaged embankment including cost of brick bats and labour all complete job as per specification and direction of E/I.	Cum	12.62 Se 2H:20	2004.96	44149.92

Add 12 % GST ₹

Add 1 % L.C ₹

Total ₹

-5,00,940.00 Say ₹

52161.00

(3511/21

Junior Engineer R.W.D, Works Section, Andhrarthari

Assistant Engineer R.W.D, Work sub Div.

Andhrarthari

R.W.D (W) Division,

Jhanjharpur

के बाधा पा।

Superintending Engineer RWD Work Circle, Darbhango

page - 6 of 8

Name of Road :- L043-L030 TO GODAM TOLA (VR43)

me :-

PMGSY

Length :- 1.024 km

Block :- Andhrarthari

ndix - I

Measurement for restoration of Embankment and shoulder with Brick Bat (Measurement in mtr.)

					·							
Chainage	Nos.		Length (in Mtr.)		Bidth (in Mtr.)		Thickness (in Mtr.)			Quantity		
	1	×	18:00	×	2.50	×	0.90	av.	=	- 40.50	eom	
ch. 200 to 400	21	×	_1 2.00	×	2.70	×	1.25 0.1	av.	=	1•5 •40:50	cum	
	2	x	13.00	×	2.40	×	0.30	av.	=	9.36 /	cum	
	-2	×	-9.00	×-	2.30	—×—	0.23	av.	Ε	4.66	cum	
	1	x	15.00	×	0.50	_x_	0.60	av.	=	4.50		
	2	x	1 6.00 3	x	2.10 ⁻	x	0.60	av.	Ξ	-40.32	7.56	Con
ch. 600 to 800	1	_x_	14.00	_×_	2.00	_×-	0.55	−av.		15.40	, , ,	1
	~	_x_	16.00	_x	2.60	×	0.50	av.	=	20.80		1
	_1	_x_	15.00	_×	2.40	—ж—	0.50	av	=	18.00		
	-1	_×_	13.00	_×	2.20	×	0.60	av.	-	17.16		
			141.00				Total qty.		=	-211.20	cum	1
												_

22.02 cum.

Sezan 30 Am

Junior Engineer R.W.D. Works Section. Andhrarthari

Assistant Engineer R.W.D. Work sub Div. Andhrarthari Executive Engineer R.W.D (W) Division,
Jhanjharpur