

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल- बक्सर

पत्रांक- 1586 अ०/बक्सर

दिनांक- 03/11/22

प्रेषक,

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल- बक्सर

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव
बिहार ग्रामीण पथ विकास अभिकरण (BRRDA)
बुद्ध मार्ग, पटना।

विषय- शीर्ष 3054 (बिहार ग्रामीण पथ अनुरक्षण नीति- 2018) योजना अंतर्गत राशि की अधियाचना के सम्बन्ध में।

महाशय,

उपर्युक्त विषय के सम्बन्ध में कहना है कि योजना शीर्ष 3054 मरम्मत (बिहार ग्रामीण पथ अनुरक्षण नीति- 2018) अंतर्गत कराये गए कार्यों के भुगतान हेतु राशि की आवश्यकता है जिसे अधियाचना प्रपत्र के साथ सलग्न कर भेजा जा रहा है।

अतः श्रीमान से अनुरोध है कि सलग्न विवरणी के अनुसार आवंटन उपलब्ध कराने की कृपा की जाए ताकि संवेदकों द्वारा कराये गए कार्य का भुगतान किया जा सके।

अनु०- यथोक्त

विश्वासभाजन

02.11.22

कार्यपालक अभियंता
ग्रा०का०वि०, कार्य प्रमंडल- बक्सर

AK
02.11.22

FORM GFR 19-A

(SEE Government of India's Decision (I) below Rule-150)
Form of Utilisation Certificate upto the month of Dec 2018

PIU - RWD (W), Div.- Buxar**MR (3054) New Maintenance Policy 2018**

Sl. No.	Name of Scheme	Sanction No. & Date with Amount (in Rs. Lacs)	Amount Received (in Rs. Lacs)	Particulars
1	Construction of Rural Roads under MR (3054) Maintenance	Lt. No.- 05, dt.-25.01.2022	5494.56438	Certified that out of Rs. 5494.56438 lacs received during the years in favour of Ex. Engineer, RWD (W), Div.- Buxar Bihar, a sum of Rs 5494.37628 lacs has been utilized for the purpose of MR (3054) New Maintenance Policy 2018 Schemes as given in the margin for which it was sanctioned and that the balance of Rs 0.18810 lacs remaining unutilized at the end of the period under.
Total -				

- 2 Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled/ are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercised :-


- Works have been supervised by Executive Engineer/ Superintending Engineer.
- Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- Construction materials have been tested
- Measurements have been recorded in the MBs and test check conducted by the Assistant.
- All other codal formalities have been observed.

3 Physical Progress achieved :-

- Construction of Road works
- Construction of CD works


Executive Engineer

R.W.D. (w) Div. Buxar



2.11.22

Requisition Format for Scheme Head- MR (3054) under Bihar Rural Road Maintenance Policy- 2018 (Initial Rectification and Surface Renewal)

Name of Works Division- RWD, Works Division- Buxar

Sl No	Package No.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount		Agreement No. & Date	Date Of Completion as per Agreement	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in percentage	Previous Total Allocated Amount (in Lakh)	up-to-date expenditure as per MIS (in Lakh)	Requisition against work done (in Lakh)	Remarks
					Length (in Km)	Amount (in Lakh)	Initial Rectification With Surface Renewal (in Lakh)	5 Years Routine Maintenance (in Lakh)									
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18
1	RM/BU/BU X/22/0006	Buxar Harhi Path To Gurdas Mathiya Hote Huve Laiganj Village Tal	10401912001	Lt. No.- 2005, Dt.- 02/05/2022	1.150	61.656	52.74859	11.64390	22/MBD/ 2020- 21 & 08/10/2022	07-07-23	2896	25 mm	5.03%	0	0	51.88121	
2	RM/BU/BU X/22/0006	Jariganwan - karanasi	10401902072	Lt. No.- 2005, Dt.- 02/05/2022	2.380	76.47	56.87576	28.15740	22/MBD/ 2020- 21 & 08/10/2022	07-07-23	2973	25 mm	5.01%	0	0	56.49982	
3	RM/BU/BU X/22/0006	L024 - Parari Sandhara SH, T01 to Dahiwar (L24)	10401902075	Lt. No.- 2005, Dt.- 02/05/2022	1.150	49.50	38.60751	13.86860	22/MBD/ 2020- 21 & 08/10/2022	07-07-23	2776	25mm	5.00%	0	0	38.46950	

1. Signed Hard Copy and Soft Copy (in excel) of recorded IRI is enclosed
2. Up-to-date Physical Progress has been uploaded in MIS



 Executive Engineer
 RWD (W), Div.- Buxar
 02.11.22
 02.11.22

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, बक्सर


का0आ0स.....1585..... बक्सर/ दिनांक.....03/11/22.....

कार्यालय आदेश

प्रमाणित किया जाता है कि बिहार ग्रामीण पथ अनुरक्षण नीती-2018 योजनान्तर्गत बक्सर ईटाढ़ी पथ से गुरुदास मठिया होते हुए लालगंज ग्राम तक पथ का कार्य गुणवत्ता एवं विशिष्टियों के अनुरूप पूर्ण कराया गया है। पथ के मापीपुस्त की जाँच मेरे द्वारा 50 प्रतिशत एवं कनीय अभियंता के द्वारा शत प्रतिशत किया गया है।


21/11/22

कनीय अभियंता
ग्रामीण कार्य विभाग
कार्य अवर प्रशाखा बक्सर



02.11.22

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, बक्सर

ROAD NAME - BUXAR ITADHI ROAD VIA GURUDAS MATHIYA TO LALGANJ CONTRACTOR NAME - AMIT KUMAR										
7/11/22	16:27:4	59	0.1	290	0	2900	2859 G	25.55263	83.9883 Normal	Y = 0 * X ^ 2 + 0.901 * X + 246.4
7/11/22	16:27:39	59	0.1	290	30.3	2900	2859 G	25.5523	83.98961 Normal	X = 700
7/11/22	16:28:0	59	0.1	330	30.3	3300	3219 G	25.55194	83.99071 Normal	Y = 877
7/11/22	16:28:14	59	0.1	250	30.3	2500	2498 G	25.55181	83.99138 Speed Breaker	
7/11/22	16:29:0	59	0.1	310	30.3	3100	3039 G	25.55153	83.99261 Speed Breaker	
7/11/22	16:29:25	59	0.1	300	31.2	3000	2949 G	25.55141	83.99288 Normal	(R) RURAL ROAD
7/11/22	16:30:0	59	0.1	270	30.3	2700	2679 G	25.55106	83.9934 Normal	Good
7/11/22	16:30:35	59	0.1	290	32.5	2900	2859 G	25.55079	83.99377 Normal	Average Poor
7/11/22	16:31:0	59	0.1	230	30.3	2300	2318 G	25.55054	83.99406 Speed Breaker	4001-5000 >5001
7/11/22	16:31:11	59	0.1	310	30.3	3100	3039 G	25.55004	83.99434 Speed Breaker	
7/11/22	16:32:0	59	0.1	320	30.3	3200	3129 G	25.54963	83.99449 Speed Breaker	
7/11/22	16:33:0	59	0.05	170	30.3	3400	3309 G	25.54928	83.99475 Normal	
LENTHE - 1.150 KM				AVERAGE -2896						

2896
8/11/22
JE

File : C:\Users\AMIT\Desktop\07111904.XIs, Section No. : 59, Eqn : $Y = 0 \cdot X^2 + 0.901 \cdot X + 246.4$
 Name of Customer : AMIT KUMAR, Name of Work/ Road : BUXARI TADHI ROAD VIA GURUDAS MATHIYA TO



20/11/22
 8/11/22
 J.E.