कार्यपालक अभियंता का कार्यालय ग्रामीण कार्य विभाग, कार्य प्रमंडल, महुआ।

पत्रांक २०२० /

महुआ/दिनांक......24/...09/2022

प्रेषक,

कार्यपालक अभियंता, ग्रामीण कार्य विभाग,

कार्य प्रमंडल, महुआ।

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी—सह— सचिव, ब्राडा,

विश्वेश्वरैया भवन,

ग्रामीण कार्य विभाग,

बिहार, पटना।

विषय :- MMGSY NDB (BRICS) योजना अन्तर्गत कराये गए कार्य के विरुद्ध अधियाचना के संबंध में।

महाशय,

उपरोक्त विषय के संबंध में कहना है कि MMGSY NDB (BRICS) योजना के अन्तर्गत कराये गए कार्य के विरूद्ध अधियाचना विहित प्रपत्र में भरकर भेजी जा रही है।

अनु0-यथोक्त।

24. %. 22 कार्यपालक अभियंता, ग्रामीण कार्य विभाग, कार्य प्रमंडल, महुआ ।

Form GFR 19-A

(See Government of India's Decision (1) below Rule-150) Form of Utilisation Certificate upto the month- 24. 09. 2022

STATE-BIHAR

SL. No	Name of Scheme	Sanction No. & Date With Amount (In Rs. Lacs)	Amount Received (In Rs.Lacs)	Particulars		
1	Construction of Rural Roads under MMGSY NDB (BRICS)	Lt-345 Dated- 06- 09-2022 Amount- 1846.24446	1846.24446	Certified that out of Rs. 1846.24446 Lacs of grants-in-aid sanctioned upto 12/2017 in favour of E-in-C, REO Bihar, Patna a sum of Rs. 1846.21813 lacs has been utilized for the purpose of MMGSY NDB (BRICS) Scheme as given in the margin for which it was sanctioned and that the balance of Rs- 0.02633 lacs remaining unutilized at the end of the period under.		
	Total:		1846.24446			

Certified that I have satisfied myself that the conditions on which the gram-in-aid was sanctioned have been duly fulfilled/ are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sancticed.

Kind of Checks exercised:-

- i Works has been supervised by Executive Engineer/Superintending Engineer.
- ii Periodical inspection has been conducted by Executive Engineer/Superintending Engineer.
- iii Construction materials have been tested.
- iv Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/ Executive Engineer
- v All other codal formalities have been observed.

3 Physical Progress achived:-

- i Construction of Road Works.
- ii Construction of CD Works.

Divisional Account Officer RWD. Works Division, Mahua

Executive Engineer
RWD. Works Division, Mahua

Rural Works Department MMGSY NDB (BRICS) Allotment Requisition Format

1
1
1 23
12
6
=
1
, mi.
Name of Division -
12.
1 =
1
\mathbf{z}
-
-
0
=
<u> </u>
1
- R.W.D Works Division, Mahua
\subseteq
7

S
Ξ.
=
=
•
7
22
_
=
=
25

		<u> </u>		-	No	SI.	
	2020-21			2	Year		
	MMGSY NDB-BRRP- 240-Mahua				Package No-		
Total -	Bishanpur Arrha P.A Gorool Jane Wali Pich Road Talim miya ke Bagicha se Bishanpur Arrha Transformar hote hue Harpur Arhha Pich road tak.	Gram Karhatiya Madhya Vidhlaya se Purab Jogi Baba astan hote hue Mishri Lal ke ghar tak. Karhatiya Bujurg P.A PMGSY Sadak se Rasulpur Fateh tak.		3	Name of Road		
		Mansi Infracon Pvt Ltd	4	Name of Contractor (In English)			
6.98000	3.110	1.820	2.050	. 5	Length (In Km)	Admii Sar	
636.85000 548.78934	280.520	1.820 173.970 152.10875	182.360	6	Amount (In Lacs)	Administrative Sanction	
548.78934	240.08727	152.10875	156.59332	7	Main Work	Agreeme	
57.90635	21.91164	16.37511	19.61960	8	Maintenance (In Lacs)	Agreement Amount (In Lacs)	
499.69087	239.71031	151.99560	107.98496	9			
499.66454	151.99560 151.96927 239.71031 239.71031		107.98496 151.13411	10	Total Value of Current Expenditure Measuremen Demand As per MIS t (In Lacs) (In Lacs) 11-9		
151.13411	0.00000		151.13411	11	t (In Lacs)	Value of Measuremen	
43.14915	0.00000	0.00000	43.14915	12	(In Lacs) 11-9	Value of Current leasuremen Demand	
	Work Completed	Work Completed	Work Completed	13	Remarks		

Divisional Accounts Officer Works Division, Mahua

.

Executive Engineer Works Division, Mahua

खर्च का मिलान MIS से होना आवश्यक है।

2 . अधियाचित राशि का पथवार मापिपुस्त की प्रथम एवं अंतिम पेज की अभिप्रमाणित छाया प्रति संलग्न होना आवश्यक है।

3 . पूर्व निर्गत राशि का उपयोगिता प्रमाण पत्र संलग्न होना आवश्यक है।

4 . निर्गत राशि का डी0 सी0 विपत्र 15 दिनांक के अन्दर ब्राडा कार्यालय में उपलब्ध कराया जाना आवश्यक है।