

कार्यपालक अभियंता का कार्यालय  
ग्रामीण कार्य विभाग,  
कार्य प्रमंडल, डिहरी

पत्रांक.....4373130

डिहरी / दिनांक.....05/04/23

प्रेषक,

कार्यपालक अभियंता,  
ग्रामीण कार्य विभाग,  
कार्य प्रमंडल, डिहरी

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी -सह-सचिव,  
ब्राडा,  
भूमि विकास बैंक भवन,  
बुद्ध मार्ग, पटना।

विषय :-

**MR New Maintenance policy-2018** में किये गये कार्य के विरुद्ध  
आवंटन उपलब्ध कराने के संबंध में।

महाप्राय,

उपरोक्त विषय के संबंध में सूचित करना है कि **MR New Maintenance policy-2018** अर्न्तगत कराये गये कार्यों के विरुद्ध संवेदक को भुगतान करने हेतु अधियाचना विहित प्रपत्र में भरकर आवश्यक कार्यवाही हेतु समर्पित की जाती है। इस पथ में कोई भी ATR लंबित नहीं है। उक्त पथ का सभी डाटा की प्रविष्टि MIS पर अद्यतन है।

अनु :- यथोक्त।

विश्वासभाजन

*NKumar*  
05.04.23

कार्यपालक अभियंता,  
ग्रामीण कार्य विभाग,  
कार्य प्रमंडल, डिहरी

*NKB*  
05/04/23

**FORM GFR 19 -A**  
(SEE GOVERNMENT of India's Decesion (I) below Rule - 150)  
**Form of Utilisation Certificate upto the Month of April 2023**  
**NEW MAINTENANCE POLICY 2018 MR (3054)**

PIU - RWD DEHRI

| S.No  | Name of Scheme                           | Sanction No. & Date       | Amount Received | Particulars                                                                                                                                                                                                                                                                                                                                                           |
|-------|------------------------------------------|---------------------------|-----------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
|       |                                          | With amount(in Rs. Lacs ) | (In Rs. Lacs)   |                                                                                                                                                                                                                                                                                                                                                                       |
| 1     | Contruction of Rural Road under MR-03054 | 10194<br>16.03.2023       | 1998.81355      | Certificate that out of Rs. 1998.81355 Lacs received during the years in favour of Executive Engineer , RWD Dehri Bihar. Sum of Rs. 1928.87450 Lacs has been utilised for the purpose of MR (3054)-2018 Fund hences as given in the margin for which it was sanctioned and that the balance of Rs. 69.93905 Lacs remaining unutilized at the end of the period under. |
| TOTAL |                                          |                           | 1998.81355      |                                                                                                                                                                                                                                                                                                                                                                       |

- 2 Certified that I have satisfied myself that the conditions on which the grand-in-aid was sanctioned have been duly fulfilled / are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

**Kind of Checks exercised :-**

- Works have been supervised by Executive Engineer / Supertending Engineer.
- Periodical inspectioin has been conducted by Executive Engineer / Supertending Engineer.
- Construction materials have been tested.
- Measurements have been recorded in the MBs and test check conducted by the Assistant.
- All other codal formalities have been observed.

3 **Physical Progress achieved :-**

- Construction of Road works.
- Construction of CD works.

*[Signature]*  
D.A.05/04/23

RWD (W) Div. Dehri

*[Signature]*  
05.04.23  
Executive Engineer  
RWD (W) Div. Dehri

*[Signature]*  
05/04/23

**Office of the Executive Engineer, Rural Works Department, Works Division, Dehri**  
Requisition formate Scheme Head MR (3054) under Bihar road Maintenance Policy-2018 (Rectification and Surface Renewal)

| Sl No. | Package No.       | Name of Road                    | Project Id as per MIS | Administrative Approval (AA) Letter No. and Date | Administrative Approval (AA) |                  | Agreement (in Lakh)                                |                                         | Agreement No. and Date                 | Date of Completion as per Agreement | Actual Date of Completion | Value of IRI (in mm/KM) | Thickness of Bitumin Layer (in mm) | Value of Bitumin Content in Percentage | Previous total amount (in Lakh) | Up to Date expenditure as per MIS (in Lakh) | Requisition against Work Done (in Lakh) | Remarks |    |
|--------|-------------------|---------------------------------|-----------------------|--------------------------------------------------|------------------------------|------------------|----------------------------------------------------|-----------------------------------------|----------------------------------------|-------------------------------------|---------------------------|-------------------------|------------------------------------|----------------------------------------|---------------------------------|---------------------------------------------|-----------------------------------------|---------|----|
|        |                   |                                 |                       |                                                  | Length (in Km)               | Amount (in lakh) | Initial Rectification on Surface Renewal (in Lakh) | Five Year Routine Maintenance (in Lakh) |                                        |                                     |                           |                         |                                    |                                        |                                 |                                             |                                         |         |    |
| 1      |                   | 2                               | 3                     | 4                                                | 5                            | 6                | 7                                                  | 8                                       | 9                                      | 10                                  | 11                        | 12                      | 13                                 | 14                                     | 15                              | 16                                          | 17                                      | 18      | 19 |
| 1      | RM/RO/DEH/23/0001 | PWD path se kumalkhaura barecha | 10301208021           | 141308.09.2022                                   | 2.93                         | 169.067          | 116.4197                                           | 39.12977                                | RWD,Dehri/07/MR3054/2022-23/01-02-2023 | 30-09-2023                          |                           | 2891.66                 | 25 MM                              | 0.05                                   |                                 |                                             | 105.709                                 |         |    |

- विभागीय पत्रांक-मु030(मु) 3054-4-04/2020 पार्त 4 5047 दिनांक 23.12.2021 के आलोक में प्रमाणित किया जाता है कि-
- गुणवत्ता पूर्ण एवं विशिष्टियों के अनुरूप कार्य कराने के बाद MB में दर्ज किया गया है।
  - सम्बन्धित कार्य कर्मीय अभियंता द्वारा कराया गया (100% जांचा गया) सहायक अभियंता द्वारा 50% तथा कार्यपालक अभियंता द्वारा 10% जांचा गया तथा MIS पर Upload किया गया।

RWD (W) Div. Dehri

*File*  
D.A.O  
05/04/23

EXECUTIVE ENGINEER  
RWD, WORKS DIVISION,  
DEHRI

*NEB*  
05/04/23

*NEB*  
05.04.23

Steco Analyzer


Name of Customer : Balram Singh  
 Name of Work/Road : PWD path to kamal Khaira bare  
 Lab Job number : 34  
 Date : 03-04-2023  
 Section No. : 34

Test Date : 03-04-2023 Road Name : PWD path to kamal Khaira bare  
 Machine No : 412 Road Type : (R) RURAL ROAD  
 Start S No :  Side :  Interval :   
 Start E No :   
 Weather :  UV Range : 1215 To 5000 1000 mm/km  
 Start Location : WD path Dist Range : 0 To 31 01 \* 1000 m  
 End Location : khaira barecho Equation :  $Y = 0 * X^2 + 1000 * X + 4152$

Print Generate Report and Graph

Redraw Graph

Map View



*[Signature]*  
 05/04/2023  
 JE

*[Signature]*  
 05/04/2023  
 A.E.

*[Signature]*  
 05.04.23  
 EE

RoadName-PWD path se kamalkhaira barecha

Cont.Name- Baliram Singh

| Date     | Time     | Section | Length | Bumps | Speed | OR    | IRI   | TEGORY | Latitude | Longitude | Event         |
|----------|----------|---------|--------|-------|-------|-------|-------|--------|----------|-----------|---------------|
|          |          | No.     | in km  | in mm | Rate  | mm/km | mm/km | ROAD   |          |           |               |
| 03/04/23 | 16:35:44 | 34      | 0.1    | 270   | 0     | 2700  | 3115  | G      | 24.56611 | 83.90112  | Normal        |
| 03/04/23 | 16:36:0  | 34      | 0.1    | 260   | 20.2  | 2600  | 3015  | G      | 24.5668  | 83.90051  | Normal        |
| 03/04/23 | 16:36:20 | 34      | 0.1    | 210   | 30.3  | 2100  | 2515  | G      | 24.56745 | 83.89986  | Normal        |
| 03/04/23 | 16:36:28 | 34      | 0.1    | 290   | 30.3  | 2900  | 3315  | G      | 24.56804 | 83.89926  | Normal        |
| 03/04/23 | 16:36:35 | 34      | 0.1    | 330   | 30.3  | 3300  | 3715  | G      | 24.56889 | 83.89909  | Normal        |
| 03/04/23 | 16:36:55 | 34      | 0.1    | 270   | 30.3  | 2700  | 3115  | G      | 24.56993 | 83.8982   | Normal        |
| 03/04/23 | 16:37:0  | 34      | 0.1    | 180   | 20.2  | 1800  | 2215  | G      | 24.57041 | 83.89764  | Normal        |
| 03/04/23 | 16:37:0  | 34      | 0.1    | 200   | 20.2  | 2000  | 2415  | G      | 24.57075 | 83.89688  | Normal        |
| 03/04/23 | 16:37:30 | 34      | 0.1    | 250   | 30.3  | 2500  | 2915  | G      | 24.5714  | 83.89593  | Normal        |
| 03/04/23 | 16:37:30 | 34      | 0.1    | 190   | 20.2  | 1900  | 2315  | G      | 24.57182 | 83.79538  | Normal        |
| 03/04/23 | 16:38:0  | 34      | 0.1    | 250   | 20.2  | 2500  | 2915  | G      | 24.57254 | 83.89451  | Speed Breaker |
| 03/04/23 | 16:38:5  | 34      | 0.1    | 270   | 30.3  | 2700  | 3115  | G      | 24.5732  | 83.89387  | Normal        |
| 03/04/23 | 16:38:5  | 34      | 0.1    | 330   | 20.2  | 3300  | 3715  | G      | 24.57374 | 83.89311  | Normal        |
| 03/04/23 | 16:38:5  | 34      | 0.1    | 190   | 30.3  | 1900  | 2315  | G      | 24.5743  | 83.89234  | Normal        |
| 03/04/23 | 16:38:41 | 34      | 0.1    | 260   | 30.3  | 2600  | 3015  | G      | 24.57503 | 83.79173  | Normal        |
| 03/04/23 | 16:39:0  | 34      | 0.1    | 320   | 30.3  | 3200  | 3615  | G      | 24.57558 | 83.89146  | Normal        |
| 03/04/23 | 16:39:0  | 34      | 0.1    | 270   | 30.3  | 2700  | 3115  | G      | 24.57624 | 83.89109  | Speed Breaker |
| 03/04/23 | 16:39:16 | 34      | 0.1    | 250   | 30.3  | 2500  | 2915  | G      | 24.57698 | 83.89057  | Normal        |
| 03/04/23 | 16:39:16 | 34      | 0.1    | 270   | 30.3  | 2700  | 3115  | G      | 24.57766 | 83.88962  | Normal        |
| 03/04/23 | 16:39:16 | 34      | 0.1    | 240   | 20.2  | 2400  | 2815  | G      | 24.57829 | 83.88893  | Normal        |
| 03/04/23 | 16:40:0  | 34      | 0.1    | 310   | 20.2  | 3100  | 3515  | G      | 24.57914 | 83.88814  | Normal        |
| 03/04/23 | 16:40:0  | 34      | 0.1    | 180   | 20.2  | 1800  | 2215  | G      | 24.5798  | 83.88757  | Normal        |
| 03/04/23 | 16:40:27 | 34      | 0.1    | 190   | 20.2  | 1900  | 2315  | G      | 24.58039 | 83.88704  | Normal        |
| 03/04/23 | 16:40:27 | 34      | 0.1    | 240   | 20.2  | 2400  | 2815  | G      | 24.5812  | 83.88637  | Normal        |
| 03/04/23 | 16:41:2  | 34      | 0.1    | 180   | 10.1  | 1800  | 2215  | G      | 24.58162 | 83.88597  | Normal        |
| 03/04/23 | 16:41:2  | 34      | 0.1    | 250   | 10.1  | 2500  | 2915  | G      | 24.58246 | 83.88524  | Normal        |
| 03/04/23 | 16:41:37 | 34      | 0.1    | 260   | 20.2  | 2600  | 3015  | G      | 24.58314 | 83.88456  | Normal        |
| 03/04/23 | 16:41:37 | 34      | 0.1    | 200   | 20.2  | 2000  | 2415  | G      | 24.58387 | 83.88409  | Normal        |
| 03/04/23 | 16:42:0  | 34      | 0.1    | 200   | 20.2  | 2000  | 2415  | G      | 24.58443 | 83.88442  | Normal        |
| 03/04/23 | 16:42:12 | 34      | 0.1    | 320   | 20.2  | 3200  | 3615  | G      | 24.58443 | 83.88442  | Normal        |
| 03/04/23 | 16:42:12 | 34      | 0.04   | 200   | 20.2  | 2000  | 2415  | G      | 24.58527 | 83.88452  | Normal        |

$$Y = 0 * X^2 + 1.000 * X + 415.2$$

$$X = 2900$$

$$Y = 3315$$

(R) RURAL ROAD

Good Average Poor

IRI Value

Average IRI=2891.66

*[Signature]*  
05/04/2023  
JE

x. Prasad  
01/04/2023  
A.E.

MEERAN  
05.04.23  
EE