

कार्यपालक अभियंता का कार्यालय,
ग्रामीण कार्य विभाग, कार्य सिमरी बख्तियारपुर।

पत्रांक:- 836(अ.क.)

सिमरी बख्तियारपुर दिनांक:- 05/04/2023

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, सिमरी बख्तियारपुर।

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव,
ब्राडा, पटना।

विषय:- 3054 बिहार ग्रामीण पथ नई अनुरक्षण नीति 2018 के योजना अन्तर्गत में
अधियाचित राशि का आवंटन उपलब्ध कराने के संबंध में।

महाशय,

उपरोक्त विषयक प्रासंगिक पत्र के अनुपालन में 3054 बिहार ग्रामीण पथ नई
अनुरक्षण नीति 2018 के योजना अन्तर्गत राशि की मॉग संलग्न विहित प्रपत्र में पथवार की
गई है।

अतः भवदीय से अनुरोध है कि विहित प्रपत्र के कॉलम 18 में अंकित कुल राशि
का आवंटन उपलब्ध कराने की कृपा की जाय। अधियाचित राशि के संदर्भ में Bump
Intrigater Report की छाया प्रति संलग्न कर समर्पित किया जा रहा है।

अनु० यथोक्त।

विश्वासभाजन

8/4/23

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, सिमरी बख्तियारपुर।

05/04/2023

8/4/23

Requisition Format for Scheme Head - MR (3054) Under Bihar Rural Road maintenance Policy 2018 (Initial Rectification and Surface Renewal)

Name of Division : Simri Bakhtiyarpur

SL.N o	Package no.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount (in Lac)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in percentage	Previous Total Allocated Amount (Lac)	up to date expenditure as per MIS (in Lac)	Requisition on Against work done (In lac)	Remarks
1	RM/SA/SIM/23/0001	MDR T02 - Mahkar	20904302069	1192/24.08.2022	Length (In Km)	Amount (in Lac)	Initial Rectification Surface Renewal (in lac)	5 years Routine Maintenance (In lac)	01MBD/2023-24 / 07.02.2023	06.09.2023	02.04.2023	2.220	Complete PCC Work	Complete PCC Work	0.00	0.00	22.46259	Road Complete
2	RM/SA/SIM/23/0001	L089-X road L033 to H tola and kumhar tola (VR50)	20904402038	1192/24.08.2022	0.510	31.21500	24.37578	3.50130	01MBD/2023-24 / 07.02.2023	06.09.2023	02.04.2023	2.190	Complete PCC Work	Complete PCC Work	0.00	0.00	24.37578	Road Complete

Handwritten signature
05/07/2023
D-e

Executive Engineer
RWD Works Division
Simri Bakhtiyarpur
Handwritten signature
05/4/23
5/14/23

Form GFR 19- A
(See Government of India's Decision (I) below Rule - 150)
Form of Utilazation Certificate upto the month of 05.04.2023
New Maintenance Policy 2018

Sl. No.	Name of Scheme	Sanction No. & Date with Amount (in lacs)	Amount Received (in lacs)	Particulars
1	1	Letter No 42 Dated 20.03.2023	Rs 3256.82366 Vide Letter No :-42 Dated 20.03.2023	Certified that out of RS 3256.82366 lacs of grants in aid sanctioned during the Years up to 2021-22 in favour of Executive Engineer, RWD Works Division Simri Bakhtiyarpur under this Department, a sum of Rs 3253.13825 lacs has been utilized for the purpose of New_MR Scheme remaining 368.54128 unutilized at the end of the period under report.
		Total :	2871.46833	


Certified and verified myself that the conditions on which the grants in aid was sanctioned have been duly fulfilled / are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kinds of Checks exercised :-


- i Works have been supervised by Executive Engineer/ Superintending Engineer.
- ii Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- iii Construction material have been tested.
- iv Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/Executive Engineer.
- v All other codal formalities have been observed.

Physical Progress achieved :-

- i Construction of Road works.
- ii Construction of CD works


Sr.D.A.O.

RWD works Division
Simri Bakhtiyarpur


Executive Engineer
RWD works Division
Simri Bakhtiyarpur
05.04.2023

Name of work : L089-X road L033 to H tola and kumhar tola (VR50)

Name of customer : Prasar Remodelling & Construction Private Limited

(R)Rural Road

Good

Average

Poor

< 4000

4001 - 5000

> 5000


Date	Time	Test No	Distance(m)	Total Distance(m)	BUMPI(m)	Speed(Km/Hr)	UI(mm/Km)	Corrected UI (mm/Km)	IRI	Status	Latitude	Direction	Longitude	Direction1	Remarks
24/04/23	17:55:38	123	0	0	0.0 cm	17.8 Km/Hr	0.0 mm/Km	88	0.17	Good	25.7777147	N	86.5968409	E	Normal
24/04/23	17:55:55	123	100	100	12.0 cm	15.5 Km/Hr	1200.0 mm/Km	1209	1.79	Good	25.7317114	N	86.6487818	E	Normal
24/04/23	17:56:06	123	100	200	15.0 cm	30.3 Km/Hr	1500.0 mm/Km	1489	2.16	Good	25.7317114	N	86.6487818	E	Normal
24/04/23	17:56:57	123	100	300	17.0 cm	27.9 Km/Hr	1700.0 mm/Km	1676	2.4	Good	25.7307425	N	86.6494837	E	Normal
24/04/23	17:57:43	123	100	400	21.0 cm	29.4 Km/Hr	2100.0 mm/Km	2050	2.87	Good	25.7299128	N	86.6488581	E	Normal
24/04/23	17:58:14	123	100	500	29.0 cm	11.7 Km/Hr	2900.0 mm/Km	2797	3.78	Good	25.7299128	N	86.6488581	E	Normal
24/04/23	17:58:54	123	100	600	15.0 cm	30.3 Km/Hr	1500.0 mm/Km	1489	2.16	Good	25.7299128	N	86.6488581	E	Normal

05/04/2023
H I T M

Handwritten
05/04/2023
02

Handwritten
05/04/2023
Etc

Name of Customer: Prasar Remodelling & Construction Private Limited, Machine no: 19215, Road: L089-X road L033 to H tola and kunhar tola (VR50), Date: 05/04/23, Section No: 123, Equation: $Y=0.936X+88.4$



Me
05/04/2023
A I T M

Handwritten
05/04/2023
gr

05/04/23
GB