

Name of Customer : SREERAM CONSTRUCTION

Name of Work/ : L074-T09 To Bedwalya (VR53)

Road : 12

Lab Job number : 12

Date : 17-04-2023

Section No. : 12

Print Generate Report and Graph

Test Date : 17-04-2023

Machine No : 391

Road Type : (R) RURAL ROAD

Side : Kochas

Interval : 1000

UIV Range : 1115 To 4000 mm/km


Dist Range : 0 To 0.8

Equation : $Y = 0 \cdot X^2 + 1.000 \cdot X + 415.2$

Start Location : 007.83.853803

End Location : 982.83.852608

Redraw Graph Map View



17/04/2023
17/04/23
17.04.23
EE

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, सासाराम-1

Email ID:-ee.rwd.sasaram1@gmail.com Mob:- 8986915310

पत्रांक.....790 0997

सासाराम / दिनांक.....17/04/2023

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, सासाराम-1

सेवामें,

नोडल पदाधिकारी (MR 3054)
ग्रामीणकार्यविभाग
पटना, बिहार

विषय :- नई अनुस्क्षण नीति-2018MR (3054) योजना के अंतर्गत पथ में कराये गये कार्य के विरुद्ध आवंटन उपलब्ध कराने के संबंध में।

महाशय,

उपरोक्त विषय के संबंध में सूचित करना है कि नई अनुस्क्षण नीति-2018 MR (3054) योजना के अंतर्गत पथ में कराये गये कार्य के लिए संवेदक को भुगतान करने हेतु अधियाचना विहित प्रपत्र में भरकर आवश्यक कार्यवाही हेतु समर्पित की जाती है।

अनु0 :- यथोक्त।

विश्वासभाजन

MKUM⁴¹
17-04-23

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, सासाराम-1

11/04/23

FORM GFR 19-A

(See Government of India's Decision (I) below Rule-150)

Form of Utilization Certificate up to April 2023

Sl.No	Name of Scheme	Sanction No.&Date With Amount (In lace Rs.)	Amount Received (In lace Rs.)	Particulars
1	Construction of Rural roads Under MR	New Maintenance Policy-2018 MR (3054) BRRDA PATNA	10129.95178	Certified that out of Rs. 10129.95178 lakh of grants-in-aid sanctioned during the years 2021-23 Infavor of EE,RWD works division Sasaram-1a sum of Rs 9946.64443 akh has been utilized for the purpose of MR (3054) Schemes as given in the margin for which it was sanctioned and that the balance of Rs. 183.30735 lakh remaining unutilized at the end of the period under report.
	Total:		10129.95178	

2. Certified that I have satisfied my self that the conditions on which the grant-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was utilized for the purpose for which it was sanctioned.

Kind of Checks exercised:-

- Works have been supervised by Executive Engineer/ Superintending Engineer.
- Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- Construction materials have been tested.
- Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/ Executive Engineer.
- All other caudal formalities have been observed.

3. Physical Progress achieved:-

- Construction of Road Works.
- Construction of CD works.



Divisional Accounts Officer
R.W.D, works Division
Sasaram-1

17.04.23

Executive Engineer

R.W.D, works Division
Sasaram-1

17.04.23

OFFICE OF EXECUTIVE ENGINEER, RURAL WORKS DEPARTMENT, WORKS DIVISION, SASARAM-1

Requisition Format for Scheme Head- MR(3054) under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Ren

Name of Works Division:- Sasaram-1

Sl no.	Batch No	Name of Road	Project ID as per MHS	Administrative Approval (AA) Letter No & Date	Length (in km)	Amount of (in Lakh)	Initial Rectification with Surface Renewal (in Lakh)	5 Year Routine Maintenance (in Lakh)	Agreement Amount	Agreement No& Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Allocated Amount (in Lakh)	up-to-date expenditure as per MIS (in Lakh)	Requisition done against work (in Lakh)	Remarks
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	
1	RM/RO /SAS/2 3/0011	L074-T09 TO BEDWALIYA (VR53)	13101294294	611 15.07.2022	0.7	28.779	25.56009	4.28586	2022-23 & 2023	2/11/2023	0	3058	25.00	5.00	-	-	19.38994	19.38994	
Total																			
					0.7	28.779	25.56009	4.28586									19.38994		

Divisional Accounts Officer
Rural Works Department,
Works Division, Sasaram-1

Executive Engineer
Rural Works Department
Works Division, Sasaram-1
17/04/23

Name of Road:- L074-T09 To Bedwaliya (VR53)

Date	Time	Section	Length	Bumps	Speed	OR	IRI	CATEGORY	Latitude	Longitude	Event
		No.	in km	in mm	Rate	mm/km	mm/km	ROAD			
17/4/23	10: 6: 5	12	0.1	290	10.1	2900	3315	G	25.184007	83.853803	Normal
17/4/23	10: 6: 13	12	0.1	280	20.2	2800	3215	G	25.18488	83.854242	Normal
17/4/23	10: 6: 25	12	0.1	260	20.2	2600	3015	G	25.185507	83.853988	Curve
17/4/23	10: 6: 39	12	0.1	170	20.2	1700	2115	G	25.185957	83.853552	Normal
17/4/23	10: 6: 45	12	0.1	260	30.3	2600	3015	G	25.186842	83.853703	Normal
17/4/23	10: 7: 0	12	0.1	290	20.2	2900	3315	G	25.187793	83.853602	Curve
17/4/23	10: 7: 20	12	0.1	300	10.1	3000	3415	G	25.187982	83.852608	Normal
Average IRI											
3058											

Y = 0 * X ^ 2 + 1.000 * X + 415.2
X = 3000
Y = 3415
(R) RURAL ROAD
Good Average Poor
<4000 4001-5000 >5001

17.04.23
Executive Engineer
Rural Work's Department
Work Division, Sasaram-1

17/04/23
AE

13/04/2023
JE