

**कार्यपालक अभियन्ता का कार्यालय,
ग्रामीण कार्य विभाग, कार्य प्रमण्डल, भभुआ**

पत्रांक.....70935/भभुआ,

दिनांक.....18.04.23.....

प्रेषक,

कार्यपालक अभियन्ता
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, भभुआ

सेवामें,

अपर-मुख्य कार्यपालक पदाधिकारी,
सह-सचिव, बी0आर0आर0डी0ए0,
बिहार, पटना।

विषय:- MR/3054 मरम्मत योजना अन्तर्गत मरम्मत कार्य की अधियाचना के संबंध में।

महाशय,

उपर्युक्त विषय के संबंध में इस प्रमंडल में MR/3054 मरम्मत योजना अन्तर्गत मरम्मत कार्य हेतु अधियाचना विहित प्रपत्र में अंकित कर सूचनार्थ एवम् आवश्यक कार्यवाही हेतु समर्पित की जाती है।

सूचनार्थ समर्पित।

अनु0:- यथोक्त।

विश्वासभाजन

18/04/23

कार्यपालक अभियन्ता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, भभुआ

ज्ञापांक.....709...../भभुआ, दिनांक.....18.04.23.....

प्रतिलिपि :- नोडल पदाधिकारी, MR/3054 ब्राडा, पटना को सूचनार्थ समर्पित।

18/04/23

कार्यपालक अभियन्ता
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल भभुआ

Requisition Format for Scheme Head - MR(3054) under Bihar Rural Road Maintenance Policy - 2018 (Initial Rectification and Surface Renewal)

Name of Works Division : Bhabhua

Sl. No.	Package No.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount (In Lakh)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content on Percentage	Previous Total Allotted Amount (in Lakh)	up-to-date expenditure as per MIS (In Lakh)	Requisition against work done. (In Lakh)	Remarks
					Length (In km)	Amount of (In Lakh)	Initial Rectification with Surface Renewal (In Lakh)	5 Years Routine Maintenance (In Lakh)										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	RM/K.A/BHA/22/0004	L035-T04 to Dharchali (VR12)	10301402070	Lt no-1597/31.3.22	6.630	315.432	188.35758	52.24090	10 MBD/2022-23 & dt 05.01.2023	04-10-2023		3285.28	25.01	5.02	0	0	169.521	
2	RM/K.A/BHA/22/0010	From Bhabua Darauli road to south side pond of village Dumri	10301501017	Lt no-1597/31.3.22	1.250	64.052	36.86231	9.97945	12 MBD/2022-23 & dt 01.02.2023	31-10-2023		3151.83	25.02	5.01	0	0	33.176	
3	RM/K.A/BHA/22/0008	L073-Goraipur Bare Road T010 to Mithapur (VR63)	10301402114	Lt no-1597/31.3.22	2.575	140.482	82.55013	19.82150	03 MBD/2022-23 & dt 16.12.2022	15-09-2023		3182.04	25.01	5.02	0	0	74.295	
4	RM/K.A/BHA/22/0008	Durgawati Chainpur road to Narotmapur vill via Dumaraith harijan tola Nakhtaul Canal	10301404008	Lt no-1597/31.3.22	2.7900	124.594	68.43019	21.69410	03 MBD/2022-23 & dt 16.12.2022	15-09-2023		3203.37	25.01	5.02	0	0	61.587	
Total					13.245	644.560	376.200	103.736									338.579	

Sund Kumar
 18/04/23
 Divisional Accounts Officer,
 RWD Work Division Bhabhua

18/04/23
 Executive Engineer,
 RWD Work Division Bhabhua

FORM GFR 19-A

(See Government of India's Decision (I) below Rule-150)

Form of Utilization Certificate up to date

Sl.No	Name of Scheme	Sanction No.&Date With Amount (In lace Rs.)	Amount Received (In lace Rs.)	Particulars
1	New Maintenance Policy- 2018 MR (3054) BRRDA PATNA	New Maintenance Policy-2018 MR (3054) BRRDA PATNA	8761.61868	Certified that out of 8761.61868 lakh of grants-in-aid sanctioned during the years 2023-24 In favor of EE,RWD works division Bhabhua a sum of Rs8477.13238 lakh has been utilized for the purpose of New Maintenance Policy- 2018 Schemes as given in the margin for which it was sanctioned and that the balance of Rs.284.48630 lakh remaining unutilized at the end of the period under report.
	Total:		8761.61868	


2. Certified that I have satisfied my self that the cosnditions on which the grant-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was utilized for the purpose for which it was sanctioned.


Kind of Checks exercised:-

- i. Works have been supervised by Executive Engineer/ Superintending Engineer.
- ii. Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- iii. Construction materials have been tested.
- iv. Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/ Executive Engineer.
- v. All other caudal formalities have been observed.

3. Physical Progress achieved:-

- i. Construction of Road Works.
- ii. Construction of CD works.


Divisional Accounts Officer
R.W.D, works Division
Bhabhua.


Executive Engineer
R.W.D, works Division
Bhabhua

Name of Customer: Parth Construction
 Name of Work/Road: T04 to Dharchoil
 Lab Job number: 80
 Date: 17-04-2023
 Section No: 80


Test Date: 17-04-2023
 Machine No: 412
 Start S No:
 Start E No:
 Weather:
 Start Location:
 End Location:
 Road Name: T04 to Dharchoil
 Road Type: (R) RURAL ROAD
 Side:
 Interval:
 UV Range: 1200 To 5000 mm/Km
 Dist Range: 0 To 5.7 0.1 • 1000 m
 Equation: $Y = 0.0 \cdot X^2 + 1.106 \cdot X + 132.5$

Print Generate Report and Graph

Redraw Graph

Map View

File: C:\Users\BPRDAS1\OneDrive\Desktop\skt\New Mr Bump 22-23\penkey\15_423\T04 to Dharchoil.xls.
 Name of Customer: Name of Work/Road: Lab Job number:



Handwritten notes:
 18.04.23
 18.04.23

Road Name - T04 to Dharcholl

Date	Time	Section No	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	CATE CODE	Latitude	Longitude	Event
17/4/23	8:18:12	80	0.1	190	0	1900	2790 G		24.92183	83.62838	Normal
17/4/23	8:18:51	80	0.1	280	30.3	2800	3313 G		24.92103	83.658147	Normal
17/4/23	8:19:10	80	0.1	300	30.3	3000	3540 G		24.920297	83.657793	Normal
17/4/23	8:19:52	80	0.1	250	40.4	2500	2972 G		24.91972	83.657473	Normal
17/4/23	8:20:11	80	0.1	240	40.4	2400	2858 G		24.91937	83.656902	Normal
17/4/23	8:20:53	80	0.1	300	30.3	3000	3540 G		24.918623	83.656665	Normal
17/4/23	8:21:14	80	0.1	260	40.4	2600	3086 G		24.917975	83.656565	Normal
17/4/23	8:21:55	80	0.1	300	30.3	3000	3540 G		24.917757	83.656935	Normal
17/4/23	8:22:16	80	0.1	230	40.4	2300	2745 G		24.91749	83.657423	Normal
17/4/23	8:22:57	80	0.1	300	30.3	3000	3540 G		24.917015	83.657744	Normal
17/4/23	8:23:18	80	0.1	290	30.3	2900	3426 G		24.916432	83.657525	Normal
17/4/23	8:23:53	80	0.1	240	40.4	2300	2745 G		24.916325	83.658163	Normal
17/4/23	8:24:10	80	0.1	300	30.3	3000	3540 G		24.916143	83.658905	Normal
17/4/23	8:24:56	80	0.1	230	40.4	2300	2745 G		24.915885	83.659595	Normal
17/4/23	8:25:12	80	0.1	220	40.4	2200	2631 G		24.915637	83.6601	Normal
17/4/23	8:25:53	80	0.1	300	30.3	3000	3540 G		24.915528	83.660202	Normal
17/4/23	8:26:14	80	0.1	290	30.3	2900	3426 G		24.915001	83.660408	Normal
17/4/23	8:26:55	80	0.1	300	30.3	3000	3540 G		24.914393	83.660767	Normal
17/4/23	8:27:16	80	0.1	310	30.3	3100	3654 G		24.913627	83.661653	Curve
17/4/23	8:27:57	80	0.1	300	30.3	3000	3540 G		24.913362	83.662266	Normal
17/4/23	8:28:18	80	0.1	200	40.4	2000	2404 G		24.913013	83.662831	Normal
17/4/23	8:28:52	80	0.1	300	30.3	3000	3540 G		24.912591	83.663573	Normal
17/4/23	8:29:20	80	0.1	290	30.3	2900	3426 G		24.912337	83.663975	Normal
17/4/23	8:29:51	80	0.1	220	40.4	2200	2631 G		24.911778	83.664841	Normal
17/4/23	8:30:22	80	0.1	300	30.3	3000	3540 G		24.911761	83.664856	Normal
17/4/23	8:30:53	80	0.1	280	30.3	2800	3313 G		24.911454	83.665676	Normal
17/4/23	8:31:24	80	0.1	300	30.3	3000	3540 G		24.91123	83.666989	Normal
17/4/23	8:31:55	80	0.1	290	30.3	2900	3426 G		24.911069	83.667942	Normal
17/4/23	8:32:26	80	0.1	280	30.3	2800	3313 G		24.911072	83.668582	Normal
17/4/23	8:32:57	80	0.1	270	30.3	2700	3199 G		24.91111	83.669462	Normal
17/4/23	8:33:28	80	0.1	300	30.3	3000	3540 G		24.911059	83.670135	Normal
17/4/23	8:33:57	80	0.1	220	40.4	2200	2631 G		24.910889	83.670649	Normal
17/4/23	8:34:30	80	0.1	300	30.3	3000	3540 G		24.910571	83.67191	Normal
17/4/23	8:34:53	80	0.1	280	30.3	2800	3313 G		24.910511	83.672604	Normal
17/4/23	8:35:32	80	0.1	290	30.3	2900	3426 G		24.910448	83.673857	Normal
17/4/23	8:35:53	80	0.1	250	40.4	2500	2972 G		24.910332	83.67473	Normal
17/4/23	8:36:34	80	0.1	270	30.3	2700	3199 G		24.910209	83.675878	Normal
17/4/23	8:36:55	80	0.1	310	30.3	3100	3654 G		24.910996	83.676341	Curve
17/4/23	8:37:16	80	0.1	300	30.3	3000	3540 G		24.911289	83.677085	Normal
17/4/23	8:37:57	80	0.1	310	30.3	3100	3654 G		24.912464	83.678039	Normal

$$Y = 0.0 \cdot X^2 + 1.136 \cdot X + 132.5$$

$$X = 2800$$

$$Y = 3313$$

(R) RURAL ROAD
Good Average Poor
<4000 4001-5000 >5001

Total IRI	
Average	3285.28

17/8/2023
20.04

17/4/23	8:38:18	80	0.1	300	30.3	3000	3540	G	24.91277	83.678163	Normal
17/4/23	8:39:59	80	0.1	250	40.4	2500	2972	G	24.913196	83.677681	Normal
17/4/23	8:40:13	80	0.1	300	30.3	3000	3540	G	24.914657	83.677531	Normal
17/4/23	8:40:54	80	0.1	310	30.3	3100	3654	G	24.915396	83.677736	Normal
17/4/23	8:41:15	80	0.1	280	30.3	2800	3313	G	24.916085	83.678229	Normal
17/4/23	8:41:56	80	0.1	300	30.3	3000	3540	G	24.916797	83.678803	Normal
17/4/23	8:42:17	80	0.1	310	20.2	3100	3654	G	24.916388	83.678094	Normal
17/4/23	8:42:58	80	0.1	230	40.4	2300	2745	G	24.915777	83.676511	Normal
17/4/23	8:43:19	80	0.1	290	30.3	2900	3426	G	24.91548	83.675584	Normal
17/4/23	8:43:50	80	0.1	300	30.3	3000	3540	G	24.94874	83.673906	Curve
17/4/23	8:44:21	80	0.1	280	30.3	2800	3313	G	24.914663	83.673129	Normal
17/4/23	8:44:52	80	0.1	230	40.4	2300	2745	G	24.914337	83.672232	Normal
17/4/23	8:45:23	80	0.1	300	30.3	3000	3540	G	24.914106	83.671363	Normal
17/4/23	8:45:54	80	0.1	310	30.3	3100	3654	G	24.913442	83.669502	Normal
17/4/23	8:46:25	80	0.1	300	30.3	3000	3540	G	24.913806	83.669443	Normal
17/4/23	8:46:56	80	0.1	280	30.3	2800	3313	G	24.914161	83.66956	Normal
17/4/23	8:47:27	80	0.1	230	40.4	2300	2745	G	24.915001	83.669665	Curve
17/4/23	8:47:55	80	0.1	290	30.3	2900	3426	G	24.915781	83.669869	Normal
17/4/23	8:48:16	80	0.1	300	30.3	3000	3540	G	24.916136	83.669932	Normal
17/4/23	8:48:57	80	0.1	310	30.3	3100	3654	G	24.917376	83.669937	Normal
17/4/23	8:49:28	80	0.1	230	40.4	2300	2745	G	24.917578	83.670204	Normal
17/4/23	8:49:58	80	0.1	300	30.3	3000	3540	G	24.917429	83.670999	Normal
17/4/23	8:50:19	80	0.1	280	30.3	2800	3313	G	24.917118	83.671753	Normal
17/4/23	8:50:51	80	0.1	280	30.3	2800	3313	G	24.920301	83.67382	Normal
17/4/23	8:51:22	80	0.1	270	30.3	2700	3199	G	24.920979	83.673922	Normal
17/4/23	8:51:53	80	0.1	280	30.3	2800	3313	G	24.925113	83.674747	Normal

18/4/23
A-E

18/04/23