

adharapur samasa xbaad to maganharapur.
kumar construction
Shedule XLV Form No. 134.

3/2

E. E R. W. D Harwadga
DIVISION

A. E R. W. D Harwadga
SUB-DIVISION

पत्रांक

Measurement Book

2375

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Measure of work: - Const. of road from					
old to new road to					
by the side					
Agmt - 02/01/2019/172-25					
Agmt - M/s. Hindustan Const.					
Const. dt - 01/04/23					
① Balcly					
① by ext. of road by					
$2 \times 13 \times 30 \times 0.375 \times 0.275 =$					80.937
$2 \times 5 \times 30 \times 0.375 \times 0.275 =$					30.937
					111.874
② G.S.B.:- Const. of G.S.B.					
by the side of road					
Const. dt -					
$2 \times 10 \times 30 \times 0.375 \times 0.20 =$					
$2 \times 3 \times 30 \times 0.375 \times 0.20 =$					
$2 \times 4 \times 30 \times 0.375 \times 0.20 =$					18.0 m ³
$2 \times 1 \times 10 \times 0.375 \times 0.20 =$					1.50 m ³
					19.50 m ³
② W.B.M.-:- Pl. laying					
Spreading & const.					
dt -					
$2 \times 4 \times 30 \times 0.375 \times 0.275 =$					6.75 m ³
$2 \times 1 \times 10 \times 0.375 \times 0.275 =$					0.562
					7.312 m ³

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L	B.	D.	
(17) Plancher of front on road side					
(Repaired after rain)					Qty = 98 m ²
(18) Pl. of facing on road side					
2.5 ft board					Qty = 0.1 m ²
(19) Pl. B/w in C.M (1:3)					
2 x 6.0 x 0.40 x 0.60 = 2.88 m ²					
(20) P.C.C. 120.0 Pl. P.C.C. 120.0 on ceiling					
2 x 6.0 = 12.0 m ²					
(21) Pl. Plastering with C.M (1:4)					
4 x 6.0 x 0.6 = 14.40					
2 x 6.0 x 0.4 = 4.80					
4 x 0.6 x 0.6 = 0.960					
20.160 m ²					
(22) Plastering two corners of wall					
4 x 6.0 x 0.6 = 14.40					
2 x 6.0 x 0.4 = 4.80					
4 x 0.6 x 0.6 = 0.960					
20.160 m ²					

Continuation

3/8/23
20

31/3/23
J.E.