

Name of Customer: Shalendra Kumar Tiwary  
 Name of Work: T03 to Deharaya  
 Road: T03 to Deharaya  
 Lab Job number: 25  
 Date: 19-04-2023  
 Section No: 25


Test Date: 19-04-2023  
 Machine No: 391  
 Start S No: 67  
 Start E No: 78  
 Weather: Normal  
 UV Range: 1615 To 4000 mm/km  
 Dist Range: 0 To 1.3  
 Equation:  $Y = 0.0 \times X^2 + 1.000 \times X + 415.2$

Road Name: T03 to Deharaya  
 Road Type: (R) RURAL ROAD  
 Side: Chennai  
 Interval:

Print Generate Report and Graph

Redraw Graph

Map View



19-04-23  
 J.E.  
 19/04/2023  
 J.E.  
 25.04.23

Activate Windows  
 Go to Settings to activate Windows

**कार्यपालक अभियंता का कार्यालय  
ग्रामीण कार्य विभाग, कार्य प्रमंडल, सासाराम-1**

Email ID:-ee.rwd.sasaram1@gmail.com Mob:- 8986915310

पत्रांक.....822 2057 सासाराम/दिनांक 25/04/2023

प्रेषक,

कार्यपालक अभियंता,  
ग्रामीण कार्य विभाग,  
कार्य प्रमंडल, सासाराम-1

सेवामें,

नोडल पदाधिकारी (MR 3054)  
ग्रामीणकार्यविभाग  
पटना, बिहार

विषय :- नई अनुस्क्षण नीति-2018MR (3054) योजना के अंतर्गत पथ में कराये गये कार्य के विरुद्ध आवंटन उपलब्ध कराने के संबंध में।

महाशय,

उपरोक्त विषय के संबंध में सूचित करना है कि नई अनुस्क्षण नीति-2018 MR (3054) योजना के अंतर्गत पथ में कराये गये कार्य के लिए संवेदक को भुगतान करने हेतु अधियाचना विहित प्रपत्र में भरकर आवश्यक कार्यवाही हेतु समर्पित की जाती है।

अनु0 :- यथोक्त।

विश्वासभाजन

MR 3054  
25.04.23  
कार्यपालक अभियंता,  
ग्रामीण कार्य विभाग,  
कार्य प्रमंडल, सासाराम-1  
25/04/23

(See Government of India's Decision (I) below Rule-150)

## Form of Utilization Certificate up to April 2023

| No | Name of Scheme                       | Sanction No.&Date With Amount (In lace Rs.)                | Amount Received (In lace Rs.) | Particulars                                                                                                                                                                                                                                                                                                                                                                            |
|----|--------------------------------------|------------------------------------------------------------|-------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 1  | Construction of Rural roads Under MR | New<br>Maintenance Policy-2018<br>MR (3054)<br>BRRDA PATNA | 10129.95178                   | Certified that out of Rs. 10129.95178 lakh of grants-in-aid sanctioned during the years 2021-23 in favor of EE, RWD works division Sasaram-1a sum of Rs 9946.64443akh has been utilized for the purpose of MR (3054) Schemes as given in the margin for which it was sanctioned and that the balance of Rs. 183.30735 lakh remaining unutilized at the end of the period under report. |
|    | Total:                               |                                                            | 10129.95178                   |                                                                                                                                                                                                                                                                                                                                                                                        |

2. Certified that I have satisfied my self that the conditions on which the grant-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was utilized for the purpose for which it was sanctioned.

**Kind of Checks exercised:-**

- Works have been supervised by Executive Engineer/ Superintending Engineer.
- Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- Construction materials have been tested.
- Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/ Executive Engineer.
- All other caudal formalities have been observed.

**3. Physical Progress achieved:-**

- Construction of Road Works.
- Construction of CD works.

Divisional Accounts Officer  
R.W.D, works Division  
Sasaram-1

Executive Engineer

R.W.D, works Division  
Sasaram-1

Registration Format for Scheme Head- MR(3054) under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

25.04.23

25/04/23

4/12/23

| Sr no.       | Batch No                  | Name of Road                | Project ID as per MIS | Administrative Approval (AA) Letter No & Date | Length<br>(in km) | Amount of<br>(in lakh) | Initial Rectification with Surface Renewal<br>(in lakh) | 5 Year Routine Maintenance<br>(in lakh) | Agreement Amount<br>(in lakh) | Date of Completion as per Agreement | Actual Date of Completion | Value of Bitumen Layer Thickness<br>(in mm) | Value of Bitumen Content in Bitumen<br>Percentage | Total Allocated amount Previous up-to-date expenditure as per MIS<br>(in lakh) | Requisition done against work<br>(in Lakh) | Remarks  |
|--------------|---------------------------|-----------------------------|-----------------------|-----------------------------------------------|-------------------|------------------------|---------------------------------------------------------|-----------------------------------------|-------------------------------|-------------------------------------|---------------------------|---------------------------------------------|---------------------------------------------------|--------------------------------------------------------------------------------|--------------------------------------------|----------|
| 1            | RM/RO/<br>SAS/23/<br>0001 | L070-T03 TO DEHRIVA (ODR40) | 10301002275           | 911<br><u>15.07.2022</u>                      | 1.2               | 60.508                 | 45.42115                                                | 10.96299                                | 45.42115                      | 15/11/2023                          | 0                         | 3098                                        | 25.00                                             | 5.00                                                                           | -                                          | 40.54112 |
| <b>Total</b> |                           |                             |                       |                                               |                   |                        |                                                         |                                         |                               |                                     |                           |                                             |                                                   |                                                                                |                                            |          |
|              |                           |                             |                       |                                               | 1.2               | 60.508                 | 45.42115                                                | 10.96299                                | 45.42115                      |                                     |                           |                                             |                                                   | -                                                                              | 40.54112                                   |          |

# Name of Road:- T03 to Dehariya

| Date        | Time     | Section | Length | Bumps | Speed | OR   | IRI  | CATEGORY | Latitude  | Longitude | Event         |
|-------------|----------|---------|--------|-------|-------|------|------|----------|-----------|-----------|---------------|
| 19/4/23     | 17:16:27 | 25      | 0.1    | 260   | 20.2  | 2600 | 3015 | G        | 24.93524  | 83.817137 | Culvert       |
| 19/4/23     | 17:16:42 | 25      | 0.1    | 240   | 20.2  | 2400 | 2815 | G        | 24.934693 | 83.817878 | Normal        |
| 19/4/23     | 17:17:2  | 25      | 0.1    | 280   | 10.1  | 2800 | 3415 | G        | 24.934362 | 83.81877  | Speed Breaker |
| 19/4/23     | 17:17:22 | 25      | 0.1    | 290   | 20.2  | 2900 | 3315 | G        | 24.93428  | 83.819713 | Normal        |
| 19/4/23     | 17:17:37 | 25      | 0.1    | 300   | 20.2  | 3000 | 3215 | G        | 24.93429  | 83.82069  | Normal        |
| 19/4/23     | 17:18:0  | 25      | 0.1    | 260   | 10.1  | 2600 | 3015 | G        | 24.93393  | 83.821565 | Normal        |
| 19/4/23     | 17:18:12 | 25      | 0.1    | 250   | 10.1  | 2500 | 3215 | G        | 24.933573 | 83.822525 | Curve         |
| 19/4/23     | 17:19:23 | 25      | 0.1    | 250   | 10.1  | 2500 | 3415 | G        | 24.934298 | 83.822945 | Speed Breaker |
| 19/4/23     | 17:20:0  | 25      | 0.1    | 250   | 10.1  | 2500 | 2915 | G        | 24.93513  | 83.823298 | Normal        |
| 19/4/23     | 17:20:10 | 25      | 0.1    | 300   | 20.2  | 3000 | 2915 | G        | 24.935968 | 83.82345  | Normal        |
| 19/4/23     | 17:20:34 | 25      | 0.1    | 220   | 20.2  | 2200 | 2615 | G        | 24.936647 | 83.82409  | Normal        |
| 19/4/23     | 17:21:0  | 25      | 0.1    | 260   | 10.1  | 2600 | 3315 | G        | 24.937438 | 83.824057 | Curve         |
| Average IRI |          |         |        |       |       |      |      |          |           |           |               |
| 3098        |          |         |        |       |       |      |      |          |           |           |               |

$$Y = 0 * X^2 + 1.000 * X + 415.2$$

$$X = 3000$$

$$Y = 3415$$

(R) RURAL ROAD

Good Average Poor

<4000 4001-5000 >5001

Executive Engineer  
Rural Work's Department  
Work Division, Sasaram-1

25.04.23

19/04/2023  
AF

19.04.23  
J.E