

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, समस्तीपुर

पत्रांक1616 ~~2730~~ दिनांक. 1/8/23

प्रेषक:— कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, समस्तीपुर।

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी—सह—सचिव
ग्रामीण कार्य विभाग, बिहार, पटना।

विषय:— शीर्ष New Maintenance Policy 2018 मद में आवंटन उपलब्ध कराने के संबंध में।
महाशय,
उपर्युक्त विषयक शीर्ष New Maintenance Policy 2018 योजनान्तर्गत निर्मित/
निर्माणाधीन पथों का विहित प्रपत्र में अधियाचना पत्र संलग्न कर भेजा जा रहा है।
अतः अनुरोध है कि संलग्न अधियाचना पत्र के अनुसार आवंटन उपलब्ध कराने की कृपा
की जाय।

अनु०—यथोक्त।

विश्वासभाजन


कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, समस्तीपुर

FROM GFR 19-A**(See Government of India's Division (I) below Rule- 150)****Form of Utilization Certificate upto 31.07.2023****PIU- E.E., R.W.D. Works Division, Samastipur**

S.N.	Name of Scheme	Sanction No.& Date	Amount Received	Particulars
1	Construction of Rural Road under New Maintenance Policy-2018	Secretary cum Empowered Officer BRRDA Bihar Patna vide upto Lt. no.-100 dt.14.07.2023	606314763.00	Certified that out of Rs.606314763.00 received upto 31.07.2023 in favour of Executive Engineer R.W.D. Works Division Samastipur a sum of Rs.573690449.00 has been utilized for the purpose of New Maintenance Policy-2018 Schemes as given in the margine for which it was sanctioned and that the balance of Rs. 32624314.00 remaining unutilized at the end of period under report.
			60,63,14,763.00	

2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for the which it was sanctioned.

Kind of Checks exercised:-

- i Works have been supervised by Executive/Superintending engineer.
- ii Periodical inspection has been conducted by Executive/Superintending engineer.
- iii Construction materials have been tested.
- iv Measurements have been recorded in the MB's and test check conducted by Assistant Engineer/Executive
- v All other codal formalities have been observed.

3 Physical Progress achieved:-

- i Construction of Road work.
- ii Construction of CD works.

24
1.8.23

Executive Engineer
Works Division Samastipur
Rural Works Dipartment

Requisition Format for scheme Head : MR(3054) Under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

RWD, Works Division : Samastipur																		
Sl No	Package No	Project ID as Per MIS	Name of Road	Administrative Approval (AA) Letter No & Date	Length (Km)	Administrative Amount	Agreement No & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (In mm/km)	Thickness of Bitumen Layer (In MM)	Value of Bitumen Content in Percentage	Previous Total Allocated Amount (In Lakh)	Upto date Expenditure as per MIS (In Lakh)	Requisition against work done (In Lakh)	Remarks		
						Amount (In Lakh)	Initial Rectification with Surface Renewal	5 Year Routine Maintenance										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
2	RM/SA/SAM/23/0003	32010102162	L037-SH to Akbarpur (ODR37)	1376 & 06.09.2022	1.900	83.250	58.328	21.995	129(MBD)2022-23	09.12.2023	Complete	2673	25	5.0	0	0	58.010	Complete
3		32010102198	L062-X Road to to L060Gangaparan (ODR62)		1.555	86.063	65.383	16.467		09.12.2023	Complete	3071	25	5.0	0	0	65.320	Complete
Total						169.313	123.711	38.462									123.330	

1 Signed Hard Copy and Soft Copy (In Excel) of recorded IRI is enclosed.

2 Up-to-date Physical Progress has been uploaded in MIS

M
1.8.22

**Executive Engineer
RWD (W) Div. Samastipur**

Name of Road :- L037 SH To Akbarpur

Section no.-20

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	CATEGORY	Latitude	Longitude	Event
28/7/23	12:55:41	20	0.1	220	0	2200	2631	ROAD	25.918465	85.771863	Normal
28/7/23	12:56:19	20	0.1	230	10.1	2300	2745	G	25.91912	85.772519	Normal
28/7/23	12:57:0	20	0.1	220	10.1	2200	2631	G	25.919849	85.772812	Normal
28/7/23	12:57:39	20	0.1	210	10.1	2100	2518	G	25.920049	85.772956	Normal
28/7/23	12:58:7	20	0.1	220	10.1	2200	2631	G	25.921536	85.773477	Normal
28/7/23	12:58:46	20	0.1	210	10.1	2100	2518	G	25.921706	85.773889	Curve
28/7/23	12:59:11	20	0.1	230	10.1	2300	2745	G	25.922061	85.775418	Normal
28/7/23	12:59:42	20	0.1	230	10.1	2300	2745	G	25.922624	85.775631	Normal
28/7/23	13:1:8	20	0.1	220	10.1	2200	2631	G	25.923427	85.775718	Normal
28/7/23	13:1:32	20	0.1	240	10.1	2400	2858	G	25.924067	85.775385	Normal
28/7/23	13:2:17	20	0.1	230	10.1	2300	2745	G	25.924313	85.774235	Normal
28/7/23	13:2:39	20	0.1	220	10.1	2200	2631	G	25.924137	85.773688	Curve
28/7/23	13:3:3	20	0.1	240	10.1	2400	2858	G	25.924316	85.772438	Normal
28/7/23	13:3:48	20	0.1	220	10.1	2200	2631	G	25.924257	85.771468	Normal
28/7/23	13:4:9	20	0.1	230	20.2	2300	2745	G	25.924653	85.770594	Normal
28/7/23	13:4:46	20	0.1	220	10.1	2200	2631	G	25.925522	85.770439	Curve
28/7/23	13:5:5	20	0.1	210	10.1	2100	2518	G	25.925838	85.769601	Normal
28/7/23	13:5:45	20	0.1	220	10.1	2200	2631	G	25.926341	85.768935	Normal
28/7/23	13:6:23	20	0.1	230	10.1	2300	2745	G	25.926466	85.7674	Normal


Total = 1.90 Km Avg. 2673.05


 Executive Engineer
 R.W.D.(W) Division,
 Samastipur


 18/8/23

File : C:\Users\kishor ji\Desktop\L037 SH To Akbarpur\28071306.Xls, Section No. :20, Eqn : $Y = 0 \cdot X^2 + 1.136 \cdot X$

Name of Customer : Baleshwar Prasad Singh, Name of Work/ Road : L037 SH To Akbarpur, Lab Job number : 20



1.8.20

1.8.20