

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमण्डल, मोतिहारी।

पत्रांक.....3107..... / दिनांक.....20/12/2023

प्रेषक

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल मोतिहारी।

सेवा में,


अपर मुख्य कार्यपालक पदाधिकारी,
—सह—सचिव BRRDA,
बिहार, पटना।

विषय — MR-3054(New Maintenance Policy 2018) के अन्तर्गत पथ के निर्माण के लिए निधि उपलब्ध कराने के संबंध में।

महाशय,

उपर्युक्त विषय के संबंध में कहना है कि MR-3054(New Maintenance Policy 2018)के अन्तर्गत पथ के निर्माण के लिए निधि हेतु सूची बनाकर इस पत्र में संलग्न कर भवदीय के अवलोकनार्थ एवं आवश्यक कार्रवाई हेतु समर्पित की जा रही है।
अनु०:— यथोक्त।

विश्वासभाजन


कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, मोतिहारी।
20/12/23

Office of the Executive Engineer, Road							
Requestion formate for Scheme Head- MR-3054 Under Bihar Rural Road Maintenance Policy -2018 (Initial Rectification with Surface Renewal)							

881
2012123
Junior Engineer

Done
20/12/22
Asst. Engineer

Sr. Divisional Accounts Officer
Rural Works Department,

**Executive Engineer,
Rural Works Department,**

R.W.D Work Division Motihari

FORM GFR 19A

(See Government of India's Decision (1) below Rule-150)
Form of Utilisation Certificate up to the month of 14.07.2023
MR HEAD-3054 (Initial Rectification with Surface Renewal)

Sl. No.	Name of Scheme	Selection No. of Date with Amount (in Rs. In Lacs)	Amount Received (in Rs. In Lacs)	Particulars
1	Construction of Rural Roads under MR HEAD-3054 (Initial Rectification with Surface Renewal)	Vide Letter no 100 dated 14.07.2023	11660.27723	Certified that out of Rs.11660.27723 Lacs received during the years 2022-23 in favour of Executive Engineer, R.W.D. Works Division, Motihari A sum of Rs.11211.44857 Lacs has been utilised for the purpose of MR HEAD-3054 (Initial Rectification with Surface Renewal) Scheme as given in the margin or whichever sanctioned and that the balance Rs.448.82866 Lacs remaining unutilised at the end of the period under.
			11660.27723	

- 2 Certified that I have satisfied myself that the conditions on which the grant-in-aid was sanctioned have been duly fulfilled/ are being fulfilled and that I have exercised the following checks to see that the money was actually utilised for the purpose for which it was sanctioned.

Kinds of exercised :-

- Works have been supervised by Executive Engineer/ Superintending Engineer.
- Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- Construction Material have been testes.
- Measurement have been recorded in the MBs and test check conducted by the Assistant.
- All other codal formalities have been observed.

3 Physical Progress achieved :-

- Construction of Road Works.
- Construction of CD Works.

[Signature]
Sr. Divisional Accounts Officer
Rural Works Department,
Works Division, Motihari

[Signature]
Executive Engineer,
Rural Works Department,
Works Division, Motihari

Name of Road :- NHPC Phokhra to Ahir tola yadav tola

Date	Time	Secl Leng th	Bumps	Speed	OR	IRI	CATEG	Latitude	Longitu	Event
		No. in km	in mm	Rate	mm/km	UV	ROAD			
16/12/23	8:17:18	44	0.1	320	0	3200	3303 G	4.38	26.49238	84.83559 Normal
16/12/23	8:18:0	44	0.1	350	10.1	3500	3602 G	4.74	26.49232	84.83653 Curve
16/12/23	8:18:29	44	0.1	340	10.1	3400	3502 G	4.62	26.49209	84.83747 Bridge
16/12/23	8:19:3	44	0.1	370	0	3700	3802 G	4.97	26.49192	84.83843 Normal
16/12/23	8:20:0	44	0.1	360	0	3600	3702 G	4.85	26.49163	84.83936 Curve
16/12/23	8:20:13	44	0.1	280	0	2800	2903 G	3.91	26.49074	84.83938 Normal
16/12/23	8:21:24	44	0.1	290	0	2900	3003 G	4.03	26.48993	84.83938 Normal
16/12/23	8:21:24	44	0.1	200	10.1	2000	2105 G	2.93	26.48941	84.84008 Curve
16/12/23	8:21:24	44	0.1	200	20.2	2000	2105 G	2.93	26.48905	84.84098 Curve
16/12/23	8:22:0	44	0.1	190	10.1	1900	2005 G	2.81	26.48955	84.8416 Curve
16/12/23	8:22:35	44	0.1	170	10.1	1700	1806 G	2.56	26.48915	84.84242 Culvert
16/12/23	8:23:10	44	0.1	200	10.1	2000	2105 G	2.93	26.48859	84.84311 Curve
16/12/23	8:23:10	44	0.1	190	10.1	1900	2005 G	2.81	26.48796	84.84375 Curve
16/12/23	8:23:45	44	0.1	180	20.2	1800	1905 G	2.68	26.48799	84.84476 Curve
16/12/23	8:24:0	44	0.1	210	20.2	2100	2205 G	3.06	26.48727	84.84515 Normal
16/12/23	8:24:20	44	0.1	220	20.2	2200	2305 G	3.18	26.4864	84.8452 Normal
16/12/23	8:24:20	44	0.1	260	20.2	2600	2704 G	3.67	26.48549	84.84502 Normal
16/12/23	8:24:20	44	0.1	230	20.2	2300	2404 G	3.3	26.48463	84.84524 Curve
16/12/23	8:25:0	44	0.1	180	20.2	1800	1905 G	2.68	26.48379	84.84537 Normal
16/12/23	8:25:0	44	0.1	200	20.2	2000	2105 G	2.93	26.48285	84.84532 Normal
16/12/23	8:25:31	44	0.1	190	20.2	1900	2005 G	2.81	26.48203	84.84535 Normal
16/12/23	8:25:31	44	0.1	180	20.2	1800	1905 G	2.68	26.48115	84.84537 Normal
16/12/23	8:26:0	44	0.1	190	20.2	1900	2005 G	2.81	26.48026	84.84539 Culvert
16/12/23	8:26:0	44	0.1	190	20.2	1900	2005 G	2.81	26.47937	84.84554 Normal
16/12/23	8:26:6	44	0.1	210	20.2	2100	2205 G	3.06	26.47849	84.84539 Normal
16/12/23	8:26:6	44	0.1	330	10.1	3300	3402 G	4.5	26.47762	84.84544 Bridge
16/12/23	8:27:17	44	0.1	290	10.1	2900	3003 G	4.03	26.47693	84.84547 Curve
16/12/23	8:27:17	44	0.1	180	20.2	1800	1905 G	2.68	26.47615	84.84591 Normal
16/12/23	8:27:52	44	0.1	220	10.1	2200	2305 G	3.18	26.47557	84.84678 Culvert
16/12/23	8:28:0	44	0.1	260	10.1	2600	2704 G	3.67	26.47504	84.84758 Normal
16/12/23	8:29:3	44	0.1	350	0	3500	3602 G	4.74	26.47449	84.84798 Normal
16/12/23	8:29:38	44	0.1	290	10.1	2900	3003 G	4.03	26.47364	84.84801 Normal
16/12/23	8:30:0	44	0.1	280	10.1	2800	2903 G	3.91	26.47275	84.84832 Normal

$$Y = 0 * X^2 + 0.998 * X + 109.5$$

$$X = 2800$$

$$Y = 2903$$

(R) RURAL ROAD

Good Average Poor
<4000 4001-5000 >5001


Total IRI SUM 84433
Total IRI Average 2558.6

88/12/23
20/12/23
16/12/23

Bum
20/12/23
AC

Verifed
20/12/23
ee

File : F:\Bump March Month\Manoranjan kumar Singh\NHPC Pokhara to Ahir tola Yadav tola tak\10121902.Xls,
 Name of Customer : NPC Phokar to Ahir tola Yadav tola tak, Name of Work/ Road : Manoranjan kumar Singh, Lab



8/11/2012
 20/12/12

8/11/2012
 20/12/12

8/11/2012
 20/12/12

8/11/2012
 20/12/12