

बिहार सरकार
कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, लखीसराय

पत्रांक:- 2382

लखीसराय/ दिनांक:- 21-12-2023

प्रेषक,

ई0 अशुतोष कुमार
कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, लखीसराय।

सेवा में,

नोडल पदाधिकारी
नई अनुरक्षण नीति 2018 (MR 3054),
ग्रामीण कार्य विभाग, बिहार, पटना।

विषय:- MR 3054/ नई अनुरक्षण नीति 2018 के अन्तर्गत कराये गये कार्य के विरुद्ध में
आवंटन उपलब्ध कराने के संबंध में।

महाशय,

उपर्युक्त विषय के संबंध में सूचित करना है कि MR 3054/ "नई अनुरक्षण नीति 2018" के अन्तर्गत NH-80 Bodhana to Block undany Lakhisarai पथ कार्य पूर्ण हो चुका है। उक्त पथ में किये कार्य का भुगतान हेतु कुल 59.20000 लाख (Fifty Nine lakh Twenty thousand) मात्र के भुगतान हेतु आवंटन की अधियाचना विहित प्रपत्र में तैयार कर समर्पित की जाती है।

अतः सादर अनुरोध है कि शीघ्र आवंटन उपलब्ध कराने की कृपा की जाय।

अनु0-यथोक्त।

विश्वासभाजन



(ई0 अशुतोष कुमार)
कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमंडल लखीसराय

RWD Works Division, Lakhisarai

Requisition Format for Scheme Head- MR (3054) Under Bihar Rural Road " New Maintenance Policy 2018" (Initial Rectification and Surface Renewal)

Name of Division:- Lakhisarai																		
S. No.	Package No.	Name of Road	Project ID as per MIS	Administrative Approval (A.A) Letter No. & Date	Administrative Approval (A.A)		Agreement Amount (in Lakh)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI in MM/KM	Thickness of Bitumen Layer (in MM)	Value of Bitumen Content (in %)	Previous Total Allocated Amount (in Lakh)	Up-to-date expenditure as per MIS (in Lakh)	Requisition done against work (in Lakh)	Remarks
					Length (KM)	Amount (in Lakh)	Initial Rectification with Surface Renewal (in Lakh)	5 Year Routine Maintenance										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	MR-N/23-24/ Lakhisarai/ 10	NH-80 Bodhana to Block Boundary Lakhisarai	28401904525	2328 & 04.05.2023	1.433	95.72500	66.40932	18.11051	42/MBD/23-24 & 06.11.2023	05.08.2024	18.12.2023	3183	25	5.06	0	0	59.20000	

21/12/2023
OK
OK

21/12/2023
OK

Executive Engineer
RWD Works Division Lakhisarai

NH-80 Bodhana to Block Boundany Lakhisarai

Date	Time	Section	Length	Bumps	Speed	OR	IRI	TEGORY	Latitude	Longitude	Event
		No.	in km	in mm	Rate	mm/km	mm/km	ROAD			
21/12/23	11:36:58	36	0.1	290	10.1	2900	3426	G	25.190266	86.17165	Normal
21/12/23	11:37:25	36	0.1	270	10.1	2700	3199	G	25.188397	86.170711	Normal
21/12/23	11:37:59	36	0.1	260	20.2	2600	3086	G	25.18763	86.170347	Normal
21/12/23	11:38:39	36	0.1	260	20.2	2600	3086	G	25.186831	86.170018	Normal
21/12/23	11:39:0	36	0.1	270	20.2	2700	3199	G	25.186073	86.169989	Normal
21/12/23	11:39:37	36	0.1	260	20.2	2600	3086	G	25.185453	86.169855	Normal
21/12/23	11:40:4	36	0.1	280	10.1	2800	3313	G	25.184782	86.169809	Normal
21/12/23	11:40:44	36	0.1	270	10.1	2700	3199	G	25.174864	86.167128	Normal
21/12/23	11:41:0	36	0.1	280	10.1	2800	3313	G	25.17345	86.166758	Curve
21/12/23	11:41:47	36	0.1	270	10.1	2700	3199	G	25.172592	86.166465	Normal
21/12/23	11:43:23	36	0.1	260	20.2	2600	3086	G	25.171042	86.166611	Normal
21/12/23	11:43:55	36	0.1	250	10.1	2500	2972	G	25.170397	86.166675	Normal
21/12/23	11:44:36	36	0.1	260	10.1	2600	3086	G	25.169621	86.166651	Normal
21/12/23	11:45:0	36	0.1	280	10.1	2800	3313	G	25.169822	86.166201	Normal

3183.07

$$Y = 0 * X^2 + 1.136 * X + 132.5$$

X = 2800
Y = 3313

(R) RURAL ROAD

Good Average Poor
<4000 4001-5000 >5001

[Signature]
21/12/23
JG 105

[Signature]
21/12/23
JG

[Signature]
Executive Engineer
RWD Works Division
Lakhisarai

Name of Customer : Manju Devi
 Name of Work/ Road : NH-80 Bodhana to Block Bouni
 Lab Job number : 36
 Date : 21-Dec-23
 Section No. : 36


Test Date : 21-Dec-23 Road Name : NH-80 Bodhana to Block Bouni
 Machine No : 399 Road Type : (R) RURAL ROAD
 Start S No : Side :
 Start E No : Interval
 Weather : UIV Range : 1972 To 4000 1000 mm/km
 Start Location : Dist Range : 0 To 1.5 0.1 * 1000 m
 End Location : Equation : $Y = 0 * X^2 + 1.136 * X + 132.5$

Print

Generate Report and Graph

Redraw Graph

Map View



21/12/23
 AC (U)

Uppal
 21/12/23

21/12/23
 Executive Engineer
 RWD Works Division
 Lakhisarai