

Name of work - Hatcherak To 1029

MMUNSY (SC)

Schedule XLV Form No. 134.

Agency - Amil Raj

**Executive Engineer
R.W.D. Works Division**

Rajawati DIVISION

A.E. Rajawati SUB-DIVISION

Measurement Book

M.B.No - 1053

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1. Provide & apply 1st coat of concrete					
mark & all work done					
VTMBP = 7 = 140.23749 = 45/m ²					3950 = m
2. Apply 2nd coat of concrete					
VTMBP = 7 = 241.1782 = 77/m ²					3566 = m
3. Apply 3rd coat of concrete					
VTMBP = 7 = 0.24113 = 76/m ²					12272 = m
4. Cost of concrete work with mark & all					
VTMBP = 15 = 109.42m ² / 188 = 89/m ²					20576 = m
5. Cost of concrete work with mark & all					
VTMBP = 15 = 241.56m ² / 142 = 17/m ²					34627 = m
6. Cost of concrete work with mark & all					
VTMBP = 15 = 1215.40 m ³					
VTMBP = 14 = 272.32 m ³					
1437.32m ³ / 189 = 89/m ³					282427 = m
7. Cost of concrete work with mark & all					
VTMBP = 8 = 365.92m ³ / 1341 = 75/m ³					673926 = m
8. Apply 1st coat of concrete					
VTMBP = 8 = 151.67 m ²					
VTMBP = 10 = 18.39 m ³					
170.06 m ³ / 227.26 = 53/m ³					6463674 = m
9. Provide & apply primer coat					
with bitumen emulsion (SS-V) all					
VTMBP = 12 = 1136.25m ² / 43 = 14/m ²					49018 = m

Continuation

1544036 = m

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
18. Rect. m.s. grade boundary			15		291178 =
field - - - - - of all					
VTMBP-11 =	16	14	2 = 19/m		7553 =
19. Prod. 2 lines of redwood					
2 in. of sign board - - - of all					
VTMBP-16 =	9	14	358 = 38/m		31665 =
20. Prod. 2 lines of redwood					
2 in. of sign board - - - of all					
VTMBP-16 =	7	14	64 = 64/m		33288 =
21. Prod. 2 lines of redwood					
2 in. of sign board - - - of all					
VTMBP-16 =	3	14	665 = 27/m		19926 =
22. Prod. 2 lines of redwood					
2 in. of sign board - - - of all					
VTMBP-16 =	2	14	8498 = 27/m		16996 =
23. Prod. 2 lines of redwood					
2 in. of sign board - - - of all					
VTMBP-16 =	2	14	818 = 77/m		19649 =
24. Prod. 2 lines of redwood					
2 in. of sign board - - - of all					
VTMBP-13 =	61	14	544 = 44/m		49862 =
25. Prod. 2 lines of redwood					
2 in. of sign board - - - of all					
VTMBP-13 =	13	15	824 = 29/m		48556 =
26. Prod. 2 lines of redwood					
2 in. of sign board - - - of all					
VTMBP-8 =	59	14	294 = 73/m		17578 =
27. Prod. 2 lines of redwood					

Continuation

3151781 FM

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
for plain concrete in open					3151781 = 4
sub-station					
VTMBP-8 = 5.562 m ² 4338 = 43/3					24144 = 0
28. Plain/Reinforced concrete in					
sub-station					
VTMBP-5 = 14.06 m ²					
VTMBP-8 = 34.199 m ²					
25070 = 0.6 / m ²					244651 = 7
29. Road & lay of 1000 mm					
sign sheet for					
VTMBP-8 = 30 m 29/3 = 52/3					274062 = 7
30. Road & lay of 1000 mm					
and HP					
VTMBP-8 = 15 m 23652 = 27/m					57786 = 7
31. Primary treatment in 1000 mm					
fall					
VTMBP-13 = 26.53 m ² 497 = 17/4					2578 = 4
				B	3508346 = 7
Add 14.422				L	35083 = 7
made of ST. 120				B	3543523 = 7
				B	421002 = 7
				L	3964431 = 7
Add 1000 S.P.				B	52369 = 4
				B	4016800 = 7
Less 18.55% as for 1000				B	745116 = 4
Less 18.55% as for 1000				B	3271684 = 7
Less 18.55% as for 1000				B	1573502 = 7
✓ 10/3/22				B	1698182 = 7
JE				AE	

Continuation