

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग कार्य प्रमण्डल, बाँका-2

पत्रांक...../बाँका

दिनांक

प्रेषक,

कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, बाँका-2

सेवा में,

नोडल पदाधिकारी 3054/MR
ग्रामीण कार्य विभाग,
बिहार, पटना।

विषय :- शीर्ष "3054 एम0आर0" New Maintenance Policy 2018 योजना अन्तर्गत आवंटन की अधियाचना के संबंध में।

महाशय,

उपर्युक्त विषय के संबंध में कहना है कि "3054 एम0आर0" New Maintenance Policy 2018 योजना के अन्तर्गत पथों में कराये जा रहे कार्यों के भुगतान हेतु राशि-31,84,555/- अधियाचना विहित प्रपत्र में उपयोगिता प्रमाण-पत्र एवं मापी पुस्त प्रमाण-पत्र सहित समर्पित किया जा रहा है।

अनुरोध है कि आवंटन उपलब्ध कराने हेतु अग्रेतर एवं आवश्यक कार्रवाई करने की कृपा की जाय।

अनु0:-1. अधियाचना प्रपत्र
2. IRI Report

विश्वासभाजन

ह0/-


कार्यपालक अभियंता
ग्रा0का0वि0, कार्य प्रमण्डल,
बाँका-2

ज्ञापक.....~~26.03.23~~...../बाँका दिनांक ...~~15.12.23~~.....

प्रतिलिपि - मुख्य अभियंता-4, ग्रामीण कार्य विभाग, बिहार, पटना को सूचनार्थ एवं आवश्यक कार्रवाई हेतु समर्पित।


15.02.23

कार्यपालक अभियंता
ग्रा0का0वि0, कार्य प्रमण्डल,
बाँका-2


15.02.23

Form GFR 19-A

(See Government of India's Decision (I) below rule-15)
Form of utilization Certificate up to the Month January' 2023
MR/3054(NEW MAINTENANCE POLICY)

PIU-RWD(W), BANKA-2

Sl. No.	Name of Scheme	Sanction No. & Date with Amount (in Rs. Lacs)	Amount Received (in Rs. Lacs)	Particulars
1	Construction of Rural roads under MR/3054(NEW MAINTENANCE POLICY)	विभागीय पत्रांक 37 दिनांक 27.05.2020 45(Encl)/18.06.2020 56(Encl)/12.08.2020 59(Encl)/18.08.2020 61(Encl)/26.08.2020 82(Encl)/13.11.2020 84(Encl)/26.11.2020 86(Encl)/11.12.2020 05(Encl)/12.01.2021 17(Encl)/26.02.2021 20(Encl)/19.03.2021 22(Encl)/24.03.2021 27(Encl)/04.05.2021 30(Encl)/21.05.2021 32(Encl)/28.05.2021 52(Encl)/24.08.2021 58(Encl)/27.10.2021 60(Encl)/09.11.2021 64(Encl)/06.12.2021 71(Encl)/28.12.2021 02(Encl)/03.01.2022 05(Encl)/25.01.2022 08(Encl)/29.01.2022 10(Encl)/21.02.2022 13(Encl)/28.02.2022 16(Encl)/08.03.2022 18(Encl)/11.03.2022 22(Encl)/16.03.2022 46(Encl)/13.04.2022 49(Encl)/27.04.2022 01(Encl)/20.05.2022 21(Encl)/08.08.2022 35(Encl)/13.10.2022 44(Encl)/18.11.2022 48(Encl)/30.11.2022 04(Encl)/10.01.2023 09(Encl)/23.01.2023 10(Encl)/27.01.2023 12(Encl)/03.02.2023	217.86340 30.12339 525.63100 320.50000 6.57325 88.44000 395.49360 368.11196 570.35090 604.70836 361.33115 82.05330 88.60000 58.28940 440.19502 97.98875 319.50000 1100.18551 165.89874 116.14900 68.05073 125.09748 106.92341 87.71454 31.30475 34.36336 67.49233 7.48128 44.40657 146.87009 326.89898 115.39105 267.83511 183.16000 278.46692 863.51702 154.21342 34.19989 69.26156	Certified that out of Rs. 8933.22994 Lacs received during the years 2020-21 in favour of Ex. Engineer. RWD Bihar, RWD-2 Banka a sum of Rs. 8933.22994 Lacs has been utilized for the purpose of MR/3054(New Maintenance Policy) schemes as given in the margin for which it was sanctioned and a sum of Rs. 37.40528 has been Surrender that the balance of Rs Nil Lacs remaining unutilized at the end of the period under.
		कुल योग—	8970.63522	
		Surrender 70 (Encl)/ 28.12.2021	- 1.07311	
		Surrender 01 (Encl)/ dt. 03.01.2022	- 36.33217	
			8933.22994	
	Total			

2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled/ are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

- Kind of Checks exercised :-
- Works have been supervised by Executive Engineer/ Superintending Engineer
 - Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer
 - Measurement have been recorded in the M/s.
 - All other code formalities have been observed
3. Physical progress achieved.
- Construction of Road Works
 - Construction of CD Works

Sr. D.A.O.
Works Division Banka-II
Rural Works Department

Executive Engineer
Works Division Banka-II
Rural Works Department

of Division :- Banka-2

Sl No.	Package No.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount (in Lac)			Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion (Expected)	Value of IKI (in mm/km)	Thickness of Bitumen layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Allocated Amount (In Lac)	Up to date expenditure as per MIS (in Lac)	Requisition Against work done (in lac)	Remarks
					Length (In Km)	Amount (in Lac)	Initial rectification on with Surface renewal (in lac)	5 Years Routine Maintenance (in lac)											
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	
1	RM/BA/BA N/22/0009	Repair of Road from Bhagalpur Dumka Road To Golhatti Tak under MR/3054	20703502057	1591 31.03.2022	5.268	419.088	332.22884	53.04888	14 MBD/2022-23 30.09.22	29.06.2023	16.12.2022	Attached	75mm	5%	2598.14110	2598.14110	31.84555	Surface Completed	
		Total																31.84555	

Executive Engineer
R.W.D.(W) Division,

Banka-2

Particulars	Details of actual measurement				Contents or area
	No.	L.	B.	D.	
3rd and final Bill					
Name of work: - Construction					
of Road from Bhagalpur					
Dumka Road To Gwalthi					
Agency: - Kundan Kumar Singh					
Rahatola, Anandpur - Road					
Bamla, PS, Dist - Bamla					
Agreement No 14 MTD/2022-23					
Agreement Dated - 08/10/2021					
D/Completion - 29.06.2023					

(1/5) Cons. of granular sub.					
base by providing well					
graded material etc.					
All dimensions are in meter					
8 X	3.800	X 1.200	X 0.075	= 2.74 m ³	
5 X	2.700	X 0.800	X 0.075	= 0.81 "	
6 X	9.500	X 0.640	X 0.075	= 2.74 "	
7 X	7.600	X 0.730	X 0.075	= 2.91 "	
6 X	4.800	X 0.480	X 0.075	= 1.04 "	
4 X	5.700	X 0.930	X 0.075	= 1.59 "	
8 X	6.200	X 0.640	X 0.075	= 2.38 "	
5 X	3.600	X 0.570	X 0.075	= 0.77 "	
6 X	2.700	X 0.775	X 0.075	= 0.94 "	
8 X	8.500	X 0.950	X 0.075	= 4.85 "	

(Continuation)

62

(Continuation)

			Lab Job number :24	
			Date :16-12-2022	
Name of Customer :Kundan Kumar Singh				
Name of Work/ Road :BGP-DUMKA RD - GOLHATTI				
Sr.no	Location of test(in km)	Corrected U.I value(mm/km)		Road category
2	0.1		2753	G
3	0.2		2320	G
4	0.3		2493	G
5	0.4		2753	G
6	0.5		3272	G
7	0.6		2493	G
8	0.7		2406	G
9	0.8		3705	G
10	0.9		3359	G
11	1		2753	G
12	1.1		3359	G
13	1.2		2926	G
14	1.3		3272	G
15	1.4		3272	G
16	1.5		2839	G
17	1.6		2839	G
18	1.7		3532	G
19	1.8		2320	G
20	1.9		3186	G
21	2		2666	G
22	2.1		3012	G
23	2.2		2320	G
24	2.3		2406	G
25	2.4		2666	G
26	2.5		2406	G
27	2.6		2406	G
28	2.7		2839	G
29	2.8		2580	G
30	2.9		2926	G
31	3		1540	G
32	3.1		1973	G
33	3.2		1887	G
34	3.3		1887	G
35	3.4		2147	G
36	3.5		1540	G
37	3.6		2580	G
38	3.7		2753	G
39	3.8		2839	G
40	3.9		2147	G
41	4		2753	G

16/12.22
JE

Na

16/12/22
जयपालक आभयवरा
ग्रामीण कार्य विभाग
कार्य प्रमण्डल बाँका

42	4.1			1887	G
43	4.2			2406	G
44	4.3			3532	G
45	4.4			3012	G
46	4.5			1714	G
47	4.6			3099	G
48	4.7			1973	G
49	4.8			2060	G
50	4.9			1973	G
51	5			2406	G
52	5.1			2060	G
53	5.2			2147	G

BGP-DUMKA RD - GOLHATTI

Date	Time	Section	No.	Length	Bumps	Speed	OR	IRI	Category	Latitude	Longitude	Event	Y = 0 * X + 2 + 0.866 * X + 501.6
16/12/22	15:48:6	24	0.1	260	0	2600	2753	ROAD		24.76339	87.40958	Normal	X = 1900
16/12/22	15:48:6	24	0.1	210	30.3	2100	2320	G		24.76336	87.41952	Normal	Y = 2147
16/12/22	15:48:42	24	0.1	230	30.3	2300	2493	G		24.76346	87.42862	Normal	
16/12/22	15:49:0	24	0.1	260	30.3	2600	2753	G		24.7637	87.43838	Normal	
16/12/22	15:49:18	24	0.1	230	20.2	2300	3272	G		24.76381	87.44813	Normal	RURAL ROAD
16/12/22	15:49:18	24	0.1	220	20.2	2200	2493	G		24.76394	87.45842	Normal	Good
16/12/22	15:49:18	24	0.1	370	30.3	3700	2406	G		24.76404	87.4675	Normal	Average
16/12/22	15:50:0	24	0.1	330	40.4	3300	3359	G		24.76432	87.47727	Normal	4001-5000
16/12/22	15:50:0	24	0.1	260	20.2	2600	2753	G		24.7646	87.48652	Normal	Poor
16/12/22	15:50:0	24	0.1	330	30.3	3300	3359	G		24.76487	87.49645	Normal	
16/12/22	15:50:29	24	0.1	280	40.4	2800	2926	G		24.76514	87.50555	Culvert	
16/12/22	15:50:29	24	0.1	320	40.4	3200	3272	G		24.76539	87.51515	Normal	
16/12/22	15:50:29	24	0.1	320	40.4	3200	3272	G		24.7655	87.52457	Normal	
16/12/22	15:50:29	24	0.1	320	40.4	3200	3272	G		24.76565	87.5348	Normal	
16/12/22	15:50:29	24	0.1	270	40.4	2700	2839	G		24.76593	87.5436	Curve	
16/12/22	15:51:4	24	0.1	270	40.4	2700	2839	G		24.76614	87.55337	Normal	
16/12/22	15:51:4	24	0.1	350	40.4	3500	3532	G		24.76624	87.56397	Culvert	
16/12/22	15:51:4	24	0.1	210	30.3	2100	2320	G		24.76644	87.5734	Normal	
16/12/22	15:51:39	24	0.1	310	30.3	3100	3186	G		24.76684	87.58248	Normal	
16/12/22	15:55:10	24	0.1	250	10.1	2500	2666	G		24.76739	87.59107	Culvert	
16/12/22	15:56:0	24	0.1	290	0	2900	3012	G		24.76755	87.6002	Normal	
16/12/22	15:56:21	24	0.1	210	0	2100	2320	G		24.7673	87.60925	Normal	
16/12/22	15:56:21	24	0.1	220	20.2	2200	2406	G		24.76692	87.6177	Normal	
16/12/22	15:56:21	24	0.1	250	20.2	2500	2666	G		24.76669	87.62793	Normal	
16/12/22	15:56:56	24	0.1	220	30.3	2200	2406	G		24.76652	87.63652	Normal	
16/12/22	15:57:0	24	0.1	220	30.3	2200	2406	G		24.76619	87.64628	Curve	
16/12/22	15:57:0	24	0.1	270	20.2	2700	2839	G		24.76671	87.65387	Normal	
16/12/22	15:57:31	24	0.1	240	20.2	2400	2580	G		24.76671	87.66328	Speed Breaker	
16/12/22	15:57:31	24	0.1	280	30.3	2800	2926	G		24.76609	87.66935	Normal	
16/12/22	15:58:7	24	0.1	120	10.1	1200	1540	G		24.76521	87.67305	Normal	
16/12/22	15:58:7	24	0.1	170	10.1	1700	1973	G		24.76446	87.6781	Normal	
16/12/22	15:58:42	24	0.1	160	30.3	1600	1887	G		24.76408	87.68618	Normal	
16/12/22	15:58:42	24	0.1	160	40.4	1600	1887	G		24.76371	87.69612	Normal	
16/12/22	15:59:0	24	0.1	190	20.2	1900	2147	G		24.76309	87.7037	Culvert	
16/12/22	15:59:17	24	0.1	120	10.1	1200	1540	G		24.76238	87.70908	Normal	
16/12/22	15:59:52	24	0.1	240	10.1	2400	2580	G		24.76168	87.71532	Bridge	

16/12/22	16:0:0	24	0.1	260	20.2	2600	2753	G		24.7611	87.72238	Bridge					
16/12/22	16:0:0	24	0.1	270	20.2	2700	2839	G		24.76043	87.7303	Normal					
16/12/22	16:0:28	24	0.1	190	20.2	1900	2147	G		24.75968	87.73097	Curve					
16/12/22	16:0:28	24	0.1	260	30.3	2600	2753	G		24.75887	87.7342	Curve					
16/12/22	16:0:28	24	0.1	160	40.4	1600	1887	G		24.75798	87.73753	Normal					
16/12/22	16:1:3	24	0.1	220	30.3	2200	2406	G		24.75716	87.7414	Curve					
16/12/22	16:1:3	24	0.1	350	10.1	3500	3532	G		24.75676	87.7502	Normal					
16/12/22	16:1:38	24	0.1	290	10.1	2900	3012	G		24.75627	87.75858	Normal					
16/12/22	16:2:14	24	0.1	140	10.1	1400	1714	G		24.75569	87.76655	Normal					
16/12/22	16:2:14	24	0.1	300	20.2	3000	3099	G		24.75513	87.77423	Normal					
16/12/22	16:2:49	24	0.1	170	10.1	1700	1973	G		24.7543	87.7771	Normal					
16/12/22	16:3:0	24	0.1	180	30.3	1800	2060	G		24.75344	87.7771	Normal					
16/12/22	16:3:0	24	0.1	170	30.3	1700	1973	G		24.75253	87.77423	Normal					
16/12/22	16:3:0	24	0.1	220	30.3	2200	2406	G		24.75188	87.77845	Normal					
16/12/22	16:3:24	24	0.1	180	40.4	1800	2060	G		24.75104	87.7843	Curve					
16/12/22	16:3:24	24	0.1	190	40.4	1900	2147	G		24.75065	87.79275	Normal					
16/12/22	16:3:24	24	0.1														
Average IRI Value=258.5																	

16.12.22
SE

16.12.22
A.M.

16.12.22
जायपालक शिवाजी
ग्रामीण कार्य विभाग
कार्य प्रमोडल, वॉकर


Name of Customer :	Kundan Kumar Singh
Name of Work/ Road :	SECTOR 20, PHASE 2 RD - GULSHAN 111
Lab Job number:	24
Date :	16-12-2007
Section No.	24

Test Date:	11-12-2022
Machine No:	407
Start S No:	
Start E No:	
Weather:	
Start Location:	
End Location:	
Road Name:	BGP-GOURKARN-D-GOUHATI
Road Type:	(R) RURAL ROAD
Side:	
UNY Range:	540 To 5000
Dist Range:	0 To 53
Equation:	$Y = 0.0 \cdot X^2 + 2.0 \cdot 0366 \cdot X + 5016$
	Interval 1000 mm/km • 1000 m

Print

Generate Report and Graph

Redraw Graph



File E:\Kundan singh bump guihou\BGP-OUUKA.RD - GOUUATM.xls, Section No. 24, Eqn : $Y = 0 \cdot X^{-2} \cdot 0.866$ -
Name of Customer :Kundan Kumar Singh, Name of Work/ Road :BGP-OUUKA.RD - GOUUATM Lab Job number :24

Richardson, O. J. 1968 -

१६.१२.२२
श्री
जार्जपालक आश्रयता
गामिण कार्या विभाग
कार्य प्रणयल, दोका

**Office of the Executive Engineer
Rural Works Department, Works Division : Banka-2**


Name of Road :- Bhagalpur Dumka Road To Golhatti Tak
Name of Scheme :- 3054/MR (New maintenance Policy 2018)
Name of contractor/Agency:- Kundan Kumar Singh
Length of Road :- 5.268 km
Project ID :- 20703502057
Package No. :- RM/BA/BAN/22/0009
Name of Block :- Bounsi


Certified that all item
wise 100% Measurement
has been taken by me

Certified that all item
wise 50% Measurement
has been taken by me

Certified that all item
wise 10% Measurement
has been taken by me


16/12/22
Junior Engineer RWD
Work section Bounsi
Works Division : Banka-2


16.12.22
Assitant Engineer RWD
Work Sub Division Bounsi
Works Division : Banka-2


16.12.22
Executive Engineer,
Rural Works Department,
Works Division : Banka-2