

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, सासाराम-1

Email ID:-ee.rwd.sasaram1@gmail.com Mob:- 8986915310

पत्रांक...1185 अगुठ सासाराम / दिनांक 22/06/23

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, सासाराम-1

सेवामें,

नोडल पदाधिकारी (MR 3054)
ग्रामीणकार्यविभाग
पटना, बिहार

विषय :- नई अनुस्क्षण नीति-2018MR (3054) योजना के अंतर्गत पथ में कराये गये कार्य के विरुद्ध आवंटन उपलब्ध कराने के संबंध में।

महाशय,

उपरोक्त विषय के संबंध में सूचित करना है कि नई अनुस्क्षण नीति-2018 MR (3054) योजना के अंतर्गत पथ में कराये गये कार्य के लिए संवेदक को भुगतान करने हेतु अधियाचना विहित प्रपत्र में भरकर आवश्यक कार्यवाही हेतु समर्पित की जाती है।

अनु0 :- यथोक्त।

विष्वासभाजन

AKumal
22.06.23
कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, सासाराम-1

FORM GFR 19-A

(See Government of India's Decision (I) below Rule-150)

Form of Utilization Certificate up to June 2023

Sl.No	Name of Scheme	Sanction No.&Date With Amount (In lace Rs.)	Amount Received (In lace Rs.)	Particulars
1	Construction of Rural roads Under MR	New Maintenance Policy-2018 MR (3054) BRRDA PATNA	11827.93642	Certified that out of Rs. 11827.93642 lakh of grants-in-aid sanctioned during the years 2021-23 Infavor of EE,RWD works division Sasaram-1a sum of Rs 11754.26382 lakh has been utilized for the purpose of MR (3054) Schemes as given in the margin for which it was sanctioned and that the balance of Rs. 73.67260 lakh remaining unutilized at the end of the period under report.
	Total:		11827.93642	

2. Certified that I have satisfied my self that the conditions on which the grant-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was utilized for the purpose for which it was sanctioned.

Kind of Checks exercised:-

- Works have been supervised by Executive Engineer/ Superintending Engineer.
- Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- Construction materials have been tested.
- Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/ Executive Engineer.
- All other caudal formalities have been observed.

3. Physical Progress achieved:-

- Construction of Road Works.
- Construction of CD works.



Divisional Accounts Officer
R.W.D, works Division
Sasaram-1

AKUMAR
22.06.23

Executive Engineer

R.W.D, works Division
Sasaram-1

OFFICE OF EXECUTIVE ENGINEER, RURAL WORKS DEPARTMENT, WORKS DIVISION, SASARAM-1
Registration Format for Scheme Head - MR(3054) under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

SI no.		Batch No	Name of Road		Project ID as per MIS		Administrative Approval (AA) Letter No & Date		Length (in km)	Amount of Rectification with Initial 5 Year Routine Maintenance (in Lakh)	Agreement Amount (in Lakh)	Agreement Completion Date as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Allocated Amount (in Lakh)	up-to-date expenditure as per MIS (in Lakh)	Requisition done against work (in Lakh)	Remarks
1	3/0002 /SAS/2	RM/RO L100-L098 TO BHAGWANPUR (OPR71)	10301002300	1412	08.09.2022	2.3	102.281	60.00073	21.6186	01/03/2022-20MBD/23 & 30/11/2023	0	3149	25.00	5.00	-	-	57.20000	57.20000		
Total																				

Divisional Accounts Officer
 Rural Works Department,
 Works Division, Sasaram-1

Executive Engineer
 Rural Works Department
 Works Division, Sasaram-1
 22.06.23

Name of Road:- L098 To Bhagwanpur (ODR71)

Date	Time	Section	Length	Bumps	Speed	OR	IRI	CATEGORY	Latitude	Longitude	Event
22/6/23	7:37:17	39	0.1	300	10.1	3000	2915	G	25.6912	83.994175	Normal
22/6/23	7:37:35	39	0.1	280	20.2	2800	3215	G	25.69173	83.99512	Normal
22/6/23	7:37:52	39	0.1	290	20.2	2900	3315	G	25.69075	83.99611	Curve
22/6/23	7:38:0	39	0.1	300	20.2	3000	2815	G	25.6913	83.996902	Normal
22/6/23	7:38:27	39	0.1	240	20.2	2400	3415	G	25.69453	83.997608	Curve
22/6/23	7:38:39	39	0.1	280	10.1	2800	3215	G	25.70325	83.997727	Normal
22/6/23	7:39:2	39	0.1	260	10.1	2600	3415	G	25.71242	83.997912	Culvert
22/6/23	7:40:0	39	0.1	250	10.1	2500	2915	G	25.7212	83.997928	Normal
22/6/23	7:40:13	39	0.1	270	10.1	2700	3115	G	25.73005	83.998097	Normal
22/6/23	7:41:0	39	0.1	300	10.1	3000	3015	G	25.7382	83.99843	Normal
22/6/23	7:41:24	39	0.1	250	10.1	2500	3415	G	25.7441	83.999292	Speed Breaker
22/6/23	7:42:0	39	0.1	290	10.1	2900	3315	G	25.7424	84.218	Normal
22/6/23	7:42:13	39	0.1	240	10.1	2400	2815	G	25.73962	84.1093	Normal
22/6/23	7:42:34	39	0.1	240	20.2	2400	2815	G	25.73612	84.1985	Normal
22/6/23	7:43:0	39	0.1	260	20.2	2600	3015	G	25.7345	84.2928	Normal
22/6/23	7:43:9	39	0.1	300	20.2	3000	3415	G	25.7362	84.3905	Culvert
22/6/23	7:43:17	39	0.1	280	30.3	2800	3215	G	25.73638	84.4865	Normal
22/6/23	7:43:33	39	0.1	260	30.3	2600	3015	G	25.73735	84.5908	Normal
22/6/23	7:43:45	39	0.1	290	20.2	2900	3315	G	25.73843	84.6868	Normal
22/6/23	7:44:0	39	0.1	250	20.2	2500	2915	G	25.73792	84.781	Curve
22/6/23	7:44:12	39	0.1	290	30.3	2900	3315	G	25.7398	84.8753	Normal
22/6/23	7:44:24	39	0.1	300	10.1	3000	3415	G	25.7441	83.999292	Culvert
22/6/23	7:45:0	39	0.1	270	10.1	2700	3115	G	25.7424	84.218	Normal

$$Y = 0 * X^2 + 1.000 * X + 415.2$$

$$X = 2700$$

$$Y = 3115$$

(R) RURAL ROAD

Good Average Poor

<4000 4001-5000 >5001

Executive Engineer
Rural Work's Department
Work Division, Sasaram-1
22.06.23

22/06/23
JE

Name of Customer : Anil Kumar Singh

Name of Work : L098 To Bhagwanpur (ODR71)

Road : 39

Lab Job number : 39

Date : 22-06-2023

Section No. : 39

Test Date : 22-06-2023

Road Name : L098 To Bhagwanpur (ODR71)

Machine No : 391

Start S No : 03

Start E No : 25

Side : Kargaher

Interval : 1000

UIV Range : 1815 To 4000

Weather : Normal

Start Location : 912.83.994175

Dist Range : 0 To 2.4

Equation : $Y = 0.0 \times X^2 + 1.000 \times X + 415.2$

Print


Generate Report and Graph

Redraw Graph

Map View

File : F:\Bomp Machine report\Mar 2023 New MR road\Anil Kumar singh New MR\22-06-2023 an.Xls. Section No. 39

Name of Customer : Anil Kumar Singh, Name of Work / Road : L098 To Bhagwanpur (ODR71), Lab Job number : 39



22.06.23

R. K. Singh