

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, सासाराम-1

Email ID:-ee.rwd.sasaram1@gmail.com Mob:- 8986915310

पत्रांक.....1197 ज्युलै सासाराम / दिनांक 24/06/23

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, सासाराम-1

सेवामें,

नोडल पदाधिकारी (MR 3054)
ग्रामीणकार्यविभाग
पटना, बिहार

विषय :- नई अनुस्मरण नीति-2018MR (3054) योजना के अंतर्गत पथ में कराये गये कार्य के विरुद्ध आवंटन उपलब्ध कराने के संबंध में।

महाशय,

उपरोक्त विषय के संबंध में सूचित करना है कि नई अनुस्मरण नीति-2018 MR (3054) योजना के अंतर्गत पथ में कराये गये कार्य के लिए संवेदक को भुगतान करने हेतु अधियाचना विहित प्रपत्र में भरकर आवश्यक कार्यवाही हेतु समर्पित की जाती है।

अनु0 :- यथोक्त।

विष्वासभाजन

24.06.23

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, सासाराम-1
24/06/23

FORM GFR 19-A

(See Government of India's Decision (I) below Rule-150)

Form of Utilization Certificate up to June 2023

Sl.No	Name of Scheme	Sanction No.&Date With Amount (In lace Rs.)	Amount Received (In lace Rs.)	Particulars
-1	Construction of Rural roads Under MR	New Maintenance Policy-2018 MR (3054) BRRDA PATNA	11827.93642	Certified that out of Rs. 11827.93642 lakh of grants-in-aid sanctioned during the years 2021-23 in favor of EE, RWD works division Sasaram-1 a sum of Rs 11754.26382 lakh has been utilized for the purpose of MR (3054) Schemes as given in the margin for which it was sanctioned and that the balance of Rs. 73.67260 lakh remaining unutilized at the end of the period under report.
	Total:		11827.93642	

2. Certified that I have satisfied my self that the conditions on which the grant-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was utilized for the purpose for which it was sanctioned.

Kind of Checks exercised:-

- Works have been supervised by Executive Engineer/ Superintending Engineer.
- Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- Construction materials have been tested.
- Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/ Executive Engineer.
- All other caudal formalities have been observed.

3. Physical Progress achieved:-

- Construction of Road Works.
- Construction of CD works.



Divisional Accounts Officer
R.W.D, works Division
Sasaram-1

24.06.23

Executive Engineer

R.W.D, works Division
Sasaram-1

24/06/23

OFFICE OF EXECUTIVE ENGINEER, RURAL WORKS DEPARTMENT, SASARAM-1

Registition Format for Scheme Head- MR(3054) under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

Name of Works Division:- Sasaram-1

Sl no.	Batch No	Name of Road	Project ID as per M15	Administrative Approval (AA) Letter No & Date	Length (in km)	Amount of Rectification with Initial Surface Renewal (in Lakh)	5 Year Routine Maintenance (in Lakh)	Agreement Amount (in Lakh)	Date of Completion as per Agreement	Actual Date of Completion	Value of Bitumen Layer (in mm)	Thickness of Bitumen Content in Percentage	Previous Total Allocated Amount (in Lakh)	up-to-date expenditure as per M15 (in Lakh)	Requisition done against work (in Lakh)	Remarks		
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	AS/RO/S 007	Adanganj more se chahiya hote huye hajarat kamden shahid per shahab dargah tak	13101035108	611 15.07.2022	1.00	48.693	31.565	4.91589	21MBD/ 23 & 09/02/2023	8/11/2023	0	3190	25.00	5.00	0.00000	0.00000	25.25200	
Total																		
					1.00	48.693	31.565	4.91589										
48.693																		
31.565																		
4.91589																		

Divisional Accounts Officer
Rural Works Department,
Sasaram-1

Executive Engineer
Rural Works Department
Sasaram-1
24.06.23
84/06/23

Name of Road:- Alamganj Mod To Chalaniya Hote Hue Hajrat Chandan Shahid Pir Sahab Dargah Tak

Date	Time	Section	Length	Bumps	Speed	OR	IRI	CATEGORY	Latitude	Longitude	Event
		No.	in km	in mm	Rate	mm/km	mm/km	ROAD			
22/6/23	8:54:29	40	0.1	290	10.1	3000	3315	G	24.944615	84.23737	Normal
22/6/23	8:55:0	40	0.1	300	10.1	3000	3415	G	24.944472	84.2478	Speed Breaker
22/6/23	8:55:42	40	0.1	300	10.1	3000	3315	G	24.9443	84.25655	Normal
22/6/23	8:55:42	40	0.1	300	10.1	2800	3215	G	24.944182	84.26648	Normal
22/6/23	8:56:0	40	0.1	280	10.1	2900	3315	G	24.943973	84.27608	Normal
22/6/23	8:56:17	40	0.1	290	10.1	2900	3315	G	24.943785	84.28552	Normal
22/6/23	8:56:41	40	0.1	290	20.2	2900	2815	G	24.943503	84.29545	Normal
22/6/23	8:57:0	40	0.1	240	20.2	2400	3415	G	24.943225	84.30437	Speed Breaker
22/6/23	8:57:28	40	0.1	300	10.1	3000	3315	G	24.942875	84.31245	Normal
22/6/23	8:58:3	40	0.1	300	10.1	3000	3315	G	24.9425	84.32188	Normal
22/6/23	8:58:38	40	0.1	210	10.1	2100	2515	G	24.94218	84.33113	Normal
22/6/23	8:59:14	40	0.1	260	10.1	2600	3015	G	24.942028	84.3404	Normal
22/6/23	9:0:0	40	0.1	290	10.1	2900	3315	G	24.942028	84.3404	Normal
Average IRI											
3190											

$Y = 0 * X^2 + 1.000 * X + 415.2$
 $X = 2900$
 $Y = 3315$
 (R) RURAL ROAD
 Good Average Poor
 <4000 4001-5000 >5001

Executive Engineer
 Rural Work's Department
 Work Division, Sasaram-1
 22.06.23

22/06/23
 AC

22/06/2023
 J.E/Sasaram

Name of Customer : BHIM SINGH

Name of Work/ in Shaid Fir Sahab Dargah tak

Road : 40

Lab Job number : 40

Date : 22-05-2023

Section No. : 40

Print

Generate Report and Graph

Test Date : 22-05-2023

Machine No : 391

Start S No : 03

Start E No : 14

Weather : Normal

U/V Range : 1515 To 4000 mm/km

Dist Range : 0 To 1.3

Equation : $Y = 0 \cdot X^2 + 1.000 \cdot X + 415.2$

Road Name : in Shaid Fir Sahab Dargah tak

Road Type : (R) RURAL ROAD

Side : Sasarem


Interval

Redraw Graph

Map View

File : F:\Bomp Machine report\Mar 2023 New MR road\Bhim Singh\22-05-2023 bh.Xls. Section No. : 40. Eqn : $Y = 0$

Name of Customer : BHIM SINGH, Name of Work/ Road : Alamganj Mod To Chalanja Hote Hue Hajrat Chanden



22.06.23
EE

22/06/23
AC

22/06/23
24/8/2023