

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, सिवान-2

पत्रांक...../592 अनु०..... सिवान, दिनांक 27/06/2023

प्रेषक,
कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, सिवान-2

सेवा में,
सचिव-सह-प्राधिकृत पदाधिकारी
बिहार ग्रामीण पथ विकास एजेन्सी
भूमि विकास बैंक भवन
बुद्ध मार्ग, पटना।

विषय:- योजना शीर्ष नई अनुरक्षण निति 2018 MR/3054 अन्तर्गत पथों में मरम्मत हेतु
अधियाचना के संबंध में।

महाशय,
उपर्युक्त विषयक प्रासंगिक पत्र के आलोक में कहना है कि योजना शीर्ष नई अनुरक्षण
निति 2018 MR/3054 अन्तर्गत संलग्न विहित प्रपत्र में 53.00489 लाख (तिरेपन लाख चार सौ
नवासी) रुपये मात्र आवंटन देने की कृपा की जाय।

अनु०-अधियाचना पत्र, Bump Integrator Equipment Report की छाया प्रति,
एकरारनामा की छाया प्रति,

विश्वासभाजन



कार्यपालक अभियंता

ग्रामीण कार्य विभाग,

कार्य प्रमंडल, सिवान-2

27/6/23

Requisition Format for Scheme Head - MR (3054) Under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

Name of Works Division :- RWD, WORKS DIVISION, SIWAN-2

S.N.	Package No.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount (in Lakh)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Allowed Amount (in Lakh)	Up-to-date expenditure as per MIS (in Lakh)	Requisition against work done (in Lakh)	Remarks
					Length (in Km)	Amount (in Lakh)	Initial Rectification with Surface Renewal (in Lakh)	5 Year Routine Maintenance (in Lakh)										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	MR-N/22-23siwan-203	L055-T02 to Rasidchak	31406702067	1999.02.05.2022	1.500	84.07	53.06489	13.88935	17 MBD of 2022-23/17.01.2023	25.09.23	19.06.2023	Good	25mm	5.032	0.00	0.00	53.00489	Complete
Total															0.00	0.00	53.00489	

प्रमाणित किया जाता है कि पृष्ठ में कराये गये कार्य के सभी अवयववार 100 प्रतिशत कार्य का दर्ज मापी का सत्यापन संबंधित कर्मीय अभियंता 50 प्रतिशत मापी का सत्यापन संबंधित सहायक अभियंता एवं 10 प्रतिशत मापी का सत्यापन अद्योहस्ताक्षरी यथा कार्यपालक अभियंता द्वारा किया जा चुका है। कसया गया कार्य मानक एवं विशिष्टियों के अनुरूप है।

कमीय अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, सिवान-2

सहायक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, सिवान-2

प्रमुखस्थायी सहायक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, सिवान-2

कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, सिवान-2

FORM GFR 19-A
(See Government of India's Decision (I) below Rule-150)
Form of Utilisation Certificate up to 26th June 2023
NEW MAINTENANCE POLICY (2018)

Sl.No	Name of Scheme	Sanction No.& Date with Amount, (in Rs. Lacs)	Amount Received (in Rs. Lacs)	Particulars
1	Construction of Rural roads under NEW MAINTENANCE POLICY (2018)	24/19.03.2020 59/18.08.2020 78/29.10.2020 82/13.11.2020 86/11.12.2020 05/12.01.2021 17/26.02.2021 20/19.03.2021 26/15.04.2021 52/24.08.2021 58/27.10.2021 60/09.11.2021 64/06.12.2021 68/23.12.2021 02/03.01.2022 05/25.01.2022 10/21.02.2022 18/11.03.2022 49/27.04.2022 01/20.05.2022 22/08.08.2022 35/13.10.2022 32/03.03.2023 42/20.03.2023 63/13.04.2023 67/24.04.2023 72/10.05.2023 81/31.05.2023	309.44834 40.85500 127.93990 129.95438 140.17554 246.86987 257.50061 46.15519 70.50399 58.39236 177.05420 87.58854 1.27421 167.06400 614.19943 279.43486 11.26696 726.24067 29.31956 62.42914 272.11117 168.58187 604.61409 1.38703 491.70500 105.00000 185.55188 97.83590	Certified that out of Rs 5868.11277 lacs received during the years 2022-23 in favour of Ex. Engineer, RWD, Works Division, siwan-2 Bihar, a sum of Rs 5749.25765 Lacs has been utilized for the purpose of NEW MAINTENANCE POILCY-2018 Schemes as given in the margin for which it was sanctioned and that the balance of Rs 118.85512 lacs remaining unutilized at the end of the period under.
	Total :		5868.11277	


2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercised :-

- Works have been supervised by Executive Engineer/Superintending Engineer.
- Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- Construction materials have been tested.
- Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/ Executive Engineer.
- All other codal formalities have been observed.

3. **Physical Progress achieved :-**

- Construction of Road works.
- Construction of CD works.


 DIVISIONAL ACCOUNT OFFICER
 RURAL WORKS DEPARTMENT
 WORKS DIVISION, SIWAN-2


 EXECUTIVE ENGINEER
 RURAL WORKS DEPARTMENT
 WORKS DIVISION, SIWAN-2
 24/6/2023

3500

Name of Customer: Genius Construction, Machine no: 19208, Road: LOS5-T02 to rasidchak, Date: 23-06-23, Section No: 144, Equation: $Y=0.904X+252.3$

UIV mm/km
2100

700
0

Distance*1000 m

0.1 0.2 0.3 0.4 0.5 0.6 0.7 0.8 0.9 1 1.1 1.2 1.3 1.4 1.5

[Signature]
23/06/23
JB

[Signature]
23/06/23
AE

[Signature]
EXECUTIVE ENGINEER
RURAL WORKS DEPT
WORKS DIVISION SIWAN-2

Name of work : L055-102 to insidchak	
Name of customer : Genius Construction	
(R)Rural Road	
Good	Average
< 4000	4001 - 5000
	> 5000
Poor	

Date	Time	Test No	Distance(m)	Total Distance(m)	BUM(%)	Speed(Km/Hr)	U(%)	Corrected U(%)	IRI	Status	Latitude	Direction	Longitude	Direction1	Remarks
23/06/23	09:12:48	144	100	100	21.0 cm	6.9 Km/Hr	2100.0 mm/Km	2151	2.99	Good	26.1319761	N	84.2605295	E	Normal
23/06/23	09:13:10	144	100	200	13.0 cm	16.6 Km/Hr	1300.0 mm/Km	1428	2.08	Good	26.1319761	N	84.2605295	E	Normal
23/06/23	09:13:30	144	100	300	8.0 cm	17.6 Km/Hr	800.0 mm/Km	976	1.48	Good	26.1319761	N	84.2605295	E	Normal
23/06/23	09:13:51	144	100	400	13.0 cm	17.0 Km/Hr	1300.0 mm/Km	1428	2.08	Good	26.1319761	N	84.2605295	E	Normal
23/06/23	09:14:13	144	100	500	17.0 cm	16.6 Km/Hr	1700.0 mm/Km	1789	2.54	Good	26.2023363	N	84.3432779	E	Normal
23/06/23	09:14:37	144	100	600	10.0 cm	15.0 Km/Hr	1000.0 mm/Km	1156	1.72	Good	26.2024012	N	84.3429880	E	Normal
23/06/23	09:15:10	144	100	700	14.0 cm	7.0 Km/Hr	1400.0 mm/Km	1518	2.19	Good	26.2028671	N	84.3401950	E	Normal
23/06/23	09:15:41	144	100	800	19.0 cm	14.2 Km/Hr	1900.0 mm/Km	1970	2.77	Good	26.2030090	N	84.3391081	E	Normal
23/06/23	09:16:15	144	100	900	18.0 cm	13.9 Km/Hr	1800.0 mm/Km	1880	2.65	Good	26.2031280	N	84.3383820	E	Normal
23/06/23	09:16:45	144	100	1000	13.0 cm	16.5 Km/Hr	1300.0 mm/Km	1428	2.08	Good	26.2028521	N	84.3375451	E	Normal
23/06/23	09:17:15	144	100	1100	14.0 cm	16.5 Km/Hr	1400.0 mm/Km	1518	2.19	Good	26.2021280	N	84.3370342	E	Normal
23/06/23	09:17:40	144	100	1200	27.0 cm	18.3 Km/Hr	2700.0 mm/Km	2693	3.66	Good	26.2012141	N	84.3365890	E	Normal
23/06/23	09:18:14	144	100	1300	14.0 cm	20.6 Km/Hr	1400.0 mm/Km	1518	2.19	Good	26.2004520	N	84.3364091	E	Normal
23/06/23	09:18:52	144	100	1400	19.0 cm	20.7 Km/Hr	1900.0 mm/Km	1970	2.77	Good	26.2004600	N	84.3356093	E	Normal
23/06/23	09:19:16	144	100	1500	17.0 cm	21.6 Km/Hr	1700.0 mm/Km	1789	2.54	Good	26.2031280	N	84.3383820	E	Normal

23/06/2023

23/06/2023

EXECUTIVE ENGINEER
RURAL WORKS DEPARTMENT
WORKS DIVISION SIWAN-2