

कार्यपालक अभियंता का कार्यालय,
ग्रामीण कार्य विभाग, कार्य प्रमण्डल मधेपुरा।

पत्रांक:- 1193 (अनु०)

/ मधेपुरा दिनांक:- 17/6/2023

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, मधेपुरा।

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी,
बिहार ग्रामीण पथ विकास अभिकरण,
बिहार, पटना।

विशय:- 3054 बिहार ग्रामीण पथ नई अनुरक्षण नीति 2018 के योजना अन्तर्गत में
अधियाचित राशि का आवंटन उपलब्ध कराने के संबंध में।




महाशय,

उपरोक्त विशयक प्रासंगिक पत्र के अनुपालन में 3054 बिहार ग्रामीण पथ नई
अनुरक्षण नीति 2018 के योजना अन्तर्गत राशि की माँग संलग्न विहित प्रपत्र में पथवार की
गई है।

अतः भवदीय से अनुरोध है कि विहित प्रपत्र के कॉलम-18 में अंकित कुल राशि का
आवंटन उपलब्ध कराने की कृपा की जाय। अधियाचित राशि के संदर्भ में Bump
Integrator Report की छाया प्रति संलग्न कर समर्पित किया जा रहा है।

अनु० यथोक्त।

विश्वासभाजन


17.6.23
कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, मधेपुरा।

17/06/23

17/6/23

Format for Scheme Head - MR (3054) Under Bihar Rural Road maintenance Policy 2018 (Initial Rectification and Surface Renewal)

Division : - Madhepura

SL No	Package no.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount (in Lac)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in percentage	Previous Total Allotted Amount (in Lac)	Up to date expenditure as per MIS (in Lac)	Requisition Against work done (in Lac)	Remarks
					Length (In Km)	Amount (in Lac)	Initial Rectification with Surface Renewal (in lac)	5 years Routine Maintenance (in lac)										
1	RM/MA/MAD/22/0006	Kumarkhand Jorawarganj Road Anandpatil To Mirren	21004713010	1192	3.325	170.59	138.05382	37.32425	52 MBD/2022-23/19.12.2022	15.09.2023	15.06.2023	2916.00	25mm	5%	0.00	0.00	138.00000	Complete
2	RM/MA/MAD/22/0005	Singheshwar - Latha	NEA220001691	2011/02.05.2022	3.160	278.69	238.27992	34.8287	31/MBD/2022-23/08.08.2022	07.05.2023	14.06.2023	2981.00	25mm	5%	0.00	0.00	238.00000	Complete

[Signature]
D.A.O.
12/06/23

RWD Works Division
Madhepura

[Signature]
Executive Engineer
RWD Works Division
Madhepura
17/6/23

Form GFR 19- A
(See Government of India's Decision (I) below Rule - 150)
Form of Utilization Certificate upto the month of 17 June 2023
New Maintenance Policy 2018

Sl. No.	Name of Scheme	Sanction No. & Date with Amount (in lacs)	Amount Received (in lacs)	Particulars
1	New Maintenance Policy 2018	Sec Cum Empowered Officer BRRDA Patna Bihar vide Letter No:-35 Dated 14.03.2023	5556.32135	Certified that out of 5556.32135 lacs of grants in aid sanctioned during the Years up to 2022-23 in favour of Executive Engineer, RWD Works Division Madhepura under this Department, a sum of Rs 5387.29995 lacs has been utilized for the purpose of New_MR Scheme remaining 169.02140 unutilized at the end of the period under report.
		Total :	5556.32135	

Certified and verified myself that the conditions on which the grants in aid was sanctioned have been duly fulfilled / are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kinds of Checks exercised :-

- i Works have been supervised by Executive Engineer/ Superintending Engineer.
- ii Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- iii Construction material have been tested.
- iv Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/Executive Engineer.
- v All other codal formalities have been observed.


Physical Progress achieved :-

- i Construction of Road works.
- ii Construction of CD works

[Signature]
D.A.O. 17/6/23
RWD works Division
Madhepura

[Signature]
17.6.23
Executive Engineer
RWD works Division
Madhepura
[Signature]
17/6/23

File : D:\Madhepura\Bump Report\Kumarkhand Jorawarganj Road Anandpatti To Miren\02091621.xls, Section No.
 Name of Customer : Diwakar Kumar, Name of Work/ Road : Kumarkhand Jorawarganj Road Anandpatti To Miren.



15106123
 17.6.13

15106123
 17.6.13

15106123
 17.6.13

Name Of Road :- Kumarkhand Jorawarganj Road Anandpatti To Miren

$$Y = 0 \cdot X^2 + 0.862 \cdot X + 448.5$$

$$X = 3500$$

$$Y = 3465$$

(R) RURAL ROAD

Good Average Poor
4000 4001-5000 >5001

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	CATEGORY ROAD	IRI	Latitude	Longitude	Event
15/6/23	14:11:28	50	0.1	270	30.3	2700	G	2775	26.00054	87.01531	Normal
15/6/23	14:11:28	50	0.1	380	20.2	3800	G	3724	25.99958	87.01588	Normal
15/6/23	14:12:3	50	0.1	300	20.2	3000	G	3034	25.99941	87.01607	Culvert
15/6/23	14:12:3	50	0.1	360	10.1	3600	G	3551	25.99809	87.01744	Normal
15/6/23	14:12:38	50	0.1	310	20.2	3100	G	3120	25.99647	87.01904	Normal
15/6/23	14:12:38	50	0.1	360	20.2	3600	G	3551	25.99646	87.01904	Normal
15/6/23	14:13:13	50	0.1	310	20.2	3100	G	3120	25.99588	87.01986	Normal
15/6/23	14:13:13	50	0.1	230	20.2	2300	G	2431	25.99477	87.02062	Normal
15/6/23	14:13:13	50	0.1	320	20.2	3200	G	3206	25.99476	87.02085	Normal
15/6/23	14:13:49	50	0.1	230	20.2	2300	G	2431	25.99482	87.02094	Normal
15/6/23	14:13:49	50	0.1	360	20.2	3600	G	3551	25.99483	87.02128	Curve
15/6/23	14:14:24	50	0.1	190	20.2	1900	G	2086	25.99374	87.02224	Culvert
15/6/23	14:14:24	50	0.1	180	30.3	1800	G	2000	25.99387	87.0231	Normal
15/6/23	14:14:24	50	0.1	180	30.3	2000	G	2172	25.99377	87.02409	Culvert
15/6/23	14:14:59	50	0.1	180	20.2	2300	G	2431	25.99401	87.02558	Normal
15/6/23	14:14:59	50	0.1	180	20.2	3300	G	3293	25.99427	87.02742	Normal
15/6/23	14:15:35	50	0.1	180	20.2	3200	G	3206	25.99452	87.02846	Normal
15/6/23	14:15:35	50	0.1	180	20.2	3000	G	3034	25.99452	87.03001	Culvert
15/6/23	14:15:35	50	0.1	180	20.2	2400	G	2517	25.99456	87.03112	Culvert
15/6/23	14:16:10	50	0.1	180	30.3	2200	G	2344	25.99459	87.03127	Culvert
15/6/23	14:16:10	50	0.1	180	20.2	2700	G	2775	25.99459	87.03127	Curve
15/6/23	14:16:45	50	0.1	180	10.1	3000	G	3034	25.99459	87.03127	Normal
15/6/23	14:16:45	50	0.1	180	10.1	3300	G	3293	25.99459	87.03127	Curve
15/6/23	14:16:45	50	0.1	180	20.2	2800	G	2862	25.99459	87.02127	Normal
15/6/23	14:17:20	50	0.1	180	20.2	2500	G	2603	25.99459	87.02127	Normal
15/6/23	14:17:56	50	0.1	180	10.1	3000	G	3034	25.99459	87.02127	Normal
15/6/23	14:17:56	50	0.1	180	20.2	2600	G	2689	25.99463	87.0312	Curve
15/6/23	14:18:0	50	0.1	180	20.2	2600	G	2689	25.99452	87.0312	curve
15/6/23	14:18:6	50	0.1	180	10.1	3800	G	3724	25.99548	87.03288	Curve
15/6/23	14:18:41	50	0.1	180	10.1	3100	G	3120	25.99548	87.03288	Normal
15/6/23	14:18:41	50	0.1	180	10.1	3700	G	3637	25.99582	87.03374	Normal
15/6/23	14:19:16	50	0.1	180	30.3	2800	G	2862	25.99603	87.03454	Normal
15/6/23	14:19:16	50	0.1	180	30.3	2200	G	2344	25.99601	87.03528	Normal
15/6/23	14:19:52	50	0.1	180	30.3						
Average IRI								2916			

15/6/23
S. K. K. 15/6/23

15/6/23
S. K. K. 15/6/23

15/6/23