



कार्यपालक अभियन्ता का कार्यालय
ग्रामीण कार्य विभाग , कार्य प्रमण्डल राजगीर (नालन्दा)

Email:- rwdrajgir@gmail.com, ee.rajgir@rwdbihar.in

पत्रांक....222

राजगीर

दिनांक...10/03/2023

प्रेषक,

कार्यपालक अभियन्ता
ग्रामीण कार्य विभाग
कार्य प्रमण्डल राजगीर।

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव,
ग्रामीण कार्य विभाग,
पटना।

विषय:- नई अनुरक्षण नीति 2018 शीर्ष MR-3054 योजना मद अन्तर्गत व्यय हेतु आवंटन की माँग के
संबंध में।

महाशय,

उपर्युक्त विषयक नई अनुरक्षण नीति 2018 शीर्ष MR-3054 योजना मद अन्तर्गत व्यय हेतु विहित
प्रपत्र में अधियाचना पत्र संलग्न कर भेजी जा रही है।

अतः अनुरोध है कि संलग्न विवरणी के अनुसार आवंटन उपलब्ध कराने की कृपा की जाय। ताकि
कराये गये कार्यों का भुगतान किया जा सके। संबंधित संवेदक का इस प्रमण्डल में कोई ATR लम्बित नहीं
है।

अनु०:- यथोक्त।

विश्वासभाजन

10/3/2023

कार्यपालक अभियन्ता
ग्रामीण कार्य विभाग
कार्य प्रमण्डल राजगीर

10/3/23

FORM GFR 19-A

(See Government of India's Decision(I) below Rule-150)

Utilisation Certificate upto the month of Feb- 2023

STATE – BIHAR

MR(3054) New Maintaince Policy 2018

Sl. No.	Name of Scheme	Sanction No. & Date with Amount (In Rs. Lacs)	Amount Received (In Lacs)	Particulars
1	MR(3054) New Maintaince Policy 2018		3179.85875	Certified that out of 3179.85875 Lacs of grants-in-aid sanctioned during the years 2020-21, 2021-22 & 2022-2023 in favour of E-in-C, RWD Bihar, Patna a sum of Rs 3160.69367 lacs has been utilized for the purpose of MR(3054) New Maintaince Policy 2018 as given in the margin for which it was sanctioned and the balance of Rs 19.16508 remaining unutilized at the end of the period under.
		Total	3179.85875	


- 2 Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned



Kind of Checks exercised :-

- Works have been supervised by Executive Engineer/ Superintending Engineer.
- Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- Construction materials have been tested.
Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer./
- Executive Engineer.
- All other codal formalities have been observed.

3 Physical Progress achieved :-

- Construction of Road Works
- Construction of CD works.


DAO
RWD, Works Division
Rajgir (Nalanda)


Executive Engineer
RWD, Works Division
Rajgir (Nalanda)

10/01/23

Requisition Format for scheme Head : MR(3054) Under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

RWD, Works Division : Rajgir

Sl No	Package No	Project ID as Per MIS	Name of Road	Administrative Approval (AA) Letter No & Date	Administrative		Agreement		Agreement No & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (In mm/km)	Thickness of Bitumen Layer (In MM)	Value of Bitumen Content in Percentage	Previous Total Allotted Amount (In Lakh)	Up to date Expenditure as per MIS (In Lakh)	Requisition against work done (In Lakh)	Remarks
					Length (Km)	Amount (In Lakh)	Initial Rectification with Surface Renewal	5 Year Routine Maintenance										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	R/M/N A/R/AJ /23/00 01	10200904009	Gangti high school to village Gangti	548/11.07 .2022	1.000	37.63800	32.92480	7.95255	07/MBD/202 2-23- 24.12.2022	23.09.202 3	Complete	3142	25.00	5.00	0.00000	0.00000	30.10000	Complete
Total					1.000	37.63800	32.92480	7.95255							0.00000	0.00000	30.10000	

- 1 Signed Hard Copy and Soft Copy (In Excel) of recorded IRI is enclosed.
- 2 Up-to-date Physical Progress has been uploaded in MIS

Divisional Account Officer
RWD, Works Division, Rajgir

Executive Engineer
RWD (W) Division Rajgir

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	CATEGORY ROAD	Latitude	Longitude	Event
09/3/23	12:4:36	36	0.1	340	30.3	3400	3891 G		25.108459	85.372571	
09/3/23	12:4:36	36	0.1	270	20.2	2700	3199 G		25.108482	85.373782	Normal
09/3/23	12:5:11	36	0.1	200	30.3	2000	2404 G		25.107561	85.373781	Normal
09/3/23	12:5:11	36	0.1	260	20.2	2600	3086 G		25.107298	85.374528	Culvert
09/3/23	12:6:22	36	0.1	270	20.2	2700	3199 G		25.106724	85.374601	Culvert
09/3/23	12:6:22	36	0.1	210	20.2	2100	2618 G		25.105542	85.375605	Normal
09/3/23	12:7:0	36	0.1	240	30.3	2400	2858 G		25.105732	85.374371	Normal
09/3/23	12:7:0	36	0.1	320	30.3	3200	3767 G		25.10508	85.373811	Curve
09/3/23	12:7:0	36	0.1	270	20.2	2700	3199 G		25.105054	85.372576	Normal

$$Y = 0 * X^2 + 1.136 * X + 132.5$$

$$X = 5507$$

$$Y = 6388$$

(R) RURAL ROAD

Good Average Poor
 <4000 4001-5000 >5001

9/10/3/2023
 S.E.

10/3/2023
 100% 100%

10/3/2023
 E-E.

