



कार्यपालक अभियंता का कार्यालय

ग्रामीण कार्य विभाग, कार्य प्रमंडल मुंगेर



पत्रांक—306 अमु.

मो0-8986915296

दिनांक—15/3/2023

ई मेल - ee.reomunger@gmail.com

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, मुंगेर।

सेवा में,

नोडल पदाधिकारी,
नई अनुरक्षण नीति 2018" (3054-MR)
ग्रामीण कार्य विभाग, बिहार पटना।

विषय :- शीर्ष MR(3054) "नई अनुरक्षण नीति 2018" योजनान्तर्गत पथ के निर्माण में
संवेदक के विपत्र भुगतान हेतु राशि की अधियाचना के सम्बन्ध में।

महाशय,

उपर्युक्त विषय के संबंध में सूचित करना है कि शीर्ष MR(3054) "नई अनुरक्षण
नीति 2018" योजनान्तर्गत पथ:-

1. Panchyat Indruk Purbi Gram Halimpur Me Sadan Mandal Ke Ghar To Madhya Vidyalay Indruk Tak PCC Road
2. Chandanpura Panchyat Milki Chak To Mushahari Tola Chandrapura Tak Sampark Path Under Jamalpur Block
3. NH-80 At Ramdeo Yadav House To Sichai Bandh Under Jamalpur Indruk West Panchyat
4. BANK PANCHAYAT MUSLIM TOLA JANAUDHA GRAM SE MASJID HOTE HUWE WAKARPUR SIMAN TAK
5. Jamalpur Chandanpura Middle School Chandanpura To Gowdan Of Ramanand Kushwaha में Surface कार्य पूर्ण के भुगतान हेतु आवंटन की अधियाचना विहित प्रपत्र में भर कर की जाती है।

अतः अनुरोध है कि आवंटन उपलब्ध कराने की कृपा की जाय।

अनु0:-यथोक्त।

विश्वासभाजन

15/3/23

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल मुंगेर

15/03/2023

Requisition Formate for Scheme Head - MR(3054) under Bihar Rural Road Maintenance Policy - 2018 (Initial Rectification and Surface Renewal)

Name of Works Division :- Munger

SI No.	Package No.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No & Date	Administrative Approval (AA)		Agreement Amount (In Lakh)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Allocated Amount (in Lakh)	up-to-date expenditure as per MIS (in Lakh)	Requisition against work done (in Lakh)	Remarks
					Length (in km)	Amount of (in Lakh)	Initial Rectification with Surface Renewal (in Lakh)	5 Years Routine Maintenance (in Lakh)										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
		Panchayat Indrakh Purbi Gram Hallampur Me Sudan Mandal Ke Char To Madhya Vidyalay Indrakh Tak PCC Road	20803704028	308/ 22.06.2022	0.3	14.495	8.7457	3.52408	S-MBD-2022-23	07-Jul-23		3030	25.00	5.00	0.00000	0.00000	8.7457	
1	RM/MT/MT/ N/22/0004	Chandrapura Panchayat Milk Chak To Shikharai Toha Chandrapura Tak Sampark Path Under Jamaipur Block	20803704034	308/ 22.06.2022	0.5	22.627	13.85085	5.14963	S-MBD-2022-23	07-Jul-23		2872	25.00	5.00	0.00000	0.00000	13.85085	
2	RM/MT/MT/ N/22/0004	NH-80 At Ramdeo Yadav House To Sichai Banah Under Jamaipur Indrakh West Panchayat	20803704030	308/ 22.06.2022	0.525	26.608	16.45439	5.95353	S-MBD-2022-23	07-Jul-23		2503	25.00	5.00	0.00000	0.00000	16.45439	
3	RM/MT/MT/ N/22/0004	BANK PANCHAYAT MUSLIM TOLA JANATIDHA GRAM SE MASJID HOTE HIWE WAKARPUR SIMAN TAK	20803708146	308/ 22.06.2022	1.3	59.117	36.28023	13.38813	S-MBD-2022-23	07-Jul-23		2734	25.00	5.00	0.00000	0.00000	36.28023	
4	RM/MT/MT/ N/22/0004	Jamaipur Chandrapura Middle School Chandrapura To Gordan Of Ramanand Kushwaha	20803703141	308/ 22.06.2022	1.465	64.649	39.46574	15.40771	S-MBD-2022-23	07-Jul-23		3016	25.00	5.00	0.00000	0.00000	39.46574	
5	RM/MT/MT/ N/22/0004																	

Total = 114.79691

- Signed Hard Copy and Soft Copy (in Excel) of recorded IRI is enclosed.
- Up-to-date Physical Progress has been uploaded in MIS.

(Signature)
15/03

Executive Engineer
RWD, Works Division, Munger

(Signature)
15/03/2023

EXECUTIVE ENGINEER, RURAL WORKS DEPARTMENT, WORKS DIVISION,
Munger

FROM GFR 19 - A

(See Government of India's Decision (I) below Rule - 150)
Form of Utilisation Certificate upto the month of Feb-2023

Name of the Head :- MR (New Maintenance Policy 2018) Fund

Month:- Feb-2023

Sl. No.	Name of Scheme	Sanctioned No./ Date	Amount Received (in Lacs Rs.)	Particulars
1	2	4	5	6
1	Construction of Rural Roads under (NEW Maintenance Policy 2018) Fund	Vide Up to Letter No.32 WE dt. 03.03.2023	2859.53522	Certified that out of Rs. 2859.53522 Lacs received during the year 2019-20 in favour of Executive Engineer R.W.D. Works Division, Munger, Bihar a sum of Rs 2779.01850 Lacs has been utilized for the purpose of MR (New Maintenance Policy 2018) Fund Schemes as given in the margin for which it was sanctioned and that the balance of Rs 80.51672 Lacs remaining un-utilized at the end of the period under.
	Total -		2859.53522	

- 2 Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose fo


Kind of Checks Exercised :-


- Works have been supervised by Executive Engineer/Superintending Engineer.
- Periodical inspection has been conducted by Executive Engineer/Superintending Engineer.
- Construction materials have been tested.
- Measurements have been recorded in the MBs and test checks conducted by the Assistant Engineer/ Executive Engineer.
- All other codal formatities have been observed.

3 **Physical Progress achieved :-**

- Construction of Road Works.
- Construction of CD. Works.


Sr. Divisional Accounts Officer
Rural Works Department
Works Division, Munger


Executive Engineer
Rural Works Department
Works Division, Munger


15/03/2023

Name of Road- BANK PANCHAYAT MUSLIM TOLA JANAUDHA GRAM SE MASJID HOTE HUWE

WAKARPUR SIMAN TAK

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	CATEGORY ROAD	Latitude	Longitude	Event
14/3/23	15:52:0	59	0.1	210	10.1	2100	2125	G	25.354338	86.507407	Normal
14/3/23	15:52:0	59	0.1	230	20.2	2300	2365	G	25.354857	86.507658	Normal
14/3/23	15:53:0	59	0.1	250	20.2	2500	2550	G	25.355552	86.507912	Normal
14/3/23	15:53:0	59	0.1	220	20.2	2200	2215	G	25.355788	86.508332	Normal
14/3/23	15:54:0	59	0.1	230	20.2	2300	2325	G	25.355875	86.50882	Normal
14/3/23	15:54:0	59	0.1	350	10.1	3500	3525	G	25.356313	86.509007	Breaker
14/3/23	15:54:0	59	0.1	300	20.2	3000	3015	G	25.356568	86.509123	Normal
14/3/23	15:55:0	59	0.1	310	20.2	3100	3135	G	25.357038	86.509477	Normal
14/3/23	15:56:0	59	0.1	320	10.1	3200	3245	G	25.357943	86.51002	Breaker
14/3/23	15:57:0	59	0.1	270	10.1	2700	2750	G	25.358477	86.510387	Normal
14/3/23	15:57:0	59	0.1	290	20.2	2900	2950	G	25.35877	86.511413	Normal
14/3/23	15:58:0	59	0.1	280	20.2	2800	2835	G	25.35915	86.512103	Normal
14/3/23	15:59:0	59	0.1	250	20.2	2500	2515	G	25.358748	86.511347	Normal

$$Y = 0 * X^2 + 1.021 * X - 31.77$$

$$X = 0$$

$$Y = -32$$

(R) RURAL ROAD

Good Average Poor

<4000 4001-5000 >5001

Signature
15/3/23
JR

Signature
15/3/23
Executive Engineer
RWD Works Division
Munger


Name of Customer :	Male Devi
Name of Work/ Road :	BANK PANCHAYAT MUSLIM 1
Lab Job number :	59
Date :	14-03-2023
Section No. :	59

Test Date :	14-03-2023	Road Name :	BANK PANCHAYAT MUSLIM
Machine No :	385	Road Type :	(R) RURAL ROAD
Start S No :		Side :	
Start E No :		Interval :	
Weather :		UV Range :	1125 To 5000 1000 mm/km
Start Location :		Dist Range :	0 To 1.4 0.1 * 1000 m
End Location :		Equation :	$Y = 0 * X^2 + 1.021 * X - 31.77$

Print Generate Report and Graph

Redraw Graph

Map View



Signature
15/03/23
SE

Signature
15/3/23

Executive Engineer
RWD Works Division Munger