

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, समस्तीपुर

पत्रांक 2188 3190 दिनांक 7/11/23

प्रेषक:-

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, समस्तीपुर।

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव
ग्रामीण कार्य विभाग, बिहार, पटना।

विषय:-

शीर्ष New Maintenance Policy 2018 मद में आवंटन उपलब्ध कराने के संबंध में।

महाशय,

उपर्युक्त विषयक शीर्ष New Maintenance Policy 2018 योजनान्तर्गत निर्मित/
निर्माणाधीन पथों का विहित प्रपत्र में अधियाचना पत्र संलग्न कर भेजा जा रहा है।

अतः अनुरोध है कि संलग्न अधियाचना पत्र के अनुसार आवंटन उपलब्ध कराने की कृपा
की जाय।

अनु0-यथोक्त।

विश्वासभाजन

A. K.
7/11/23
कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, समस्तीपुर

Rm
7.11.23

FROM GFR 19-A**(See Government of India's Division (I) below Rule- 150)****Form of Utilization Certificate upto 06.11.2023****PIU- E.E., R.W.D. Works Division, Samastipur**

S.N.	Name of Scheme	Sanction No.& Date	Amount Received	Particulars
1	Construction of Rural Road under New Maintenance Policy-2018	Secretary cum Empowered Officer BRRDA Bihar Patna vide upto Lt. no.-147 dt.01.11.2023	685032963.00	Certified that out of Rs.685032963.00 received upto 06.11.2023 in favour of Executive Engineer R.W.D. Works Division Samastipur a sum of Rs.615058871.00 has been utilized for the purpose of New Maintenance Policy-2018 Schemes as given in the margine for which it was sanctioned and that the balance of Rs. 69974092.00 remaining unutilized at the end of period under report.
			68,50,32,963.00	

2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for the which it was sanctioned.

Kind of Checks exercised:-

- i Works have been supervised by Executive/Superintending engineer.
- ii Periodical inspection has been conducted by Executive/Superintending engineer.
- iii Construction materials have been tested.
- iv Measurements have been recorded in the MB's and test check conducted by Assistant Engineer/Executive
- v All other codal formalities have been observed.

3 Physical Progress achieved:-

- i Construction of Road work.
- ii Construction of CD works.

Executive Engineer
Works Division Samastipur
Rural Works Dipartment

Ru
7.11.23


Requisition Format for scheme Head : MR(3054) Under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

RWD, Works Division : Samastipur		Project ID as Per MIS	Name of Road	Administrative Approval (AA) Letter No & Date		Administrative		Agreement Amount		Agreement No & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in MM)	Value of Bitumen Content in Percentage	Previous Total Allotted Amount (in Lakh)	Upto date Expenditure as per MIS (in Lakh)	Requisition against work done (in Lakh)	Remarks
SI No	Package No					Length (Km)	Amount (in Lakh)	Initial Rectification with Surface Renewal	5 Year Routine Maintenance										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	
1	FM/SA/SAM/22/0002	NLA220001267	MLR 102 To NABTOL	1341 & 24.03.2022	2.520	152.420	117.159	33.746	127(MBD)22-23	20.11.2023	Complete	2904	25	5.0	0	0	117.150	Complete	
2		3201011035552	Pavachal Mahito ke ohar see Shantkar chok		2.430	184.260	144.265	32.368		20.11.2023	Complete	2608	25	5.0	0	0	144.260	Complete	
Total					4.950	336.680	261.424	66.114									261.410		

1 Signed Hard Copy and Soft Copy (in Excel) of recorded IRI is enclosed.

2 Up-to-date Physical Progress has been uploaded in MIS

[Signature]
Executive Engineer
RWD (W) Div. Samastipur
7.11.23



06/11/23

06/11/23

Assf. 2 T Manager
 Samastipur

Executive Engineer
 Rural Work Department
 Works Division, Samastipur

Name of Road :-Gram Matua Pyarelal Mahto Ke Ghar To Shankar Chowk.

Section no.-32

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	CATEGORY	Latitude	Longitude	Event
6/11/23	9:46:53	32	0.1	220	0	2200	2631	ROAD	25.902701	85.876483	Normal
6/11/23	9:47:31	32	0.1	230	10.1	2300	2745	G	25.9026	85.876948	Normal
6/11/23	9:48:5	32	0.1	210	10.1	2100	2518	G	25.902624	85.877811	Normal
6/11/23	9:48:47	32	0.1	220	10.1	2200	2631	G	25.902663	85.878436	Normal
6/11/23	9:49:9	32	0.1	220	10.1	2200	2631	G	25.902687	85.878944	Curve
6/11/23	9:49:42	32	0.1	230	10.1	2300	2745	G	25.902705	85.879438	Normal
6/11/23	9:50:10	32	0.1	220	10.1	2200	2631	G	25.903058	85.880465	Normal
6/11/23	9:50:45	32	0.1	200	10.1	2000	2404	G	25.902478	85.881836	Normal
6/11/23	9:51:9	32	0.1	210	10.1	2100	2518	G	25.901523	85.883858	Curve
6/11/23	9:51:40	32	0.1	200	10.1	2000	2404	G	25.901463	85.884157	Normal
6/11/23	9:52:7	32	0.1	230	10.1	2300	2745	G	25.901473	85.88458	Normal
6/11/23	9:52:40	32	0.1	220	10.1	2200	2631	G	25.901129	85.88498	Normal
6/11/23	9:53:6	32	0.1	210	10.1	2100	2518	G	25.90072	85.885259	Normal
6/11/23	9:53:45	32	0.1	220	10.1	2200	2631	G	25.899843	85.88585	Curve
6/11/23	9:54:10	32	0.1	230	10.1	2300	2745	G	25.89983	85.886625	Normal
6/11/23	9:54:45	32	0.1	220	10.1	2200	2631	G	25.899449	85.889634	Normal
6/11/23	9:55:9	32	0.1	210	10.1	2100	2518	G	25.899426	85.889774	Normal
6/11/23	9:55:42	32	0.1	220	10.1	2200	2631	G	25.90067	85.891028	Normal
6/11/23	9:56:7	32	0.1	220	10.1	2200	2631	G	25.900628	85.89115	Normal
6/11/23	9:56:42	32	0.1	230	10.1	2300	2745	G	25.900688	85.891269	Curve

Asst. IT Manager
Samastipur

6/11/23

6/11/23

Executive Engineer
Rural Work Department
Works Division, Samastipur

Time	Section	Length	Bumps	Speed	OR	IRI	CATEGORY	Latitude	Longitude	Event
	No.	in km	in mm	Rate	mm/km	mm/km				
6/11/23	32	0.1	220	10.1	2200	2631	ROAD	25.901257	85.893103	Normal
6/11/23	32	0.1	210	10.1	2100	2518	G	25.90131	85.894424	Normal
6/11/23	32	0.1	220	10.1	2200	2631	G	25.901324	85.89458	Normal
6/11/23	32	0.1	210	10.1	2100	2518	G	25.90116	85.895957	Normal
Total=		2.40	Km	Avg. 2607.58						


 Executive Engineer
 Rural Works Division
 Sheikhpura
 Works Division, Samastipur


 Rubal Wajid