

कार्यपालक अभियन्ता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमण्डल, सहरसा

सहरसा, दिनांक 10.11.23 /

पत्रांक-1772-23/

प्रेषक:-

कार्यपालक अभियन्ता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, सहरसा।

सेवा में,

नोडल पदाधिकारी,
3054 (M.R) कोषांग,
बिहार, पटना।

विषय:-

शीर्ष 3054 नई अनुरक्षण नीति-2018 अंतर्गत Initial Rectification and Surface renewal. कराये गये कार्य हेतु अधियाचना के संबंध में।

महाशय,

उपर्युक्त विषयक कहना है कि विहित प्रपत्र में संलग्न विवरणी के अनुसार शीर्ष Mr 3054 New Maintenance Policy-2018. अन्तर्गत Initial Rectification and Surface renewal. कराये गये कार्य हेतु राशि Rs.82,26,624/- (रुपये बेरासी लाख छबीस हजार छः सौ चौबीस) मात्र राशि की आवश्यकता है।

अतः कार्यहित में अनुरोध है कि उक्त अधियाचित राशि Rs.82,26,624/- (रुपये बेरासी लाख छबीस हजार छः सौ चौबीस) उपलब्ध कराने की कृपा की जाय ताकि कराये जा रहे कार्यों का विपत्र भुगतान किया जा सके।

- अनु०:- (1) अधियाचना प्रपत्र
(2) IRI Value Report
(3) Map
(4) प्रमाण-पत्र।

10/11/23

विश्वासभाजन

10-11-2023

कार्यपालक अभियन्ता

ग्रामीण कार्य विभाग, कार्य प्रमण्डल,
सहरसा

**OFFICE OF THE EXECUTIVE ENGINEER
RWD WORKS DIVISION SAHARSA.**

Name of Scheme:- Chandrain Chowk Se Ekadh Madhya Vidalaya Hote Hue Besar Tola
Tak, PACKAGE No- RM/SA/SAH/22/0003, Project ID- 20904313017.

**Certified that all item wise 100%
Measurement has been taken by me**

(Signature)
10/11/23

**Junior Engineer
RWD Work section Nauhatta
Works Division Saharsa**

**Certified that all item wise 50%
Measurement has been cheked by me**

(Signature)
10/11/23

**Assistant Engineer
RWD Work Section Nauhatta
Works Division Saharsa**

**Certified that all item wise 10%
Measurement has been cheked by me**

(Signature)
10-11-2023

**Executive Engineer
Rural work Department
Works Division Saharsa**

Rural Works Department

MR NEW MAINTENANCE POLICY-2018, ALLOTMENT REQUISITION

Date-10.11.2023

Name of Division:- RWD Works Division Saharsa

Sl. No.	Year	Name of Road	Name of Contractor (In English)	Project Id	Administrative Sanction		Agreement Amount (In Lacs)		Value of TRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Allotment Received (in Lacs)	Total Expenditure as per MIS (in Lacs)	Value of Measurement (in Lacs)	Current Demand (in Lacs)	Remarks
					Length (in Km)	Amount (in Lacs)	Main Work	Maintenance								
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17
53	2022-23	Chandrain Chowk Se Elach Hadhya Vidlaya Hote Hue Besar Toa Tak	Chandrika Prasad Sah	20904313017	1.660	110.63000	82.26624	20.12930	2811	25.000	5%	0.00000	0.00000	82.26624	82.26624	Complete

RWD Works Division
Saharsa

Executive Engineer
RWD Works Division
Saharsa

18/11/23

20/11/23

Name of Road - Chandrain Chowk Se Ekadh Madhya Vidyalaya Hote Hue Besar Tola Tak

Name of Contractor Chandrika Prasad Sah

Batch Name -RM/SA/SAH/22/0003

Date	Time	Section		Length		Bumps		Speed		OR		CATEGOR Y	Latitude	Longitude	Event
		No.		in km		in mm		Rate		mm/km	mm/km				
08-11-2023	11:54:13	95		0.100		180		10.1		2000	2478	G	25.954302	86.458772	Normal
08-11-2023	11:54:34	95		0.100		200		10.1		2000	2478	G	25.954355	86.458823	Normal
08-11-2023	11:55:00	95		0.100		270		10.1		2700	3167	G	25.954370	86.458005	Normal
08-11-2023	11:55:14	95		0.100		180		10.1		2000	2478	G	25.952950	86.457612	Normal
08-11-2023	11:55:25	95		0.100		270		10.1		2700	3167	G	25.955144	86.454293	Normal
08-11-2023	11:56:00	95		0.100		210		10.1		2100	2577	G	25.954646	86.453623	Normal
08-11-2023	11:56:34	95		0.100		210		10.1		3000	3462	G	25.955088	86.452970	Normal
08-11-2023	11:57:09	95		0.100		190		10.1		1900	2380	G	25.954959	86.452225	Normal
08-11-2023	11:57:21	95		0.100		210		10.1		2100	2577	G	25.955067	86.451562	Normal
08-11-2023	11:58:02	95		0.100		180		10.1		2000	2478	G	25.955040	86.452074	Normal
08-11-2023	11:58:37	95		0.100		270		10.1		2700	3167	G	25.955015	86.452249	Normal
08-11-2023	11:59:08	95		0.100		180		10.1		2000	2478	G	25.955116	86.452351	Normal
08-11-2023	11:59:45	95		0.100		200		10.1		2000	2478	G	25.943703	86.455258	Normal
08-11-2023	12:00:04	95		0.100		180		10.1		2000	2478	G	25.948839	86.453993	Normal
08-11-2023	12:00:29	95		0.100		270		10.1		2700	3167	G	25.948941	86.454195	Normal
08-11-2023	12:01:07	95		0.100		180		10.1		2000	2478	G	25.948839	86.453993	Normal
08-11-2023	12:01:48	95		0.060		270		10.1		2700	3167	G	25.949474	86.454045	Normal
		Total		46655.0											
		Average		2811.00											

$$Y = 0 \cdot X^2 + 0.984 \cdot X + 510.7$$

$$X = 2100$$

$$Y = 2577$$

(R) RURAL ROAD

Good Average Poor
<4000 4001-5000 >5001


10/11/23

10/11/23

08-11-2023

File : E:\BUMP INDICATOR\Sahaisa\11081243.xls, Section NO. : 95, Eqn : test

Name of Customer : Chandrika Prasad Sah, Name of Work/ Road : Chandrain Chowk se Ekadh Madhay Vidalya



Chandrika
10/11/23

Prasad
10/11/23
AE

Chandrika
10-11-2023