

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, सासाराम-1

Email ID:-ee.rwd.sasaram1@gmail.com

Mob:- 8986915310

पत्रांक.....2371/2170 सासाराम/दिनांक.....16/11/2023

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, सासाराम-1

सेवामें,

नोडल पदाधिकारी (MR 3054)
ग्रामीण कार्य विभाग
पटना, बिहार

विषय :- नई अनुरक्षण नीति-2018MR (3054) योजना के अंतर्गत पथ में कराये गये कार्य के विरुद्ध आवंटन उपलब्ध कराने के संबंध में।

महाशय,

उपरोक्त विषय के संबंध में सूचित करना है कि नई अनुरक्षण नीति-2018 MR (3054) योजना के अंतर्गत पथ में कराये गये कार्य के लिए संवेदक को भुगतान करने हेतु अधियाचना विहित प्रपत्र में भरकर आवश्यक कार्यवाही हेतु समर्पित की जाती है।

अनु० :- यथोक्त।

विश्वासभाजन

(इ० रामचन्द्र पंडित)
कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, सासाराम-1

FORM GFR 19-A

(See Government of India's Decision (I) below Rule-150)

Form of Utilization Certificate up to Nov 2023

Sl.No	Name of Scheme	Sanction No.&Date With Amount (In lace Rs.)	Amount Received (In lace Rs.)	Particulars
1	Construction of Rural roads Under MR	New Maintenance Policy-2018 MR (3054) BRRDA PATNA	12350.53751	Certified that out of Rs. 12350.53751 lakh of grants-in-aid sanctioned during the years 2021-23 Infavor of EE, RWD works division Sasaram-1 sum of Rs 12219.70481akh has been utilized for the purpose of MR (3054) Schemes as given in the margin for which it was sanctioned and that the balance of Rs.130.83270 lakh remaining unutilized at the end of the period under report.
	Total:		12350.53751	

2. Certified that I have satisfied my self that the conditions on which the grant-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was utilized for the purpose for which it was sanctioned.

Kind of Checks exercised:-

- i. Works have been supervised by Executive Engineer/ Superintending Engineer.
- ii. Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- iii. Construction materials have been tested.
- iv. Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/ Executive Engineer.
- v. All other caudal formalities have been observed.

3. Physical Progress achieved:-

- i. Construction of Road Works.
- ii. Construction of CD works.


Divisional Accounts Officer
R.W.D, works Division
Sasaram-1


Executive Engineer

R.W.D, works Division
Sasaram-1

OFFICE OF EXECUTIVE ENGINEER, RURAL WORKS DEPARTMENT, WORKS DIVISION, SASARAM-1

Requisition Format for Scheme Head- MR(3054) under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

Name of Works Division:- Sasaram-1

Sl no	Batch No	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No & Date	Administrative Approval (AA)		Agreement Amount (in Lakh)		Agreement No & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Allocated Amount (in Lakh)	up-to-date expenditure as per MIS (in Lakh)	Requisition against work done (in Lakh)	Remark
					Length (in km)	Amount of Rectification with Surface Renewal (in Lakh)	Initial Rectification with Surface Renewal (in Lakh)	5 Year Routine Maintenance (in Lakh)										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	RN/RO/S AS/23/0 011	Kuchila road to Khara Ojhalaya	13101286695	1412 08.09.2022	4.2	170.656	141.63214	23.27069	14MBD/20 22-23 & 03/02/20 23	02-Nov-23	0	3026	25	5.01	0.00000	0.00000	140.49891	
2	RN/RO/SA S/23/001 4	G.T. Road - Samahuta	10301102044	1891 25.03.2023	2.8	127.906	93.33015	20.05383	9/MBD/23- 24 & 25/09/2023	24-Jun-24	0	3172	25	5.12	0.00000	0.00000	93.33015	
3	RN/RO/SA S/23/001 4	LC77-N H 2 TO PAKHNARI (ODR57)	10301002285	1891 25.03.2023	0.9	45.474	32.18594	5.47367	9/MBD/23- 24 & 25/09/2023	24-Jun-24	0	3115	25	5.09	0.00000	0.00000	32.18594	
4	RN/RO/SA S/23/001 4	Miranda - Mouni	10301002196	1891 25.03.2023	2.31	112.147	75.16313	17.49327	9/MBD/23- 24 & 25/09/2023	24-Jun-24	0	3135	25	5.20	0.00000	0.00000	75.16313	

Divisional Account Officer
Rural Works Department,
Works Division, Sasaram-1

Executive Engineer
Rural Works Department
Works Division, Sasaram-1

Name of Road:- Mitanda To Mauni

Date	Time	Section No	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	CATEGORY ROAD	Latitude	Longitude	Event
11/11/23	14:28:3	76	0.1	200	10.1	2000	2415	G	24.920888	83.92483	Normal
11/11/23	14:28:11	76	0.1	310	10.1	3100	3515	G	24.921772	83.924965	Normal
11/11/23	14:28:38	76	0.1	300	10.1	3000	3415	G	24.922515	83.925437	Normal
11/11/23	14:34:0	76	0.1	260	20.2	2600	3015	G	24.922935	83.925487	Normal
11/11/23	14:34:12	76	0.1	270	10.1	2700	3115	G	24.923785	83.925453	Normal
11/11/23	14:35:5	76	0.1	260	10.1	2600	3015	G	24.9247	83.925655	Normal
11/11/23	14:35:16	76	0.1	230	10.1	2300	2715	G	24.925413	83.926093	Normal
11/11/23	14:35:41	76	0.1	300	10.1	3000	3415	G	24.926287	83.926413	Normal
11/11/23	14:36:16	76	0.1	260	10.1	2600	3015	G	24.926847	83.92643	Normal
11/11/23	14:52:9	76	0.1	240	20.2	2400	3415	G	24.926462	83.925555	Culvert
11/11/23	14:52:17	76	0.1	270	10.1	2700	3115	G	24.926557	83.924628	Normal
11/11/23	14:53:0	76	0.1	300	20.2	3000	3415	G	24.926763	83.923635	Normal
11/11/23	14:53:19	76	0.1	280	10.1	2800	3215	G	24.927475	83.923585	Normal
11/11/23	14:53:31	76	0.1	250	10.1	2500	2915	G	24.928348	83.923568	Normal
11/11/23	14:54:0	76	0.1	300	20.2	3000	3415	G	24.92922	83.923652	Normal
11/11/23	14:54:10	76	0.1	270	20.2	2700	3115	G	24.930125	83.923737	Normal
11/11/23	14:54:30	76	0.1	290	20.2	2900	3315	G	24.930905	83.924107	Normal
11/11/23	14:54:39	76	0.1	260	20.2	2600	3015	G	24.931582	83.924578	Normal
11/11/23	14:55:5	76	0.1	250	20.2	2500	2915	G	24.932408	83.924697	Normal
11/11/23	14:55:12	76	0.1	310	20.2	3100	3515	G	24.933238	83.924697	Normal
11/11/23	14:55:40	76	0.1	250	10.1	2500	2915	G	24.934168	83.924697	Normal
11/11/23	14:56:16	76	0.1	260	10.1	2600	3015	G	24.93499	83.92478	Curve
11/11/23	14:56:19	76	0.1	290	10.1	2900	3315	G	24.935302	83.923922	Normal
11/11/23	14:57:0	76	0.1	300	10.1	3000	3015	G	24.9358	83.923163	Normal
Average IRI							3135				

$$Y = 0 * X^2 + 1.000 * X + 415.2$$

$$X = 3000$$

$$Y = 3415$$

(R) RURAL ROAD
Good Average Poor
<4000 4001-5000 >5001

11.11.23
J.E.

11/11/23
A.C.

Executive Engineer
Rural Work's Department
Work Division, Sasaram-1

Name of Customer:	Nawal Kishor Singh
Name of Work Road:	Mitanda To Mauni
Lab Job number:	76
Date:	11-11-2023
Section No.	76


Test Date:	11-11-2023	Road Name:	Mitanda To Mauni
Machine No:	391	Road Type:	(R) RURAL ROAD
Start S No:	12	Side:	Sheosagar
Start E No:	35	Interval	
Weather:	Normal	UIV Range:	1415 To 5000
Start Location:	0888.83 92463	Dist Range:	0 To 2.5
End Location:	358.83 923163	Equation:	$Y = 0 * X^2 + 1.000 * X + 415.2$

Print Generate Report and Graph

Redraw Graph

Map View

File: F:\Bomp Machine report\Mar_2023 New MR road\Basant Kumar (Nawal Kishor) New MR
Name of Customer: Nawal Kishor Singh, Name of Work Road: Mitanda To Mauni, Lab Job number: 76



11.11.23
J.E.

11/11/23
AC

11/11/23