

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग कार्य प्रमंडल, बेनीपट्टी।

पत्रांक 1720 486

दिनांक 13/10/2023

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, बेनीपट्टी ।

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव,
बिहार ग्रामीण पथ विकास अभिकरण,
ग्रामीण कार्य विभाग,
बिहार, पटना ।

विषय:- शीर्ष NEW MAINTENANCE POLICY - 2018 (MR - 3054) में आवंटन उपलब्ध कराने के संबंध में।

महाशय,

उपरोक्त विषय के संबंध में कहना है शीर्ष NEW MAINTENANCE POLICY - 2018 (MR-3054) अन्तर्गत पथ में संलग्न विवरणी के अनुसार आवंटन उपलब्ध कराने की कृपा की जाय ताकि संवेदक का भुगतान किया जा सके।

अनु०:-

1. अधियाचना प्रमाण पत्र 1 पृष्ठ में।
2. उपयोगिता प्रमाण पत्र एक प्रति ।

विश्वासराजन

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, बेनीपट्टी।

FORM GFR 19-A

(See Government of India's Decision (I) below Rule-150)

Form of Utilisation Certificate Upto the month of 30 September 2023

New Maintenance policy - 2018

PIU – Executive Engineer, R.W.D (W) Division, Benipatti

SL. No	Name of Sachem	Sanction No. & Date with Amount (In Rs. lacs)	Amount Received (In Rs. lacs)	Particulars
1	Construction of Rural roads under New maintenance policy - 2018	Authorization letter No. 74 we dt- 16.05.2023 Rs.191.49520	1810.53505	Certified that out of Rs.1810.53505 Lakh received during the years up to 2023-24 (30 September 2023) in favour of Ex. Engineer, RWD (W) Division Benipatti, Madhubani, Bihar, a sum of Rs. 1800.55827 Lakh has been utilized for the purpose of New maintenance policy-2018 as given in the margin for which the balance of Rs 9.97678 Lakh remaining unutilized at the end of the period under.


2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercised :-

- Works have been supervised by Executive Engineer/Superintending Engineer.
- Periodical inspection has been conducted by Executive Engineer/Superintending Engineer.
- Construction materials have been tested.
- Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/Executive Engineer.
- All other codal formalities have been observed.

3. Physical Progress achieved:-

- Construction of Road Works.
- Construction of CD Works.


13/10/23

**Divisional Account Officer,
R.W.D (W) Division
Benipatti**



13/10/23

**Executive Engineer
R.W.D (W) Division
Benipatti**


Formate of Requisition under Head New Maintenace policy - 2018 (MR- 3054) for the month of October-2023

ame of Division :- Benipatti

SI No.	Package No.	Name of road	Project ID as per MIS	Administrative Approval (AA) Letter No & Date	Administrative Approval (AA)		Agreement Amount (in Lakh)		Agreement No & Date	Date of Completion as par Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Alloted Amount (In Lakh)	up-to-date expenditure as par MIS (In Lakh)	Requisition against work done (In Lakh)	Remarks
					Length (In km)	Amoun of (in lakh)	Initial Rectification with Surface Renewal (In Lakh)	5 Year Routine Maintenance (In Lakh)										
1	RM/MA/BEN/20/ 0001	Madhubani jila antargat benipatti prkhand me ganguli se tisi narsam path	31910003008	1014/ 03.03.2020	3.800	129.67300	74.48522	29.47830	17MBD/2022-23 30.12.2022	29.12.2023	12.10.2023	2474	25	5	0.00000	0.00000	70.48522	Work Complete
Total					3.800	129.67300	74.48522	29.47830	—	—	—	2474	25	5	0.00000	0.00000	70.48522	


13/10/23

Divisional Account Officer,
R.W.D(W)Div. Benipatti


13/10/23
Executive Engineer
R.W.D(W)Div. Benipatti

OFFICE OF THE EXECUTIVE ENGINEER
RWD WORKS DIVISION
BENIPATTI

Name of Scheme:- Madhubani jila antargat benipatti prkhand me ganguli se tisi narsam path, Package No. -

RM/MA/BEN/20/ 0001

Project ID - 31910003008

Certified that all item wise 100%
measurement has been taken by
me


13/10/23

Junior Engineer
RWD Work Section Bisfi
Works Division Benipatti

Certified that all item wise 50%
measurement has been Cheked by
me


13.10.23
AB

Assistant Engineer
RWD Work Sub Division Bisfi
Works Division Benipatti

Certified that all item wise 10%
measurement has been Cheked by
me


13/10/23

Executive Engineer
RWD Works Division
Benipatti

Name Of Road:-Madhubani jila antargat benipatti prkhand me ganguli se tisi narsam (Nabard) tak path nirman

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI In MM/Km UIV	CATEG ORY ROAD	Latitude	Longitu de	Event
12/ 10/ 23	11: 19: 0	42	0.1	240	20.2	2400	2350 G		26.3955	85.88918	Normal
12/ 10/ 23	11: 19: 0	42	0.1	270	20.2	2700	2656 G		26.39545	85.89018	Normal
12/ 10/ 23	11: 19: 34	42	0.1	290	10.1	2900	2854 G		26.39489	85.89081	Normal
12/ 10/ 23	11: 19: 34	42	0.1	240	20.2	2400	2360 G		26.39429	85.89161	Normal
12/ 10/ 23	11: 20: 9	42	0.1	250	20.2	2500	2458 G		26.39353	85.89222	Normal
12/ 10/ 23	11: 20: 9	42	0.1	230	20.2	2300	2261 G		26.39281	85.89276	Normal
12/ 10/ 23	11: 20: 44	42	0.1	200	20.2	2000	1964 G		26.39202	85.8933	Normal
12/ 10/ 23	11: 21: 0	42	0.1	290	10.1	2900	2854 G		26.39121	85.89348	Normal
12/ 10/ 23	11: 21: 20	42	0.1	300	0	3000	2953 G		26.3903	85.89331	Normal
12/ 10/ 23	11: 21: 20	42	0.1	300	10.1	3000	2953 G		26.38933	85.89324	Normal
12/ 10/ 23	11: 21: 20	42	0.1	230	20.2	2300	2261 G		26.3885	85.89358	Normal
12/ 10/ 23	11: 22: 0	42	0.1	270	20.2	2700	2656 G		26.38757	85.89352	Normal
12/ 10/ 23	11: 22: 0	42	0.1	250	20.2	2500	2458 G		26.38627	85.8934	Normal
12/ 10/ 23	11: 22: 30	42	0.1	230	20.2	2300	2261 G		26.38591	85.89421	Normal
12/ 10/ 23	11: 22: 30	42	0.1	270	20.2	2700	2656 G		26.38534	85.89492	Normal
12/ 10/ 23	11: 23: 5	42	0.1	250	20.2	2500	2458 G		26.3846	85.89458	Normal
12/ 10/ 23	11: 23: 5	42	0.1	230	20.2	2300	2261 G		26.38385	85.89413	Normal
12/ 10/ 23	11: 23: 41	42	0.1	270	20.2	2700	2656 G		26.38298	85.89358	Normal
12/ 10/ 23	11: 24: 0	42	0.1	250	20.2	2500	2458 G		26.38298	85.89358	Curve
12/ 10/ 23	11: 24: 16	42	0.1	230	20.2	2300	2261 G		26.38217	85.89313	Normal
12/ 10/ 23	11: 25: 0	42	0.1	270	20.2	2700	2656 G		26.38146	85.89259	Normal
12/ 10/ 23	11: 25: 0	42	0.1	250	20.2	2500	2458 G		26.38058	85.89221	Normal
12/ 10/ 23	11: 25: 27	42	0.1	230	20.2	2300	2261 G		26.37993	85.89133	Normal
12/ 10/ 23	11: 26: 0	42	0.1	270	20.2	2700	2656 G		26.37993	85.89133	Normal
12/ 10/ 23	11: 32: 30	42	0.1	250	20.2	2500	2458 G		26.37937	85.89075	Normal
12/ 10/ 23	11: 33: 0	42	0.1	300	0	3000	2953 G		26.37853	85.89031	Normal
12/ 10/ 23	11: 33: 5	42	0.1	270	20.2	2700	2656 G		26.37853	85.89031	Curve
12/ 10/ 23	11: 33: 5	42	0.1	250	20.2	2500	2458 G		26.37853	85.89031	Normal
12/ 10/ 23	11: 33: 5	42	0.1	230	20.2	2300	2261 G		26.37774	85.8899	Normal
12/ 10/ 23	11: 33: 40	42	0.1	250	20.2	2500	2458 G		26.37687	85.88961	Normal
12/ 10/ 23	11: 34: 0	42	0.1	230	20.2	2300	2261 G		26.37599	85.88956	Normal
12/ 10/ 23	11: 34: 16	42	0.1	190	20.2	1900	1865 G		26.37503	85.88947	Normal
12/ 10/ 23	11: 34: 16	42	0.1	200	20.2	2000	1964 G		26.37418	85.8893	Normal
12/ 10/ 23	11: 35: 0	42	0.1	300	10.1	3000	2953 G		26.37325	85.88955	Normal

$$Y = 0 * X^2 + 0.989 * X - 13.58$$

$$X = 2300$$

$$Y = 2261$$

(R) RURAL ROAD

Good Average Poor
<4000 4001-5000 >5001


12/10/23 11:35:0	42	0.1	270	20.2	2700	2656 G	26.37233 85.88953 Normal
12/10/23 11:36:0	42	0.1	250	20.2	2500	2458 G	26.37142 85.88939 Normal
12/10/23 11:36:2	42	0.1	230	20.2	2300	2261 G	26.3706 85.88894 Curve
12/10/23 11:36:37	42	0.1	230	20.2	2300	2261 G	26.36899 85.88821 Normal
				Avg	2474.02		

WJ
12/10/23

~~WJ~~
12/10/23
J-E

~~RK~~
13.10.23
AB

File : C:\Users\RWD\OneDrive\Desktop\BUMP SANJAY\26081149.Xls, Section No. : 42, Eqn : $Y = 0 * X^2 + 0.989 * X$
 Name of Customer : SANJAY KUMAR SINGH, Name of Work/ Road : Madhubani jila antarget benipatti prkhand me



[Signature]
 12/10/23
 DE

[Signature]
 13.10.23
 AB

[Signature]
 21/10/23