

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमण्डल, मधेपुरा

पत्रांक- 2274 अनु0

दिनांक- 19/10/23

प्रेषक,

ई0 विद्यानन्द प्रसाद,
कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, मधेपुरा।

सेवा में,

नोडल पदाधिकारी,
3054 एम.आर. कोषांग,
ग्रामीण कार्य विभाग, बिहार, पटना।

विषय- MR (3054) under New Maintenance Policy- 2018 के क्रियान्वित पथों के भुगतान हेतु अधियाचना के संबंध में।

प्रसंग- भवदीय पत्रांक 113 अनु0 दिनांक 10.01.2020

महाशय,

उपर्युक्त विषयक प्रासंगिक पत्र के संबंध में कहना है कि कार्यप्रमण्डल मधेपुरा अन्तर्गत MR (3054) under New Maintenance Policy- 2018 योजना के पथ में पूर्ण कराये गये कार्यों का भुगतान हेतु अधियाचना विहित प्रपत्र में तैयार कर आवश्यक कार्रवाई हेतु समर्पित की जाती है।

सूचनार्थ एवं आवश्यक कार्रवाई हेतु समर्पित।

अनु0- 1. अधियाचना विहित प्रपत्र में।

2. Recorder IRI की प्रतिहस्ताक्षरित प्रति।

विष्वासभाजन

19/10/23
(ई0 विद्यानन्द प्रसाद)
कार्यपालक अभियंता,
19/10/23

Form GFR 19- A
(See Government of India's Decision (I) below Rule - 150)
Form of Utilization Certificate upto the month of 18 October 2023
New Maintenance Policy 2018

Sl. No.	Name of Scheme	Sanction No. & Date with Amount (In lacs)	Amount Received (In lacs)	Particulars
1	New Maintenance Policy 2018	Letter No 56 Dated 12.08.2020 Letter No 86 Dated 11.12.2020	Rs 601.67084 Vide Letter No :- 126 Dated 18.09.2023	Certified that out of RS 8567.13802 lacs of grants in aid sanctioned during the Years up to 2023-24 in favour of Executive Engineer, RWD Works Division Madhepura under this Department, a sum of Rs 8510.64051 lacs has been utilized for the purpose of New_MR Scheme remaining 56.49751 unutilized at the end of the period under report.
		Total :	601.67084	


Certified and verified myself that the conditions on which the grants in aid was sanctioned have been duly fulfilled / are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kinds of Checks exercised :-

- i Works have been supervised by Executive Engineer/ Superintending Engineer.
- ii Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- iii Construction material have been tested.
- iv Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/Executive Engineer.
- v All other codal formalities have been observed.

Physical Progress achieved :-

- i Construction of Road works.
- ii Construction of CD works


D.A.G.
RWD works Division
Madhepura


19/10/23
Executive Engineer
RWD works Division
Madhepura


19/10/23

Requisition Format for Scheme Head - MR (3054) Under Bihar Rural Road maintenance Policy 2018 (Initial Rectification and Surface Renewal)

Name of Division : Madhepura

S.L.N 0	Package no.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount (in Lac)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in percent	Previous Total Allocated Amount (1 Lac)	up to date expenditure as per MIS (in Lac)	Requisition Against work done (In lac)	Remarks
					Length (In Km)	Amount (in Lac)	Initial Rectification with Surface Renewal (in lac)	5 years Routine Maintenance (In lac)										
1	RM/MA/MAD/23/0009	Construction of Road From Maura Jharjaha Panchyat Silma To PMGSY Road via Inter Astariya College	21004713026	1447 / 28.02.2023	2.260	135.572	88.38740	36.29990	22 MBD/2023-24 /28.07.2023	27.04.2024	17.10.2023	3182.00	25mm	5%	0.00	0.00	88.30000	Complete
2	RM/MA/MAD/23/0009	madheli saifan to PMGSY road via south	21004712034	1838 / 24.06.2019	0.830	47.775	27.37270	14.00285	22 MBD/2023-24 /28.07.2023	27.04.2024	17.10.2023	3008.00	25mm	5%	0.00	0.00	27.35000	Complete

Bhadi
19/11/23
D.A.O.

Executive Engineer
RWD Works Division
Madhepura
19/11/23

of Road :-Maura Jharjaha Panchyat Sima To PMGSY Road via Inter Astariya Collee Name of Contractor :-kanchan kumari

Date	Time	Section	Length in km	Bumps in mm	Speed Rate	OR mm/km	CATEGORY ROAD	IRI	Latitude	Longitude	Event
10/18/23	14:12:27	3	0.1	150	0	1500	G	2522	26.0254	86.846203	Normal
10/18/23	14:12:27	3	0.1	230	20.2	2300	G	3431	26.06536	86.845761	Normal
10/18/23	14:13:2	3	0.1	240	20.2	2400	G	3545	26.06535	86.845767	Culvert
10/18/23	14:13:2	3	0.1	250	20.2	2500	G	3658	26.06535	86.845767	Normal
10/18/23	14:13:37	3	0.1	210	20.2	2100	G	3204	26.06310	86.860730	Normal
10/18/23	14:14:0	3	0.1	230	20.2	2300	G	3431	26.06310	86.860730	Normal
10/18/23	14:14:13	3	0.1	230	10.1	2300	G	2400	26.06319	86.860795	Normal
10/18/23	14:14:48	3	0.1	220	10.1	2200	G	3318	26.06319	86.860795	Normal
10/18/23	14:15:23	3	0.1	340	10.1	3400	G	3681	26.06335	86.860909	Normal
10/18/23	14:15:23	3	0.1	250	10.1	2500	G	3658	26.06335	86.860909	Normal
10/18/23	14:16:34	3	0.1	380	0	3800	G	3125	26.06400	86.861093	Normal
10/18/23	14:16:34	3	0.1	280	10.1	2800	G	3000	26.06400	86.861093	Normal
10/18/23	14:17:8	3	0.1	220	10.1	2200	G	3318	26.06360	86.857193	Culvert
10/18/23	14:17:8	3	0.1	230	10.1	2300	G	3431	26.06360	86.857193	Curve
10/18/23	14:18:0	3	0.1	220	10.1	2200	G	2330	26.06357	86.857896	Culvert
10/18/23	14:18:19	3	0.1	180	20.2	1800	G	2863	26.06357	86.857896	Normal
10/18/23	14:18:19	3	0.1	190	20.2	1900	G	2877	26.06415	86.861158	Culvert
10/18/23	14:18:19	3	0.1	210	30.3	2100	G	3204	26.06415	86.861158	Normal
10/18/23	14:19:0	3	0.1	270	20.2	2700	G	3300	26.06415	86.861158	Normal
10/18/23	14:19:0	3	0.1	190	20.2	1900	G	2977	26.06415	86.861158	Normal
10/18/23	14:19:0	3	0.1	200	20.2	2000	G	3090	26.06409	86.861144	Culvert
10/18/23	14:19:29	3	0.1	250	20.2	2500	G	3658	26.06409	86.861065	Normal
Average IRI								3182			

$$Y = 0 * X^2 + 1.136 * X - 181$$

$$X = 2400$$

$$Y = 2545$$

(R) RURAL ROAD

Good Average Poor


<4000 4001-5000 >5001

Executive Engineer
R.W.D. Work Division
Madhupura

Signature
J.F.

File : F:\STECO-USB-GPS V1_1\118051013.Xls. Section No. : 3. Egn : $Y = 0 * X^2 + 1.136 * X - 181$

Name of Customer : KANCHAN KUMAR. Name of Work/ Road : Maura Jhariaha Panchyat Sima To PMGSY Road via



J.E
18/10/23

R.W.D
18/10/23

Executive Engineer
R.W.D. Work Division
Madhepura