

Name of Work : Pakri Bazar to Muza
 Name of Agency : Deepak Kumar
 At- Fathapur, P.O- Chakmaruf, P.S - Belsar O.P Dist - Vasiahall

BIHAR PUBLIC WORKS DEPARTMENT,

[Form F-2]

ITEM RATE TENDER AND CONTRACT FOR WORKS

Agreement No. 25.12. of 2023-2024

General Rule and Directions for the guidance of Contractors.

Date of Written Order :

Date of Completion of Work :

1. All works proposed for execution by contract will be notified in of from invitation to tender pasted on a board hung up in the office of and signed by the subdivision office Executive Engineer.

This notice will states the works to be carried out the hems and approximate quantity there of as well as the date for submitting and opening tender also the amount of earnest money to be deposited and the amount of the security deposit to be deposited by the successful tenderer and the percentage any to deposited from bills. Copies of the specifications, designs and drawings and any other documents required in connection with the submission of tender signed (for the purpose of identification by the Sub divisional/Officer/Executive Engineer during office hours.

2. In the event of the tender being submitted by firm it must be aligned separately by each member there or in the event of the absence of any partner, it must be signed on his behalf by a person holding as power-attorney authorising to do to.
3. Receipts for payments made on account of works when executed by a firm must also be signed by the several partners except where the contractors are described in the their as a firm with case she receipt must singed in the name of the firm be one of the partners, or by sold other person having authority to give effectual receipts of the firm.
4. The memorandum of work tendered for and the memorandum of materials to be supplied by the public work Department and their issue rates shall be filled and completed in the office of the sub divisional office Executive Engineer before the tender form is issued if a team is issues to an intending tender without having been 16 filled in and completed he shall request the office the have this done before he completes and delivers his tender.

5. The amount of earnest money to be deposited with by-

Rs.

If the amount of the estimate does not exceed Rs. 2000		
If the amount of the estimate exceed Rs. 2000 bpt does not exceed Rs. 5000		
If the amount of the estimate exceed Rs. 5000 bpt does not exceed Rs. 10,000		

दीपक कुमार

H. A. O. 1
 R.W.D. Works Division
 Haffpur

Executive Engineer
 R.W.D. Works Division
 Haffpur

(46)

Comparative STATEMENT									
Name of Work :- Pakri Bazar to Muza									
Head	New Maintenance Policy Pilot Project			Quotation no.					
Block	Patelbhi Behar			Date of Issuing Quotation.					
District	Hapur								
Sl. No.	Item			Unit	Quantity	Name of Quotationer			
						Deepak Kumar	Rajiv Kumar Singh		
						Rate	Total	Rate	Total
1	15.3 (i)	Pot hole patching: Treatment of isolated failed pavement areas in traffic lanes using appropriate materials to repair the defect and restore the riding surface to a smooth condition and Edge Repair - Repair of broken edge of seal to line and level to maintain nominal sealed width, with Mix Seal Surfacing							
		First Year							
		Second Year	Sum	0.000	334.100	0.000	336.100	0.000	
		Third Year	Sum	0.000	334.100	0.000	336.100	0.000	
		Fourth Year	Sum	0.000	334.100	0.000	336.100	0.000	
		Fifth Year	Sum	0.000	334.100	0.000	336.100	0.000	
			Sum	0.000	334.100	0.000	336.100	0.000	
2	15.3 (i)	Surface Depression and Rut Patching Application of a levelling course of bituminous materials to depressed or rutted areas of pavement Repair of Pot holes filled with 75 mm BM X 1.25							
		First Year							
		Second Year	Cum	0.000	12,282.50	0.000	12,286.00	0.000	
		Third Year	Cum	0.000	12,282.50	0.000	12,286.00	0.000	
		Fourth Year	Cum	0.000	12,282.50	0.000	12,286.00	0.000	
		Fifth Year	Cum	0.000	12,282.50	0.000	12,286.00	0.000	
			Cum	0.000	12,282.50	0.000	12,286.00	0.000	
3	RCD 10.6	Crack Sealing Filling of cracks and joints, excluding "crocodile" cracking using liquid bituminous sealants in accordance with monthly works program (Qty=L _c)							
		First Year							
		Second Year	M	0.000	3.28	0.000	3.30	0.000	
		Third Year	M	0.000	3.28	0.000	3.30	0.000	
		Fourth Year	M	0.000	3.28	0.000	3.30	0.000	
		Fifth Year	M	0.000	3.28	0.000	3.30	0.000	
			M	0.000	3.28	0.000	3.30	0.000	
4	15.3 (i)	Surface Treatment Application of bituminous surface materials and cover aggregate area of pavement with: (a) Loss of aggregate (surface ravelled) (b) bleeding and flushing; or (c) Laminated asphalt surface. Patch repair over bituminous surface with 20 mm Premix carpet with seal coat Type B							
		First Year							
		Second Year	Sum	0.00	342.24	0.000	343.00	0.00	
		Third Year	Sum	0.00	342.24	0.000	343.00	0.00	
		Fourth Year	Sum	0.00	342.24	0.000	343.00	0.00	
		Fifth Year	Sum	0.00	342.24	0.000	343.00	0.00	
			Sum	0.00	342.24	0.000	343.00	0.00	
						0.000			

5	15.3 (f)	Digout Repair Treatment of isolated failed pavement areas > 0.25m ² by replacement with new material or improvement of existing material including restatement of road surface. Repair of Pot holes filled with 75 mm BM X 1.25 (Qty = L ² / B ² * a ₁ * 0.075 * β)						
		First Year	Cum	0.000	12,286.66	0.000	12,286.66	0.000
		Second Year	Cum	0.000	12,286.66	0.000	12,286.66	0.000
		Third Year	Cum	0.000	12,286.66	0.000	12,286.66	0.000
		Fourth Year	Cum	0.000	12,286.66	0.000	12,286.66	0.000
		Fifth Year	Cum	0.000	12,286.66	0.000	12,286.66	0.000
6	15.3 (g)	Repair of concrete pavement Repair isolated areas of damaged concrete pavement < 0.25m ² patching with 20 mm thick premix carpet with seal coat Type B seal coat Type B (Qty = L ² / B ² * a ₂ * 0.075 * β)						
		First Year	Sum	46.875	327.22	30676.875	334.15	15663.281
		Second Year	Sum	93.750	327.22	46015.313	334.15	21326.563
		Third Year	Sum	140.625	327.22	61353.750	334.15	46989.844
		Fourth Year	Sum	187.500	327.22	61353.750	334.15	62653.125
		Fifth Year	Sum	187.500	327.22	61353.750	334.15	62653.125
7	10.10	Repair of old joint sealant Removal of existing sealant and re sealing of construction, longitudinal or expansion joint in concrete pavement with fresh sealant material Qty = (L _c / 4) * B _c						
		First Year	M	1875.000	26.74	50137.500	27.00	50625.000
		Second Year	M	1875.000	26.74	50137.500	27.00	50625.000
		Third Year	M	1875.000	26.74	50137.500	27.00	50625.000
		Fourth Year	M	1875.000	26.74	50137.500	27.00	50625.000
		Fifth Year	M	1875.000	26.74	0.000	27.00	50625.000
7	15.2	Unsealed Shoulder Repair Making up the irregularities/loss material on shoulder to design level/profit/ Making up of Berms/shoulder, stripping excess soil from the shoulder surfaces to achieve level etc. (Qty = L ² / B ² * a ₃ * β) * 2						
		First Year	Sqm	0.000	55.86	0.000	57.00	0.000
		Second Year	Sqm	0.000	55.86	0.000	57.00	0.000
		Third Year	Sqm	0.000	55.86	0.000	57.00	0.000
		Fourth Year	Sqm	0.000	55.86	0.000	57.00	0.000
		Fifth Year	Sqm	0.000	55.86	0.000	57.00	0.000
8	15.1	Embankment Repairs Restoration of Ralcuts in the embankment and shoulder/Berms with soil, moorum etc (Qty = L _c * B _c * 0.3 * a ₄) * β * 2						
		First Year	Cum	0.000	378.38	0.000	378.40	0.000
		Second Year	Cum	0.000	378.38	0.000	378.40	0.000
		Third Year	Cum	0.000	378.38	0.000	378.40	0.000
		Fourth Year	Cum	0.000	378.38	0.000	378.40	0.000
		Fifth Year	Cum	0.000	378.38	0.000	378.40	0.000
9	15.6	Surface Drain Cleaning Cleaning of channels, including kerb and channel, and reshaping earthen drain, including culvert inlet and outlet drains, to maintain flow of water and protect road and road side from						
		First Year	M	0.00	3.11	0.000	3.13	0.00
		Second Year	M	0.00	3.11	0.000	3.13	0.00
		Third Year	M	0.00	3.11	0.000	3.13	0.00
		Fourth Year	M	0.00	3.11	0.000	3.13	0.00
		Fifth Year	M	0.00	3.11	0.000	3.13	0.00
10		Culvert Cleaning and Culvert Repair						
		Maintenance of C/D Works (Hume Pipe Culvert)						
		First Year	No.	1.00	1,241.28	1,241.280	1,242.00	1,242.00

146

		Second Year	No.	1.00	1,341.28	1241.280	1,342.00	1,342.00
		Third Year	No.	1.00	1,341.28	1241.280	1,342.00	1,342.00
		Fourth Year	No.	1.00	1,341.28	1241.280	1,342.00	1,342.00
		Fifth Year	No.	1.00	1,341.28	1241.280	1,342.00	1,342.00
15.7	(H)	Maintenance of C/D Works (Slab Culvert)						
		First Year	No.	0.00	2,520.35	0.000	2,520.50	0.00
		Second Year	No.	0.00	2,520.35	0.000	2,520.50	0.00
		Third Year	No.	0.00	2,520.35	0.000	2,520.50	0.00
		Fourth Year	No.	0.00	2,520.35	0.000	2,520.50	0.00
		Fifth Year	No.	0.00	2,520.35	0.000	2,520.50	0.00
15.13		White washing of parapet walls of CD work and tree trunks						
		First Year	Sqm	21.00	18.62	391.020	19.00	399.00
		Second Year	Sqm	21.00	18.62	391.020	19.00	399.00
		Third Year	Sqm	21.00	18.62	391.020	19.00	399.00
		Fourth Year	Sqm	21.00	18.62	391.020	19.00	399.00
		Fifth Year	Sqm	21.00	18.62	391.020	19.00	399.00
11	15.12	Tree and Shrub management Cutting of branches of trees, shrubs and trimming of grass and weeds from the Roadway or within the Road land.						
		(i) Cutting of branches of trees and shrubs						
		First Year	No.	0.00	126.55	126.550	127.00	0.00
		Second Year	No.	1.00	126.55	126.550	127.00	127.00
		Third Year	No.	1.00	126.55	126.550	127.00	127.00
		Fourth Year	No.	1.00	126.55	126.550	127.00	127.00
		Fifth Year	No.	1.00	126.55	126.550	127.00	127.00
		(ii) Cutting of shrubs from roadway						
		First Year	No.	0.00	7.77	0.000	8.00	0.00
		Second Year	No.	0.00	7.77	0.000	8.00	0.00
		Third Year	No.	0.00	7.77	0.000	8.00	0.00
		Fourth Year	No.	0.00	7.77	0.000	8.00	0.00
		Fifth Year	No.	0.00	7.77	0.000	8.00	0.00
		(iii) Trimming of grass and weeds						
		First Year	Sqm	0.00	2.59	0.000	3.00	0.00
		Second Year	Sqm	0.00	2.59	0.000	3.00	0.00
		Third Year	Sqm	0.00	2.59	0.000	3.00	0.00
		Fourth Year	Sqm	0.00	2.59	0.000	3.00	0.00
		Fifth Year	Sqm	0.00	2.59	0.000	3.00	0.00
12	15.9	Sign maintenance Sign repair, re-erection, support replacement and/or maintenance cleaning.						
		First Year	Km	2.00	1,141.22	2282.440	1,142.00	2,284.00
		Second Year	Km	2.00	1,141.22	2282.440	1,142.00	2,284.00
		Third Year	Km	2.00	1,141.22	2282.440	1,142.00	2,284.00
		Fourth Year	Km	2.00	1,141.22	2282.440	1,142.00	2,284.00
		Fifth Year	Km	2.00	1,141.22	2282.440	1,142.00	2,284.00
13	15.12	Guard stones/boundary stones/gaundrells Painting guard stones, boundary stones and gaundrell						
		First Year	Sqm	3.04	18.62	56.605	18.65	56.70
		Second Year	Sqm	3.04	18.62	56.605	18.65	56.70
		Third Year	Sqm	3.04	18.62	56.605	18.65	56.70
		Fourth Year	Sqm	3.04	18.62	56.605	18.65	56.70
		Fifth Year	Sqm	3.04	18.62	56.605	18.65	56.70
14	15.11	Maintenance of 280 m and km stones						
		First Year	Km	2.00	755.50	1511.000	756.00	1,512.00
		Second Year	Km	2.00	755.50	1511.000	756.00	1,512.00
		Third Year	Km	2.00	755.50	1511.000	756.00	1,512.00
		Fourth Year	Km	2.00	755.50	1511.000	756.00	1,512.00
		Fifth Year	Km	2.00	755.50	1511.000	756.00	1,512.00

15	RCD 8.13	Providing and laying of hot applied thermoplastic compound 2.5 mm thick including reflectorising glass beads @ 250 gms per sqm area, thickness of 2.5 mm is exclusive of surface applied glass beads as per IRC:35. The finished surface to be level, uniform and free from streaks and holes. Road marking (Qty=L*W*0.1*2)							
	First Year	Sqm		0.00		0.000			
	Second Year	Sqm		0.00		0.000			
	Third Year	Sqm		8.00	670.23	5361.840	671.00	5,368.00	
	Fourth Year	Sqm		0.00		0.000			
	Fifth Year	Sqm		8.00	670.23	5361.840	671.00	5,368.00	
16		Providing and laying of hot applied thermoplastic compound 2.5 mm thick including reflectorising glass beads @ 250 gms per sqm area, thickness of 2.5 mm is exclusive of surface applied glass beads as per IRC:35. The finished surface to be level, uniform and free from streaks and holes. Road marking for CC Portion							
	First Year	Sqm		0.00		0.000			
	Second Year	Sqm		0.00		0.000			
	Third Year	Sqm		400.00	757.11	302844.000	758.00	303,200.00	
	Fourth Year	Sqm		0.00		0.000			
	Fifth Year	Sqm		400.00	757.11	302844.000	758.00	303,200.00	
17		Maintenance of Already Planted Trees for additional four Years-Maintenance of trees by the road side (Avenue trees) by mixing the soil with decayed farm yard/sludge manure, watering, fixing the tree guard and maintaining the plants for additional four							
	First Year	Each		0.00	0.00	0.000	0.00		
	Second Year	Each		0.00	788.00	0.000	789.00	0.00	
	Third Year	Each		0.00	676.00	0.000	677.00	0.00	
	Fourth Year	Each		0.00	602.00	0.000	603.00	0.00	
	Fifth Year	Each		0.00	602.00	0.000	603.00	0.00	

1,105,769.69

1,117,523.42

L1

L2

Total Cost (In Rs)

1% Labour Cess

18 % GST

Add 10% Seigniorage Fee

Grant Total Cost (In Rs.)

1,105,760.00

1,117,523.00

11,057.60

11,175.23

199,036.80

201,154.14

3,000.00

3,000.00

1,332,848.37

1,332,848.37

En Eng Rate quoted by
200pk mngtra approved

Rate quoted by Deepak
or is recommended for
approval.

23/06/2023

AE

23/6

23/6/23

Lowest Rate quoted by Deepak Kumar is approved for
Rs. 13,18,944.00 (Rs. Thirteen lakhs Eight thousand
nine hundred forty four) only

M-4

Superintending Engineer
Rural Works
Work Circle, Muzaffarpur

lowest rate quoted by Quotation Deepak
Kumar is approved for Rs. 13,17,059.00
(Rs. Thirteen lakhs seventeen thousand fifty
nine) only


Superintending Engineer
Rural Works Department
Work Circle, Muzaffarpur
~~Superintending Engineer
Rural Works Department
Work Circle, Muzaffarpur~~
07/10/22

आयकर विभाग
INCOME TAX DEPARTMENT




भारत सरकार
GOVT. OF INDIA



स्थायी लेखा संख्या कार्ड
Permanent Account Number Card

AUAPK1706F



नाम / Name

DEEPAK KUMAR

निर्देशक का नाम / Director's Name

LAL BAHADUR PRABHAKAR

जन्म की तारीख / Date of Birth

08/04/1985

हस्ताक्षर / Signature

हस्ताक्षर / Signature

11971