

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल खड़गपुर-तारापुर

मो०-8986915854

ई मेल - cc.kh.tarnapur.rwd2@gmail.com

पत्रांक 702(अनु०)/तारापुर
प्रेषक,

दिनांक 06/04/2024

ई० विमल कुमार
कार्यपालक अभियन्ता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, खड़गपुर-तारापुर।

सेवा में,

नोडल पदाधिकारी MR 3054
ग्रामीण कार्य विभाग,
बिहार, पटना।

विषय :- New Maintenance Policy 2018 (MR3054) अंतर्गत पथों के निर्माण कार्यों का आवंटन उपलब्ध कराने के संबंध में।

महाशय,

उपर्युक्त विषय के संबंध में कहना है कि New Maintenance Policy 2018 (MR3054) अंतर्गत पथों के निर्माण कार्यों के भुगतान हेतु विहित प्रपत्र में संलग्न विवरणी के अनुसार रु०- 350.65543 राशि की आवश्यकता है।

अतः अनुरोध है कि उक्त राशि का आवंटन उपलब्ध कराया जाय, ताकि संवेदक को भुगतान किया जा सके।

अनु०-यथोक्त।

विश्वासभाजन

ई० विमल कुमार
कार्यपालक अभियन्ता,

06/04/2024

**Office of The Executive Engineer
Rural Works Department
Works Division, Kharagpur-Tarapur**

Requisition Format for Scheme Head - NHR(3054) under Bihar Rural Road Maintenance Policy - 2018 (Initial Rectification and Surface Renewal)

Sl. No.	Package No.	Name of Road	Project ID as per MIS	Administrative Approval/NA Letter No. & Date	Administrative		Agreement Amount		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of RRI (in mm/Km)	Thickness of Bitumen Layer in mm	Value of Bitumen content in Percentage	Previous Total Allocated Amount (in Lakh)	Up-to-date Expenditure as per MIS (in Lakh)	Requisition against work done (in Lakh)	Remarks
					Length (in Km)	Amount (in Lakh)	Initial Rectification with Surface Renewal (in Lakh)	5 Year Routine Maintenance (in Lakh)										
1	RW/NU/CH/230014	Repair of Road Bandipur P.V. D Road To Dhoobai Via Chak Dhoobai	2080380003	1521 08.09.2022	1.720	113.33900	91.87927	18.56811	20MBD/2023-24 01.11.2023	31.07.2024	-	2965	SDBC-25mm Thickness of PCC Layer in 160 mm	SDBC-5.0	0.00000	0.00000	91.87927	Surface Complete
2	RW/NU/CH/230014	Kharagpur-Tarapur(SH) Se Madhura Gaon Hore Bye Bypass Gaon tak via Jamsuna Garh Tila	2080380789	1521 08.09.2022	4.150	321.528	258.77616	48.84455	20MBD/2023-24 11.01.2023	31.07.2024	-	3055	SDBC-25mm Thickness of PCC Layer in 160 mm	SDBC-5.0	0.00000	0.00000	258.77616	PCC Surface Complete
3	RW/NU/CH/AZ30011	LAST-KHARAGPUR JAMUI GAVALI THREE MILE MISSING LNK (TRACKS)	20803802073	1447 28.02.2023	4.220	338.16600	235.94661	51.67956	18MBD/2023-24 10.10.2023	09-07-2024	-		SDBC-25mm Thickness of PCC Layer in 160 mm	SDBC-5.0	165.16262	165.16262	70.78399	Surface Complete
4	RW/NU/CH/AZ30011	LAST-Chara shir manadir to sajan sai sthan (TRACK)	2080380004	1447 28.02.2023	1.550	95.05900	70.19352	16.63903	18MBD/2023-24 10.10.2023	09-07-2024	-		SDBC-25mm Thickness of PCC Layer in 160 mm	SDBC-5.0	49.13546	49.13546	21.05806	Surface Complete

[Signature]
Divisional Account Officer
Rural Works Department
Works Division Kharagpur-Tarapur

[Signature]
Executive Engineer
Rural Works Department
Works Division Kharagpur-Tarapur

EXECUTIVE ENGINEER, WORK DEPARTMENT, WORKS DIVISION ,KHARAGPUR-TARAPUR,(MUNGER)

FORM GFR19 A

(See Government Of India'S Decesion (1) Below Rule 150)

(Form Of Utilization Certificate up To The Month Of Up To April .2024)

(MR New Maintenance Policy 2018)

SL. No.	Name Of Scheme/Purpose	Sanctioned with Date	Sanctioned Amounts(In Lacs-Rs.)	Amount Recived(IN Rs. Lacs)	Particulars
1	Construction of Rural Road & Bridge underMR New Maintenance Policy 2018	Ltr. No. 35 Dt. 13.10.2022 Ltr. No.47 dt 24.11.2022 Ltr. No.04 dt 10.01.2023 Ltr. No.10 dt 27.01.2023 Ltr. No.21 dt 20.02.2023 Ltr. No.33 dt 07.03.2023 Ltr. No.56 dt 28.03.2023 Ltr.No.78 dt 24.05.2023 Ltr.No.85 dt 14.06.2023 Ltr.No.92 dt 28.06.2023 Ltr.No.100 dt 14.07.2023 Ltr.No.106 dt 02.08.2023 Ltr.No.147 dt 01.11.2023 Ltr.No.47 dt 25.03.2024	12324.82256	12324.82256	Certified that out of Rs.12324.82256 Lakh received up to date in Favour of Executive Engineer, RWD, Kharagpur-Tarapur Sum of Rs.12022.28361 Lakh has been Utilized for the Purpose of MR New Maintenance Policy 2018 Program Fund Scheme as given in the margin for Which it was sanctioned and that the balance of Rs. 302.53895 Lakh remaining Untlilized amount at the end of the period Under.

2 Certyified that I have satisfied myself that the condition on which the grants in aid was sanctioned have been duly fulfilled /are being fulfilled And that I have exercised the checks to see that the money was actually utilized for which it was sanctioned.

Huma
06/04/24
Divisional Account Officer
Rural Works Department
Works Division Kharagpur-Tarapur

[Signature]
6-4-24
Executive Engineer
R.W.D. (W) Div, Kharagpur-Tarapur
(Munger)

Name of work : Repair of Road Banshipur P.W.D Road To Dhobai Via Chak
Dhobai

Name of customer : S.B. Engicon Private Limited

(R/R)Rural Road


					Good		Average			Poor					
					< 4000		4001 - 5000			> 5000					
Date	Time	Test No	Distance(m)	Total Distance(m)	BUMP(cm)	Speed(Km/Hr)	U/(mm/Km)	Corrected U/(mm/Km)	IRI	Status	Latitude	Direction	Longitude	Direction†	Remarks
06/04/24	11:31:56	24	100	100	28.0 cm	18.9 Km/Hr	2800.0 mm/Km	2938	3.95	Good	25.1063902	N	86.6694505	E	Normal
06/04/24	11:32:12	24	100	200	25.0 cm	28.5 Km/Hr	2500.0 mm/Km	2647	3.6	Good	25.1057306	N	86.6700702	E	Normal
06/04/24	11:32:30	24	100	300	29.0 cm	20.2 Km/Hr	2900.0 mm/Km	3035	4.07	Good	25.1049101	N	86.6704304	E	Normal
06/04/24	11:33:04	24	100	400	32.0 cm	30.6 Km/Hr	3200.0 mm/Km	3326	4.42	Good	25.1042203	N	86.6608204	E	Normal
06/04/24	11:33:42	24	100	500	30.0 cm	30.5 Km/Hr	3000.0 mm/Km	3132	4.19	Good	25.1039205	N	86.6714803	E	Normal
06/04/24	11:34:00	24	100	600	26.0 cm	25.6 Km/Hr	2600.0 mm/Km	2744	3.72	Good	25.1036301	N	86.6723802	E	Normal
06/04/24	11:34:19	24	100	700	29.0 cm	25.0 Km/Hr	2900.0 mm/Km	3035	4.07	Good	25.1034104	N	86.6734105	E	Normal
06/04/24	11:34:43	24	100	800	31.0 cm	19.6 Km/Hr	3100.0 mm/Km	3229	4.3	Good	25.1032203	N	86.6734101	E	Normal
06/04/24	11:35:18	24	100	900	25.0 cm	10.4 Km/Hr	2500.0 mm/Km	2647	3.6	Good	25.1029706	N	86.6753103	E	Normal
06/04/24	11:35:43	24	100	1000	29.0 cm	13.6 Km/Hr	2900.0 mm/Km	3035	4.07	Good	25.1026404	N	86.6759702	E	Normal
06/04/24	11:35:05	24	100	1100	32.0 cm	17.0 Km/Hr	3200.0 mm/Km	3326	4.42	Good	25.1030701	N	86.6763604	E	Normal
06/04/24	11:36:23	24	100	1200	27.0 cm	19.8 Km/Hr	2700.0 mm/Km	2841	3.84	Good	25.1029302	N	86.6776101	E	Normal
06/04/24	11:36:45	24	100	1300	33.0 cm	23.8 Km/Hr	3300.0 mm/Km	3423	4.53	Good	25.1031105	N	86.6785905	E	Normal
06/04/24	11:37:08	24	100	1400	29.0 cm	22.8 Km/Hr	2900.0 mm/Km	3035	4.07	Good	25.1034603	N	86.6794403	E	Normal
06/04/24	11:37:29	24	100	1500	26.0 cm	23.8 Km/Hr	2600.0 mm/Km	2744	3.72	Good	25.1033106	N	86.6804102	E	Normal
06/04/24	11:37:51	24	100	1600	30.0 cm	18.9 Km/Hr	3000.0 mm/Km	3132	4.19	Good	25.1032201	N	86.6810306	E	Normal
06/04/24	11:38:15	24	100	1700	33.0 cm	28.2 Km/Hr	3300.0 mm/Km	3423	4.53	Good	25.1035502	N	86.6822301	E	Normal

06/04/24

06/04/24

06/04/24

Name of Customer: S.B. Enterprises Private Limited, Machine no: 19213, Road: Repair of Road Banashpur P.W.D Road To Dhobai Via Chak Dhobai, Date: 06-04-24, Section No: 24, Equation: $Y=0.969X+224.9$



[Signature]
06/04/24

[Signature]
06/04/24
JL

[Signature]
06/04/24
RE