

2nd year Maintenance Bill

48

Sch. XLV-Form No. 134

[illegible]

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	<u>Abstract of cost.</u>				
1. Restoration of rain cuts with soil masonry.					
do do all comp.					
Qty vide TMB page No-48.					
109.35m ² @ RS 379.59/-					41508=
2. Maintenance of Earthen shoulder.					
do do all comp.					
Qty vide TMB page No-49.					
603.70m ² @ RS 56.81/-					34296=
3. Patch Repair over Bituminous surface.					
do do all comp.					
Qty vide TMB page No-49					
84.35m ² @ RS 287.40/-					24251=
4. Maintenance of C/P work (H.C. culvert)					
do do all comp.					
Qty vide TMB page No-49.					
05 Nos @ RS 1102.50/-					5514=
5. Maintenance of C/P work (slab culvert)					
do do all comp.					
Qty vide TMB page No-49.					
02 Nos @ RS 2273.47/-					4547=
6. Maintenance of Road Sign board.					
do do all comp.					
Qty vide TMB page No-50.					
0.28km @ RS 1054.28/-					295=

Continuation
RS-110411=0

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
7. Maintenance of 200m and Km stone					
do do all comp					
Qty vide TMB page No-50.					
0.35 Km @ RS 614.10/-					21520
8. White Washing of parapet wall of CD work					
do do all comp					
Qty vide TMB page No-50					
105.0m ² @ RS 16.03/-					16832
				RS	1123092
Less Below 0.51%					57320
Total Rs					1117362
SPD					
21.02.2024					
J-E					