

5th year maintenance

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
New: Construction of Road from Hanuman Chowk to yadav Tola.					
Agency- Sri. Rishikesh Rangan					
Agenda - 27 (S.B.S) / 2017-18					
D.O.W - 28.03.17					
Actual D.O.C - 15.03.2018					
Rate - 10 % Below					

① Restoration of Raincuts -

P.H.S →	8	2.10	0.85	0.35	4.99
L.H.S →	10	1.75	0.90	0.35	5.51
R.H.S →	7	1.60	0.95	0.30	3.19
L.H.S →	12	2.00	0.80	0.30	5.76
R.H.S →	15	2.15	0.80	0.30	7.74

L.H.S →	17	1.90	0.90	0.35	10.17
					37.36 m ²

② Maintenance of earthen

Shoulder

L.H.S	12	4.00	0.15		26.40
	10	3.50	0.60		21.00
	15	5.00	0.50		37.50
R.H.S	11	6.25	0.70		48.12
	16	4.00	0.65		41.60
	11	3.00	0.75		24.75
	4	2.50	0.65		6.50
					205.87 m ²

③ Maintenance of Hump pipe

