

3rd year maintenance Bill

Sch. XLV-Form No. 134

57

Particulars	Details of actual measurement				Contents of area
	No.	L	B	D	
Name of work - Maintenance of Road					
From Pachaura RWD Road to Alipur.					
Agency - Sri Pappu Singh					
App. No - 12-MBD/2017-18					
Actual date of completion - 05/08/2020					

RECORD ENTRY

① Restoration of rain cuts

-----20-----20-----E ₁					
	68	0.80	1.20	0.30	19.584 m ³
	62	0.95	1.20	0.30	21.204 m ³
	56	1.15	1.20	0.30	23.184 m ³
	42	1.35	1.20	0.30	20.412 m ³
	36	1.65	1.20	0.30	21.384 m ³
	18	1.90	1.10	0.30	11.286 m ³
	22	2.25	1.10	0.30	16.335 m ³
	12	2.55	1.10	0.30	10.098 m ³
	6	2.95	1.00	0.30	5.310 m ³
					148.797 m ³

② Maintenance of Earthen shoulder

-----20-----20-----E ₁					
	2	36	3.25	1.20	280.80 m ²
	2	18	4.60	1.20	198.72 m ²
	2	12	6.40	1.10	168.96 m ²
	2	14	5.75	1.10	177.10 m ²
					825.58 m ²

③ Repair of Pot holes with B.H.

-----20-----20-----E ₁					
	26	0.60	0.60	0.075	0.702 m ³
	22	0.80	0.70	0.075	0.924 m ³
	20	0.90	0.75	0.075	1.013 m ³
	16	0.90	0.90	0.075	0.972 m ³

Continuation

3.611 m³



Particulars	Details of actual measurement				Contents of area
	No	L	B	D	
	B.F.				3.6114 ³
	12x	1.15x	6.90x	0.075	0.9324 ³
	6x	1.45x	1.25x	0.075	1.0884 ³
	6x	1.75x	1.15x	0.075	0.9064 ³
	4x	1.90x	1.45x	0.075	0.8274 ³
	4x	2.85x	1.75x	0.075	1.4964 ³
	1x	4.42x	1.90x	0.075	0.6304 ³
					9.494 ³

④ Patch repair over Pot holes

	26x	0.60x	0.60		9.364 ²
	22x	0.80x	0.70		12.324 ²
	20x	0.90x	0.75		13.504 ²
	16x	0.90x	0.90		12.964 ²
	12x	1.15x	0.90		12.424 ²
	8x	1.45x	1.25		14.504 ²
	6x	1.75x	1.15		12.0754 ²
	4x	1.90x	1.45		11.024 ²
	4x	2.85x	1.75		19.954 ²
	1x	4.42x	1.90		8.404 ²
					126.5054 ²

⑤ Patch repair over B.T. Surface

	14x	1.20x	0.90		15.124 ²
	12x	1.35x	1.25		26.254 ²
	8x	2.40x	1.75		33.604 ²
	4x	2.90x	1.90		22.044 ²
	6x	2.55x	1.90		29.074 ²
	6x	2.55x	1.90		29.074 ²
					126.084 ²

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L	B	D	
<u>ABSTRACT OF COST</u>					
① Restoration of rain cuts					
-----do-----	-----do-----	-----do-----	-----do-----	-----do-----	-----do-----
148.793 m ²	VTMBP-53				
	@ Rs 327.36/m ²				Rs 48710.00
② Maintenance of Eastern shoulder					
-----do-----	-----do-----	-----do-----	-----do-----	-----do-----	-----do-----
825.58 m ²	VTMBP-53				
	@ Rs 49.55/m ²				Rs 40907.00
③ Repair of Pot holes with B.M.					
-----do-----	-----do-----	-----do-----	-----do-----	-----do-----	-----do-----
9.49 m ³	VTMBP-53				
	@ Rs 9213.32/m ³				Rs 87455.00
④ Patch repair over Pot holes					
-----do-----	-----do-----	-----do-----	-----do-----	-----do-----	-----do-----
126.505 m ²	VTMBP-58				
	@ Rs 250.57/m ²				Rs 31698.00
⑤ Patch repair over B.M. surface					
-----do-----	-----do-----	-----do-----	-----do-----	-----do-----	-----do-----
126.08 m ²	VTMBP-58				
	@ Rs 262.23/m ²				Rs 33062.00
⑥ Maintenance of H.P. Culvert					
-----do-----	-----do-----	-----do-----	-----do-----	-----do-----	-----do-----
7.00 H.M.	VTMBP-59				
	@ Rs 949.32/H.M.				Rs 3797.00
⑦ Maintenance of Road sign					
-----do-----	-----do-----	-----do-----	-----do-----	-----do-----	-----do-----
0.320 Km	VTMBP-59				
	@ Rs 935.04/Km				Rs 295.20
					Rs 24592.00

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L	B	D	
① P.					Rs 245924.00
② Maintenance of K.H.P.H. stone					
.....20		20	20	20	
0.380 K.H.		VTHBP-57			
		Rs 563.83/KM		Rs	2132.00
③ Cutting of branches of trees					
.....20		20	20	20	
4.00 Nos.		VTHBP-57			
		Rs 85.63/No		Rs	343.20
④ White washing on parapet walls					
.....20		20	20	20	
82.56 m ²		VTHBP-57			
		Rs 13.97/m ²		Rs	1155.20
				Rs	247635.20
less 10% Balance as per Agt.				Rs	243642.00

C.B.P

Total

Rs 222872.00

~~Ref~~
 04.06.24

6/9/17
 A.E

~~Ref~~
 06.08.23

A.E

J.F