

है कि नाली में नाली नदी
100 फुट है जिस की गहराई
नौका या हाथी कमियां आती
हैं। निमा, बापू का पुत्र
मधुन के पदनाम से लिखा
गया है

Aug 4 18.7.19
कार्यपालक अभियन्ता
प्रादेशिक कार्य विभाग
कृष्ण प्रमण्डल, पकडीदयाल
18.7.19

Schedule XLV Form No.-134

R.W.D. PAKARIDAYAL DIVISION
R.W.D. MADHUDAN SUB-DIVISION

MEASUREMENT BOOK

704

Name of officer _____

Date of first entry _____

Date of last entry _____

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	3rd year Maintenance				
N/w:→	Maintenance of road from				
	Talampur to Baki Tikam.				
	MMGSY - NDB - BRICA.				
Agency:→	M/s. Uttar Bihar const. co.				
	Pro- Sanjay Kumar.				
Agreement no:→	12 SBD/2019-20				
D.O.S→	03.09.2019				
D.O.C→	26.04.2021				
D.O.Y→	07.05.2024				
1.)	Restoration of raincuts				
	do- all comp. job.				
	5x	30x	2x	1.125x	0.3005 = 101.2543
	1x	28x	2x	1.125x	0.300 = 18.90 "
					120.1543
2.)	Making up of Berms				
	do- all comp. job.				
	5x	30x	2x	1.125x	337.5042
	3x	30x	2x	1.125x	202.50 "
	1x	15x	2x	1.125x	33.75 "
					573.7542
3.)	Repairs of Pot holes filled				
	with 75MM BM do- all comp. job.				
	6x	2.10x	1.60x	0.075x	1.51243
	8x	1.80x	1.10x	0.075x	1.188 "
				C.O =	2.70043

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
				B.F =	2.700 M ³
	11X	1.50X	1.50X	0.075 =	1.856 "
	2X	3.00X	2.10X	0.075 =	0.945 "
	5X	2.90X	1.00X	0.075 =	1.088 "
					6.589 M ³
4.) Patch repair over pot holes with 20mm Primix Carpet - do all comp.					
	6X	2.50X	1.50 =		22.50 M ²
	12X	1.00X	0.90 =		10.80 "
	9X	1.90X	1.10 =		18.81 "
	7X	3.00X	1.60 =		33.60 "
	2X	2.00X	0.50 =		2.00 "
					87.71 M ²
5.) Patch repair over bituminous surface with 20mm do all comp.					
	6X	2.10X	1.60 =		20.16 M ²
	8X	1.80X	1.10 =		15.84 "
	11X	1.50X	1.50 =		24.75 "
	2X	3.00X	2.10 =		12.60 "
	5X	2.90X	1.00 =		14.50 "
					87.85 M ²
6.) Maintenance of C.D works					
					do - all comp. job → 4.000 M ³
7.) Maintenance of road sign					
					do - all comp. job → 0.20 KM.

Continuation

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
ABSTRACT OF COST.					
1.) Restoration of raincoats					
- do - all comp. job.					
120.15 M ³ vide TMB P-61					
@ Rs. 378.32/M ³					Rs. 45,455.00
2.) Making up Bormp					
- do - all comp. job.					
573.75 M ² vide TMB P-61					
@ Rs. 58.42/M ²					Rs. 33,518.00
3.) Repairs of pot holes filled					
with 75mm B.M. - do - all comp. job.					
6.589 M ³ vide TMB P-62					
@ Rs. 11141.79/M ³					Rs. 73,413.00
4.) Patch repair over pot holes					
with 20mm P.M.C. - do - all comp. job.					
87.71 M ² vide TMB P-62					
@ Rs. 305.42/M ²					Rs. 26,788.00
5.) Patch repair over bituminous surface with 20mm - do - all comp. job.					
87.85 M ² vide TMB P-62					
@ Rs. 322.31/M ²					Rs. 28,315.00
6.) Maint ⁿ of C.D works					
- do - all comp. job.					
4.00 nos. vide TMB P-62					
@ Rs. 1109.67 each					Rs. 4439.00
C.D.					Rs. 2,11,928.00

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
			B.F.		Rs 2,11,928=00
7.) Maint ⁿ of road sign					
—do— all comp. job.					
0.20 KM vide TMB P-62					Rs 32,312=00
@Rs. 1066.50/KM					Rs 213=00
8.) Maint ⁿ of 200m and KM					
stone —do— all comp. job.					
0.30 KM vide TMB P-63					
@Rs. 651.05/KM					Rs 195=00
9.) Cutting of branches of					
trees and shrubs —do— all					
comp. job.					
4.00 nos vide TMB P-63					
@Rs. 105.39 each					Rs 422=00
10.) Cutting of shrubs					
from roadway —do— all					
comp. job.					
17.00 nos vide TMB P-63					
@Rs. 6.47 each					Rs 110=00
11.) Trimming of grass and					
weeds —do— all comp. job.					
9.68 M ² vide TMB P-63					
@Rs. 2.16/M ²					Rs 21=00
12.) White washing of parapet					
wall —do— all comp. job.					
103.92 M ² vide TMB P-63					Rs 102=00
@Rs. 16.54/M ²					Rs 1739=00
			C.O.		Rs 2,14,628=00

Continuation

	material	statement
i)	E/W	= 176.176 M ³
ii)	stone Metal	= 4.74 M ³
iii)	Sand	= 1.053 M ³
iv)	Bitumen Emulsion (RS-1)	= 0.043 T
v)	Bitumen (S-90)	= 0.374 M.T
Assn 07/05/24 J.E		

Continuation