

Даржамак-Толу Болдаришга то 1028 (5с)

Schedule XLY-Form No. 134

E. R. U. D. (U) **DIVISION**
E. H. Y. H.

A. E. R. U. D. (U) **SUB-DIVISION**
TANKUPPA

MEASUREMENT BOOK

Chandam Khumar

2950

(These four lines should be repeated at the commencement of the measurement relating to each work)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of Work - Construction of Road From Darjia chak to Beldanigha to Long under MMHSY (SC)					
Name of Agency - Chandan Kumar, At- Paroria, Sohaiapur, Manpur, Distt - Gaya					
Document No. - 66/MMHSY/SC/SBD/pw,					
Date of commencement - 16.09.20					
Date of completion - 15.09.21					
Date of measurement - 22.2.22					
Description of Bench mark & Reference Pillars -- etc					
Reference & Workshop near road -- 1.014 KM.					
2 Surveyed Pillars / Boundary					

1st year Part-B
year Maintenance Bill

64

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - Construction					
of Road from					
Dargiya Chack to 1019					
Beldara Bigha to 1028					
Under MMGSY (SC)					
Agency - Chandan Kumar					
At - Paroria, Sohanpur					
Meharpur, Dist - Gaya					
Agreement no - 66/MMGSY/SC/SBD					
2020-2021					
Date of commencement -					
16.06.2020					
Date of Completion - 15.09.2021					
Master copy work					
Date of actual completion					
of Part A - 25.08.2023					
(1.) Restoration of					
Rain cuts / Berms.					
— do — do —					
5X 4X 10.0X0.60X0.30 = 36.00 m ³					
2X 15.0X0.60X0.30 = 5.40 m ³					
1X 15.0X0.70X0.30 = 3.15 m ³					
TOTAL = 44.55 m ³					

Continuation

1st year
69

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration of saw cuts / Bams- do do					
44.55 m ³ qty TMS Page (64)					
@ ₹ 404.06/m ³ — ₹ 18001=00					
② Making up Bams/ Shoulder do do					
247.60 m ³ qty TMS Page (65)					
@ ₹ 60.28/m ³ — ₹ 14925=00					
③ Patch Repair of Paf holes with 20mm Prestressed concrete do do					
20.55 m ³ qty TMS Page (65)					
@ ₹ 237.96/m ³ — ₹ 4891=00					
④ Patch repair over bituminous surface 20mm wide seal surface do do					
22.55 m ² qty TMS Page (65)					
@ ₹ 255.32/m ² — ₹ 5758=00					

Continuation

Continuation