

3rd Year Maint. Bill

Sch. XLV-Form No. 134 **4J**

Particulars	Details of actual measurement				Contents of area
	No.	L	B	D	
N/w-Maint. of Road from OLD G.T. Road to Dayal Bigha Mandir					
Agency - Badliwam Singh					
Agg. No -	49/SBD/2020-21				
Date of start -	10-06-2020				
Actual date of comp -	27-5-2021				
Details					
① Restoration of Paveds -					
4x8	8	1.30	0.30		12.48m ²
6x5	5	1.40	0.30		13.60m ²
8x6	20	1.50	0.30		22.32m ²
10x7	30	1.45	0.30		31.75m ²
5x4	50	1.20	0.30		8.10m ²
					88.263m ²

② Making up of Berms/Shoulder -					
2x8	10	1.20			192m ²
2x10	12	1.25			300m ²
					492m ²
③ Repair of Potholes 75mm BM -					
2x	1.20	0.5			1.20m ³
4x	1.50	0.5			3.00m ³
					4.20m ³

④ Put repair over potholes 20mm mix s.s. & d.s. -					
5x	1.8	2.1			18.9m ²
9x	2.3	1.50			24.15m ²
4x	2.40	1.35			12.96m ²

OST

Particulars	Details of actual measurement			Contents of area
	No.	L	B	D
Nhw- Maint. of Road from Old G.T. Road to Dayal bigha Mandir				
Agency - Badliyam Singh				
Agg. No - 49/SBD/2020-21				
Dated of start - 10-06-2020				
Actual date of comp - 27-05-2021				
Details				

- ① Restoration of Rainwater
Qty vide TRIB P.No - (40)
I.No ① 88.263m² @ 394-20 = 34783.20
- ② Making up of Boring/Show/deg
Qty vide TRIB P.No - (40)
I.No ② 492m² @ 59.17 = 29112.20
- ③ Repair of pot holes 75mm BM

- Qty vide TRIB P.No - (40)
I.No ③ 4.20m³ @ 9834.42 = 41305.20
- ④ Pot repair over bituminous
20mm mix sealed
Qty vide TRIB P.No - (40)
I.No ④ 56.01m² @ 245.15 = 13731.20
- ⑤ Pot repair over bituminous
20mm mix sealed
Qty vide TRIB P.No - (41)
I.No ⑤ 56.242m² @ 256.43 = 14422.20
- ⑥ Maint of H.P.C
- Qty vide TRIB P.No - (41)
I.No ⑥ 2. NO 1130.67 = 2261.20
- ⑦ Maint of Road signs
Qty vide TRIB P.No -

