

M. Muesy

SC. 311247 नदी

(132)

Schedule XLV-Form No.-134

Const. OF Road & CD WORK FROM S0170 PWD
Sinaila Road to Kewat tola Arithana Puth

DIVISION

Agreement NO - 118/SBD/18-20 dt 30/5/19

SUB-DIVISION

Agreement route - 97,00,359-0

440
30/5/19.

MEASUREMENT BOOK

mls excellent

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Abstract of cost					
(1) Restoration of rain cists with soil:-					
101.58 m ³ Q.V.T.M.B.P. (54)					
@ 378.32/m ³ - RS -					38434.00
(2) Making up of Bonny shoulder:-					
252.22 m ² Q.V.T.M.B.P. (55)					
@ 58.18/m ² - RS -					14674.00
(3) Repair of pot holes filled with 75mm WBM:-					
51.71 m ² Q.V.T.M.B.P. (56)					
@ 356.54/m ² - RS -					18437.00
(4) Patch repair over pot holes with 20mm:-					
51.71 m ² Q.V.T.M.B.P. (56)					
@ 292.98/m ² - RS -					15150.00
(5) Patch repair over bituminous surface with 20mm m/c seal:-					
51.91 m ² Q.V.T.M.B.P. (57)					
@ 229.84/m ² - RS -					11931.00
(6) Maintenance of T.P. culverts:-					
2.00 Nos Q.V.T.M.B.P. (58)					
@ 1109.67/each - RS -					2219.00
(7) Maintenance of Road					
Singer:-					

Continuation

Continuation

Scanned with CamScanner