

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Nfwr. Sirghyahi Mr Boto ran Roy					
ke gher to Sirghyahi yadav.					
Total.					
Agency. Chhenshyam Roy					
Agc. No. 31 (S.B.D.)/2021-22					
D.O.W- 03.07.2021					
Agency D.O- 25.03.2022					
① Restoration of Rain Guts —					
6 x 3.15 x 0.90 x 0.35 = 5.95					
4 x 5.20 x 0.75 x 0.30 = 4.68					
7 x 4.15 x 0.80 x 0.30 = 6.97					
5 x 6.00 x 0.85 x 0.35 = 8.92					
8 x 2.10 x 0.70 x 0.30 = 3.53					

30.05 m³

② Masonry work of Beam —					
8 x 3.00 x 0.90 —					21.60
15 x 5.00 x 0.80 —					60.00
10 x 4.00 x 0.85 —					38.25
12 x 6.00 x 0.90 —					64.80
20 x 4.00 x 0.85 —					68.00
7 x 2.50 x 0.70 —					12.25
					<u>264.90 m²</u>

③ Patch repair, on already filled					
with premix cement					
put					
3 x 2.75 x 1.70 —					14.02 m ²

④ Maintenance of humetite

[illegible]