

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1. Name of work:- Baraini pul to masher Toli hotel hu pipul tree.					
2. Agency:- Vijay Kumar Singh					
3. Date of commencement:- 21.1.21					
4. Date of completion:- 20.10.21					
5. Agreement NO:- 49-SAD/20-21					

1) Repair of concrete pavement

— do —

$$4 \times 1.2 \times 1.05 = 5.04 \text{ m}^2$$

$$5 \times 1.50 \times 0.90 = 6.75 \text{ m}^2$$

$$2 \times 0.80 \times 0.75 = 1.20 \text{ m}^2$$

$$4 \times 1.00 \times 0.95 = 3.80 \text{ m}^2$$

$$= 16.79 \text{ m}^2$$

$$\text{Limit} \rightarrow 16.41 \text{ m}^2$$

2) Repair of old
Joint Sealant

— do —

$$10 \times 30.00 = 300.00 \text{ m}$$

$$12 \times 30.00 = 360.00 \text{ m}$$

$$= 660.00 \text{ m}$$

Continuation

$$\text{Limit} \rightarrow 656.25 \text{ m}$$

Continuation