

2nd year Maintenance

Name of work: - Naya Faltapur P.H. to Bandhuan
 Agency: - Shri K. K. K. K.
 Sch. XLV - Norm No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1. Restoration of rainwater /					
Bearers -					
Complete all Jobs					
	2	30m	1.25	0.30	22.50
	2	30m	1.25	0.30	22.50
	3	30m	1.25	0.30	33.750
					67.50 m ³
					78.75
2. making of Bearers / sho-					
ulders -					
Complete all Jobs					
	1	5	30m	1.25	187.50
	1	5	30m	1.25	187.50
	3	30m	1.25		112.50
					486
					487.50 m ²
3. Patch repair over					
Pot (Bituminous surface)					
holes with 20mm Premix -					
Complete all Jobs					
	2	5.5	1.25		13.75
	2	10.6	1.25		26.50
	2	6.0	1.25		15.0
	2	1.50	1.25		3.75
					59.0 m ²

Continuation

Scanned with CamScanner