

# 3rd year maint. bill

40

Sch. XLV-Form No. 134

| Particulars                          | Details of actual measurement |    |    |    | Contents of area |
|--------------------------------------|-------------------------------|----|----|----|------------------|
|                                      | No.                           | L. | B. | D. |                  |
| Name of work - maint. of road        |                               |    |    |    |                  |
| Gram Mansur miya ke                  |                               |    |    |    |                  |
| Karnad to Sabbehari pagchim          |                               |    |    |    |                  |
| to/a.                                |                               |    |    |    |                  |
| Agency - Shashikant Singh.           |                               |    |    |    |                  |
| Agreement no - 47/SBO/2020-21        |                               |    |    |    |                  |
| Date of work order - 17/09/2020      |                               |    |    |    |                  |
| Actual Date of completion - 16/09/21 |                               |    |    |    |                  |
| Date of measurement - 12/09/23       |                               |    |    |    |                  |
|                                      |                               |    |    |    |                  |
|                                      |                               |    |    |    |                  |
|                                      |                               |    |    |    |                  |
|                                      |                               |    |    |    |                  |
|                                      |                               |    |    |    |                  |

(1) Restoration of raincuts.

|                                          |     |                       |
|------------------------------------------|-----|-----------------------|
| $5 \times 6.00 \times 0.85 \times 0.65$  | $=$ | 16.57                 |
| $6 \times 4.50 \times 0.90 \times 0.80$  | $=$ | 19.44                 |
| $7 \times 5.00 \times 1.00 \times 0.95$  | $=$ | 33.25                 |
| $6 \times 4.00 \times 0.80 \times 0.85$  | $=$ | 16.32                 |
| $4 \times 5.00 \times 0.90 \times 0.60$  | $=$ | 10.80                 |
| $6 \times 3.50 \times 0.80 \times 0.30$  | $=$ | 5.04                  |
| $10 \times 4.00 \times 0.70 \times 0.50$ | $=$ | 14.00                 |
| $7 \times 5.39 \times 0.60 \times 0.85$  | $=$ | 19.24                 |
|                                          | $=$ | 134.66 m <sup>3</sup> |

(2) Making up of berms/  
shoulder.

|                              |     |       |
|------------------------------|-----|-------|
| $10 \times 3.00 \times 0.90$ | $=$ | 27.00 |
|------------------------------|-----|-------|

Continuation

| Particulars                                     | Details of actual measurement |    |    |    | Contents of area |
|-------------------------------------------------|-------------------------------|----|----|----|------------------|
|                                                 | No.                           | L. | B. | D. |                  |
| <u>Abstract Qty. of Cast</u>                    |                               |    |    |    |                  |
| (1) Restoration of Reincluds.                   |                               |    |    |    |                  |
| vide qty. page no-                              |                               |    |    |    |                  |
| 134.66 m <sup>3</sup> @ 404.06 / m <sup>3</sup> |                               |    |    | =  | 54411.00         |
| (2) Making up of berms /                        |                               |    |    |    |                  |
| shoulder.                                       |                               |    |    |    |                  |
| vide qty. page no-41                            |                               |    |    |    |                  |
| 1047.38 m <sup>2</sup> @ 60.28 / m <sup>2</sup> |                               |    |    | =  | 63136.00         |
| (3) Repair of pot holes                         |                               |    |    |    |                  |
| Gilled 75mm.                                    |                               |    |    |    |                  |
| vide Qty. page no-41                            |                               |    |    |    |                  |
| 133.54 m <sup>3</sup> @ 371.21 / m <sup>3</sup> |                               |    |    | =  | 49571.00         |
| (4) patch repair on already                     |                               |    |    |    |                  |
| Gilled pot holes 75mm.                          |                               |    |    |    |                  |
| vide qty. page no-41                            |                               |    |    |    |                  |
| 133.56 m <sup>2</sup> @ 257.50 / m <sup>2</sup> |                               |    |    | =  | 34392.00         |
| (5) Maint. of H.P Culvert.                      |                               |    |    |    |                  |
| vide qty. page no-42                            |                               |    |    |    |                  |
| 2.00 nos @ 1166.58 / nos                        |                               |    |    | =  | 2333.00          |
| (6) Maint. of 200m and                          |                               |    |    |    |                  |
| km Stone.                                       |                               |    |    |    |                  |
| vide qty. page no-42                            |                               |    |    |    |                  |
| 0.48 km @ 583.43 / km                           |                               |    |    | =  | 280.00           |

Continuation