

कार्यपालक अभियंता का कार्यालय,
ग्रामीण कार्य विभाग, कार्य प्रमण्डल, रजौली।

Mob No.: 8986915851.

Email I.D.: - eerwdrajauli@gmail.com

पत्रांक... 1639 (अनु.)

रजौली / दिनांक 28/11/24

प्रेषक,

ई0 अरविन्द कुमार,
कार्यपालक अभियंता।

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव,
बिहार ग्रामीण पथ विकास अभिकरण, पटना।


विषय :- नई अनुरक्षण नीति-2018 योजनान्तर्गत आवंटित राशि का उपयोगिता प्रमाण पत्र तथा आवंटन
अधियाचना के संबंध में।

महाशय,

उपर्युक्त विषय के संबंध में कहना है, कि इस प्रमंडल के अधीन नई अनुरक्षण नीति-2018 योजनान्तर्गत
पथों में चल रहे कार्य के भुगतान हेतु विहित प्रपत्र में माँग पत्र एवं उपयोगिता प्रमाण पत्र संलग्न करते हुए आग्रह
है, कि आवंटन उपलब्ध कराने की कृपा की जाय ताकि कराये गए कार्यों का भुगतान किया जा सके।

अनु० :- यथोक्त।

विश्वास-भाजन,


28.11.24

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, रजौली।


28/11/24

Requisition for Scheme Head :- MR (3054) under Bihar Rural Road Maintenance Policy 2018
(Initial Rectification and Surface Renewal)

Name of Works Division: RWD (W) Division, Rajauli

Name of Works Division: RWD (M) Division, Rajasul																			
Sl. No	Package No.	Name Of Road	Project Id as per MIS	Administrative Approval (AA) Letter No- & Date	Administrative Approval (AA)		Agreement Amount		Agreement No- & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/Km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen content in percentage	Previous Total allotted Amount (in Lakh)	upto date expenditure as per MIS (in Lakh)	Requisition against work done (in lakh)	Remarks	
					Length (in km)	Amount (in lakh)	Initial Rectification with surface Renewal (in lakh)	5 years routine Maintenance (in Lakh)											
B	RM/NA/RAJ/24/0001				LT 6120/04.12.23	8.200	266.74000	168.03251	69.29150	03-MR-3054/MBD/2024-25	28.05.2025	-	3026	25	5.00	0.00000	0.00000	161.00000	On-Going
	Repura - Bairat Shahwajpur (Bairat)	10502702054	1.890	89.53000		57.87828	21.88320	-	2756			25	5.00	55.00000	55.00000	0.50426	Completed		
	Altari - Paroria	10502702028	3.891	175.07000		112.83282	42.84065	-	3060			25	5.00	107.00000	107.00000	3.91249	Completed		
B	L090-LAKHAURA TO DHANGAWAN (TRACK20)				10502702189														
G. Total						6.200	531.34000	338.74361	134.01535	-	-	-	-	-	5	162.00000	162.00000	165.41675	

In Word One Crore Sixty Five Lakh Forty One Thousand Six Hundred Seventy Five only

Executive Engineer,
Rural Works Department,
Works Division- Rajauli

28/11/24

28/11/24

FORM GFR 19-A

(See Government of India's Decision (1) below Rule 150)
Form of Utilization Certificate up to the Month of **21-NOVEMBER-2024**.

S. No	Name of Scheme	Sanction No. & Date with Amount (In Rs.lacs)	Amount Received (in Rs.Lacs)	Decrease (in Lacs)	Particulars
1	Bihar Rural Roads New Maint. Policy 2018	As on 31-MARCH-2024	7593.00583	207.13771	Certified that out of Rs. 8396.35218 Lakh received upto the Financial Year 2024-25 (21-NOVEMBER-24) in favour of Executive Engineer, RWD (W) Division, Rajauli, Bihar out of which a sum of Rs. 8150.48517 Lakh has been utilized for the purpose of New Maintenance Policy 2018 Under MR3054 Scheme as given in the margin for which it was sanctioned and Rs. 230.81214 has been surrendered and that the balance of Rs. 15.05487 Lacs remaining unutilized at the end of the said period.
2		Lt. 69 Dt 06.05.24	302.02318	23.67443	
		Lt. 72 Dt 03.06.24	8.94202		
		Lt. 74 Dt 03.06.24	23.05773		
		Lt. 76 Dt 11.06.24	28.03576		
		Lt. 79 Dt 19.06.24	126.36000		
		Lt. 82 Dt 28.06.24	126.26290		
		Lt. 85 Dt 24.07.24	8.81562		
		Lt. 105 Dt 08.10.24	17.84914		
		Lt. 122 Dt 20.11.24	162.00000		
			8396.35218	230.81214	

8165.54004

2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercised :-

- Works have been supervised by Executive Engineers/Superintending Engineer.
- Periodic inspection has been conducted by Executive Engineer/Superintending Engineer.
- Construction materials have been tested.
- Measurements have been recorded in the MBs and test check conducted by the Assistant.
- All other codal formalities have been observed.

Physical Progress achieved :-

- Construction of Road Works
- Construction of CD Works


Executive Engineer,
Rural Works Department,
Works Division, Rajauli.


21/11/24


21/11/24


Name of Contractor- Sanjay Kumar										Name of Road- Akari - Paroria									
Date	Time	Section No.	Length in km	Bumpup in mm	Speed	OR	IRI	Latitude	Longitude	F.vent	Batch No- R/M/N/A/R/A/J/24/0001								
05/11/24	11:26:9	50	0.1	670	10.1	2700	6.54	24.77047	85.35586	Normal	Y = 0 * X ^ 2 + 0.854 * X - 376.5								
05/11/24	11:27:0	50	0.1	460	10.1	2600	4.72	24.7703	85.35673	Normal	X = 16667								
05/11/24	11:27:19	50	0.1	780	20.2	2800	8.61	24.77	85.35771	Normal	Y = 14610								
05/11/24	11:27:19	50	0.1	670	10.1	2700	7.26	24.76986	85.35865	Normal									
05/11/24	11:28:0	50	0.1	450	20.2	2500	9.98	24.7696	85.35913	Normal	(R) RURAL ROAD								
05/11/24	11:28:0	50	0.1	940	20.2	2400	6.08	24.76941	85.36056	Normal	Good								
05/11/24	11:28:30	50	0.1	990	10.1	2200	7.54	24.76945	85.3615	Normal	Average								
05/11/24	11:29:0	50	0.1	850	10.1	2500	9.26	24.76935	85.36242	Normal	<4000								
05/11/24	11:29:5	50	0.1	890	20.2	2900	9.63	24.76937	85.3634	Normal	4001-5000								
05/11/24	11:29:5	50	0.1	790	20.2	2700	8.7	24.76942	85.36431	Normal	>5001								
05/11/24	11:30:16	50	0.1	760	10.1	2600	8.42	24.76992	85.36515	Normal									
05/11/24	11:30:16	50	0.1	780	10.1	2800	8.61	24.7704	85.36594	Normal									
05/11/24	11:30:16	50	0.1	440	30.3	2400	5.36	24.77091	85.36665	Normal									
05/11/24	11:30:16	50	0.1	730	20.2	2300	8.14	24.77148	85.36749	Normal									
05/11/24	11:30:51	50	0.1	650	20.2	2500	7.39	24.7723	85.36786	Normal									
05/11/24	11:31:0	50	0.1	670	30.3	2700	7.57	24.77294	85.36854	Normal									
05/11/24	11:31:0	50	0.1	590	30.3	2900	6.81	24.77338	85.36934	Normal									
05/11/24	11:31:26	50	0.1	570	20.2	2700	6.62	24.77383	85.37019	Normal									
05/11/24	11:37:16	50	0.09	50	21.2	2667	5.23	24.78232	85.37652	Normal									
Total		1.890	12730.00	344.400	49567.00	52360.00													
Average			670.00	18.13	2608.79	2755.79													

Kumbar
06/11/24
CE

ABJ
6/11/24
AF

26.11.24
ECE

File E:\Maintenance Bump Data of Rajauli\Sanjay berrull 05.10.2024\0511202455.Xls, Section No. 50, Egn
 Name of Customer : Sanjay Kumar, Name of Work/ Road : Akari- paroria, Lab Job number : 50



Kamlesh
 06/11/24
 SE

AB-hg
 6/11/24
 AF

P
 06.11.24
 EE

Schedule XLV-Form No. 134

M.R

Name of Road— Akelli To Pataxia

SANJAY KUMAR
BARUA

DIVISION

खतिय सुडाक

SUB-DIVISION

अथवा ११
अथवा १२

M.B.No—(1373)

MEASUREMENT BOOK



1.

Name of work -

Situation of work -

Agency by which work is executed -

Date of measurement -

No. and date of agreement.

(These four lines should be repeated at the commencement of the measurements relating to each work).

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/Work -	Const. of Road form.				
Alcasi	to parori 9.				
Agency -	Sri Sanjay Kumar.				
Agreement -	Rwa Rajmala/03M/R-3054/23-24				
Date of start -	29/08/2024				
Date of Completion -	06/11/2024				
	Measurement				
	Records entry				

(1/1) clearing & grubbing Road					
land (By manual means) and					
2x10x30	x	1.0	=	600.00m ²	
2x10x30	x	1.0	=	600.00m ²	
2x10x30	x	1.0	=	600.00m ²	
2x10x30	x	1.0	=	600.00m ²	
2x10x30	x	1.0	=	600.00m ²	
2x10x30	x	1.0	=	600.00m ²	
2x3x30	x	1.0	=	180.00m ²	
			=	3780.00m ²	



ABSTRACT OF COST

16

Sch. XLV-Form No. 134

Particulars	Details of actual measure				Contents of area
	No.	L.	B.	D.	
1/1) clearing & grubbing round land d-d					
TMB, P-1 = 0.378 m ³					
@ 76928.08/m ³ = Rs. 29078 = ∞					
2/2) Const. of subgrade & existing shoulder d-d					
TMB, P-15 = 753.052 m ³					
@ 173.51/m ³ = Rs. 130662 = ∞					
3/3) GSB Gr-II					
TMB, P-3 = 49.71 m ³					
@ 1495.094/m ³ = Rs. 74363 = ∞					
4/4) WBM Gr-II					
TMB, P-4 = 63.058 m ³					
@ 2715.49/m ³ = Rs. 171233 = ∞					
5/5) WBM Gr-III					
TMB, P-6 = 109.217 m ³					
@ 2787.22/m ³ = Rs. 304412 = ∞					
6/6) prime coat					
TMB, P-8 = 145.6.227 m ²					
@ 57.63/m ² = Rs. 83922 = ∞					
7/7) Tack coat					
TMB, P-12 = 7151.39 m ²					
@ 19.76/m ² = Rs. 141311 = ∞					
8/8) SDBC					
TMB, P-13 = 177.521 m ³					
@ 11659.51/m ³ = Rs. 2069808 = ∞					
					3007747 =

Continuation



Sch.XLV-Form No. 134 BIF 3007747E

Particulars	Details of actual measure				Contents of area
	No.	L.	B.	D.	
9/9 (I) km stone					
TWB, P-13 = 3 Nos.					
@ 2512.45/Ho = m.					7537.00
(II) 200m stone					
TWB, P-13 = 8 Nos.					
@ 7556.2/Ho = m.					6045.00
10/10 (I) 600mm equilateral triangle					
TWB, P-13 = 9 Nos.					
@ 4307.8/Ho = m.					38770.00
(II) 600mm circles					
TWB, P-13 = 9 Nos.					
@ 5757.41/Ho = m.					51817.00
(III) 600 x 450 Rectangles					
TWB, P-13 = 5 Nos.					
@ 5609.02/Ho = m.					28045.00
(IV) 900mm octagon stone					
TWB, P-13 = 4 Nos.					
@ 10197.57/Ho = m.					40790.00
(I/II) Boundary Pillars					
TWB, P-13 = 69 Nos.					
@ 641.86/Ho = m.					44288.00
(12/12) plainly of bars.					
TWB, P-13 = 85 Nos.					
@ 1305.10/Ho = m.					110933.00
(13/13) Road Melay in RT					
TWB, P-14 = 378.00 m ²					
@ 886.50/m ² continuation					335097.00

3671069E

Sch.XLV-Form No. 134 BIF-3671069

Particulars.	Details of actual measure				Contents of area
	No.	L.	B.	D.	
(14/14) pro & tang of masonry length of bund etc					
TMB, P-14 = 3.148					
Q 226.50/m ³ @ 12862.83/m ³					384082
2m. 38409					20
(15/15) brick masonry in cm (1:3) dg					
TMB, P-15 = 7.887 m ³					
Q 6281.03/m ³ = 14.49538					20
(16/16) plastering with (1:4) dg					
TMB, P-16 = 15.23 m ²					
Q 188.99/m ² = 14.2878					20
(17/17) painting two uniform surface etc					
TMB, P-17 = 16.62 m ²					2181
Q 139.16/m ² = 14.2313					20
(18/18) e/w in existing structure etc etc					
TMB, P-18 = 98.14 m ³					362082
Q 405.83/m ³ = 14.39829					20
(19/19) sand filling in foundation etc					
TMB, P-19 = 1.254 m ³					
Q 614.06/m ³ = 14.770					20
(20/20) providing PCC M15 (1:2:5) etc					
TMB, P-20 = 13.06 m ³					
Q 5256.21/m ³ = 14.68651					20
					38697032

Continuation

Particulars	Details of actual measure				Contents of area
	No.	L.	B.	D.	
(21/21) B/m work in CM (114) in foundry de d					
TMB, P-9 = 56.14 m ³					
@ 6037.23/m ³ = Rs. 338936					
(22/22) B/m work in CM (114) in substructure de d					
TMB, P-9 = 38.887 m ³					
@ 6314.82/m ³ = Rs. 245577					
(23/23) Plain / Reinforced concrete only de d					
TMB, P-10 = 4.068 m ³					
@ 249456/132.19/m ³ = Rs. 24946					
(24/24) mms Bitumen painting de d					
TMB, P-10 = 14.10 m ²					
@ 19.76/m ² = Rs. 279					
(25/25) RCC M/S Deck slab					
TMB, P-10 = 4.668 m ³					
@ 6754.24/m ³ = Rs. 3124					
(26/26) S/P/P bar reinforcement in superstructure de d					
TMB, P-10 = 0.884 MT					
@ 75323.53/MT = Rs. 43989					
(27/27) mms of heavy section steel de d					
TMB, P-11 = 15.0 m ²					
@ 5536/m = Rs. 838					

Continuation 4555392=

[illegible]

06.11.22

13