

ABSTRACT OF COST

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1/15/21	Restoration of				
	Rain culs of beam				
	of H.V.T.M.S.P. No. (38)				
	28-634m ² @ 379.59/m ²				10869 =
2/15/2	Making up of				
	Beam/shoulder				
	of H.V.T.M.S.P. No. (38)				
	62-10m ² @ 56.81/m ²				3528 =
3/15/2	Maintenance of				
	of RT surface				
	of H.V.T.M.S.P. No. (38)				
	5-732m ² @ 270.98/m ²				1554 =

4/15/9	Maintenance of				
	Road side				
	of H.V.T.M.S.P. No. (39)				
	0-06km @ 104.28/m ²				61 =
5/15/20	Cutting of branch of				
	tree				
	of H.V.T.M.S.P. No. (39)				
	1mas @ 106.12/m ²				106 =
					= 16118 =
Add @	12% S.T. = 14				1934 =
Add @	1% L.C = 14				161 =
	Total				18213 =
less	10% Reluct = 14				1821 =
	Net Total				16392 =

Continuation
 Awarded
 21/04/24
 SB


 21/04/2024
 AE