

Particulars	Details of actual measurement				Contents of area
	No	1	2	3	
	2nd year maintenance				
Name of work - Contd of p.c.					
U.L. Bridge at Borua					
River near Silauta village					
on Launiya-Kankariya					
path					
Agency - S.B. Engicon Pvt Ltd					
AGS No - 02/SBD/2021-22					
D.O.S - 19.5.21					
D.O.C - 18.5.23					
<u>1</u> (15.1) Restoration of rain cuts -					
with gail --- all m.					
$22 \times 2.50 \times 0.30 \times 0.25 = 4.125$					
$32 \times 2.75 \times 0.30 \times 0.25 = 6.60$					
$35 \times 2.0 \times 0.30 \times 0.25 = 5.25$					
$29 \times 2.75 \times 0.30 \times 0.25 = 6.58$					
$21 \times 1.50 \times 0.30 \times 0.25 = 2.36$					
					$= 24.9143$
<u>2</u> (15.2) making up of L.S					
of material/irregularities					
on shoulder --- m.					
$6 \times 11.6 \times 0.50 = 33.6m^2$					
$10 \times 2.0 \times 0.60 = 48.0$					
$2 \times 30.0 \times 0.60 = 36.0$					
$3 \times 4.0 \times 0.50 = 6.0$					
					$= 123.6m^2$

Particulars	Details of actual measurement				Contents of area
	No	L	B	H	
5 15.11) Maintenance of Dormer (sided) 6 m slope cell (1)			Bf	B	17641.00
Qty side p.nc - (56) T m B-					
0.139 km ² B 738.79 / km ² B					102.0
6 15.12 (10) Trimming of grass and weeds from the shoulder --- all					
Qty side p.nc - (56) T m B					
490.00 m ² B 2.33 / m ² B					1142.0
7 15.13) White washing two coat on parapet / railing --- all Corp					
Qty side p.nc - (56) T m B					
12.00 m ² B 21.48 / m ² B					258.0
				B	19144.0
Add 1 to Labour Const					191.0
Add 12 % Cr ST				+B	2297.0
Add 10 % S.E				+B	122.0
				B	21734.00
Corp 10.55 % below				B	2295.0
				B	19459.00
					241924
					DE