

1st Year Maint. Bill

Sch. XLV-Form No. 134

44

Particulars	Details of actual measurement				Contents of area
	No.	L	B	D	
Nhw- Maint- of Road from Babhi					
Senduar PMSY Road to Paham					
Harizan Tola		—	0.525	km	
Agency- Ravi Ranjan Kumar					
Agg-NO- 85/SBD/2020-21					
Date of start-		20-06-2020			
Date of comp.-		19/03/2021			
Actual date of comp.-		9/03/2022			
1. Restoration of Rainwater-					
Best Soil do — do-					
$2 \times 4.20 \times 1.40 \times 0.30 =$					3.52 m^3
$2 \times 6.50 \times 1.60 \times 0.30 =$					6.24 m^3
$3 \times 6.30 \times 1.55 \times 0.30 =$					8.78 m^3
$2 \times 3.20 \times 1.40 \times 0.30 =$					2.68 m^3
$2 \times 5.60 \times 1.50 \times 0.30 =$					5.04 m^3

06.26 m³

ABSTRACT OF COST

I. Restoration of Payments

Beim soll das das

Qty vide TM B P No - 44

4. No 1	26.26 m ³	@ 395.76 =	10393.20
---------	----------------------	------------	----------

2- Making up of Beams

Shoulder - ~~de~~ ~~de~~

Qty	vide TMB	P.No - 44
-----	----------	-----------

T.No. ② 147.355 m² ② 60.07 = 8852 = 3

3. Boerix Capsule with

Seal coat Dec --- do ---

Qty vide TMB P. No - 44

T.No 56925^m@ 289.20 = 2003-04

4. Maint. of HPC — do

Qty	vide TMB	P. No -
-----	----------	---------

Continuation

۲۰۲۳

