

2nd Year Maint. Bill

Sch. XLV-Form No. 134

Particulars	Details of actual measurement			Contents of area
	No.	L	B	D

N/w - Maint. of Road from Babhani

Sunder PMGSY Road to Pahari

Harijan Tola — 0.525 km

Agency - Ravi Rangan Kumar

Agg. No - 55/SBD/2020-21

Date of start - 20/06/2020

Actual date of comp. - 9/03/2022

① Restoration of Rainwater

Brooms soil — do — do

2x 2-60x1.5x0.30 = 5.04 m³

2x 4-20x1.40x0.30 = 3.52 m³

2x 6-50x1.60x0.30 = 6.24 m³

8-78 m³

2nd/2020

ABSTRACT OF COST

Sch. XLV-Form No. 134

5

Particulars	Details of actual measurement				Contents of area
	No.	L	B	D	

N/w-Maintn of Road from Babhani					
Senduar PMSY Road to Pahari					
Harigan Tola - 0.525 km					
Agency - Ravi Ramyan Kumar					
Ag. No - 55/SBP/2020-21					
Date of start - 20/06/2020					
Actual date of comp - 9/3/2022					
⑥. Restoration of Raincut					
Berms do - do -					
Qty vide TMB P. No - (48)					
I. No (3) 31.836 m ³ @ 395.76 = 12599 = ∞					
⑥. Making up of Berms					
Shoulder do - do -					
Qty vide TMB P. No - (48)					
I. No. (2) 177.025 m ² @ 60.07 = 10634 = ∞					

③/5 Patch repair Over road					
Wheels 20 mm premix do -					
Qty vide TMB P. No - (48)					
I. No (5) 14.03 m ² @ 289.20 = 4057 = ∞					
④/9 Maint. of Road signs -					
Qty vide TMB P. No - (49)					
I. No. (7) 0.06 km @ 1088.60 = 69 = ∞					
⑤/10 Maint. of 200m km stone					
Qty vide TMB P. No - (49)					
I. No (10) 0.08 km @ 628.24 = 49 = ∞					
⑥/7 Maint. of HPC - do -					
Qty vide TMB P. No - (48)					
I. No. 2. No (2) 1141.98 = 2284 = ∞					
⑦/11 Cutting and benching					

Sch. XLV-Form NO. 134

Particulars	Details of actual measurement			Contents of area
	No.	L	B	D
Qty vide TMBP No- (49)				
I. No- (11) 2. No @ 109.74 =				219.200
8/12 white washing on parapet wall door -				
Qty vide TMBP No- (49)				
I. No- (12) 42.0m ² @ 17.59 =				739.200
Total RS =				30650.200
Less 15 % Below RS =				4597.200
Net payable RS =				26053.200

Ref. 2/03/24
JE

At 02/05/24
AT

For work
11/2