



# 3rd Year Maintenance bill

Sch. XLV-Form No. 134 **37**

| Particulars                         | Details of actual measurement |      |      |      | Contents of area                  |
|-------------------------------------|-------------------------------|------|------|------|-----------------------------------|
|                                     | No.                           | L    | B    | D    |                                   |
| N/W —                               | Maintenance of road           |      |      |      |                                   |
|                                     | from Annual Pradhan Mantri    |      |      |      |                                   |
|                                     | Sadak to Annual Bazar         |      |      |      |                                   |
|                                     | Annam piyano gawan            |      |      |      |                                   |
|                                     | note hje.                     |      |      |      |                                   |
| N/Agency —                          | Sri. Sandeep Kumar.           |      |      |      |                                   |
| Agg No —                            | 28 SBD/2018-19                |      |      |      |                                   |
| A.D. O.C —                          | 17.12.2021                    |      |      |      |                                   |
| ① Restoration of Raincut/Berms.     |                               |      |      |      |                                   |
|                                     | with soil, mookum etc.        |      |      |      |                                   |
|                                     | 10                            | 2.70 | 0.60 | 0.30 | 4.86                              |
|                                     | 12                            | 3.0  | 0.55 | 0.30 | 5.94                              |
|                                     | 13                            | 3.50 | 0.65 | 0.30 | 8.87                              |
|                                     | 12                            | 2.80 | 1.50 | 0.30 | 15.12                             |
|                                     | 15                            | 3.50 | 0.50 | 0.30 | 14.17                             |
|                                     |                               |      |      |      | = 48.96 m <sup>3</sup>            |
|                                     |                               |      |      |      | Qty Limit = 48.79 m <sup>3</sup>  |
| ② Making up of Berms/shoulder       |                               |      |      |      |                                   |
|                                     | 2                             | 6.50 | 0.65 |      | 8.45                              |
|                                     | 8                             | 5.40 | 0.90 |      | 38.88                             |
|                                     | 9                             | 9.80 | 0.50 |      | 83.79                             |
|                                     | 10                            | 5.40 | 0.50 |      | 48.60                             |
|                                     | 12                            | 6.50 | 0.65 |      | 50.70                             |
|                                     | 8                             | 5.70 | 0.90 |      | 41.04                             |
|                                     |                               |      |      |      | = 271.46 m <sup>2</sup>           |
|                                     |                               |      |      |      | Qty Limit = 271.03 m <sup>2</sup> |
| 3-① Repair of pot holes filled with |                               |      |      |      |                                   |
|                                     | 75mm BM —                     |      |      |      |                                   |
|                                     | 2                             | 1.50 | 0.50 |      | 1.50                              |
|                                     | 1                             | 1.00 | 1.70 |      | 1.70                              |
|                                     |                               |      |      |      | = 3.20 m <sup>2</sup>             |
|                                     |                               |      |      |      | Qty Limit = 3.16 m                |

Continuation



# Abstract of cost

Sch. XLV-Form No. 134 37

| Particulars                                             | Details of actual measurement |        |   |          | Contents of area |
|---------------------------------------------------------|-------------------------------|--------|---|----------|------------------|
|                                                         | No.                           | L      | B | D        |                  |
| ① Restoration of Raincut/Berms with soil, muck etc.     |                               |        |   |          |                  |
| ↑MB/P-37                                                |                               | 48.79  | @ | 356.77   | = 17407.00       |
| ② Making up of Berms/Shoulder                           |                               |        |   |          |                  |
| ↑MB/P-37                                                |                               | 271.03 | @ | 53.25    | = 14432.00       |
| 3-① Repair of Pot holes filled with                     |                               |        |   |          |                  |
| ↑MB/P-37                                                |                               | 3.16   | @ | 11153.43 | = 35245.00       |
| 3-② Patch repair over pot holes.                        |                               |        |   |          |                  |
| ↑MB/P-38                                                |                               | 4233   | @ | 231.18   | = 9753.00        |
| ④ Maintenance of C/P work (HPC)                         |                               |        |   |          |                  |
| ↑MB/P-38                                                |                               | 2.00   | @ | 1095.22  | = 2190.00        |
| 5-① Cutting of branches of trees                        |                               |        |   |          |                  |
| ↑MB/P-38                                                |                               | 2.00   | @ | 103.62   | = 207.00         |
| 5-② Trimming of grass and weeds.                        |                               |        |   |          |                  |
| ↑MB/P-38                                                |                               | 15.00  | @ | 2.12     | = 32.00          |
| 5-③ Cutting of shrubs from roadway                      |                               |        |   |          |                  |
| ↑MB/P-38                                                |                               | 6.00   | @ | 6.37     | = 38.00          |
| ⑥ white washing of parapet walls of C/P work and trees. |                               |        |   |          |                  |
| ↑MB/P-38                                                |                               | 42.00  | @ | 16.00    | = 672.00         |
|                                                         |                               |        |   |          | = 79976.00       |

## Material Statement

- ① E/W — 8944m<sup>3</sup>
- ② Stone metal — 3.17m<sup>3</sup>
- ③ crushed stone chips — 0.09m<sup>3</sup>
- ④ Bitumen (5-90) — 0.006MT
- ⑤ Bitumen emulsion (RS1) — 0.001MT

Continuation

Kishor  
10/11/24  
EE