

4th Year Maintenance Roll

53

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of Road	Maintenance of Road				
from NH 30 A	Babaka Dhaba To				
	from Vishanpur Mahadev Jola.				
Agency	Griha Construction				
App. No.	86 SBD/2018-19				
Actual date of completion	20/02/2020				

MEASUREMENT

① Restoration of rain cuts

.....20.....20.....612					
48x	0.60	1.20	0.30	10.368 m ³	
46x	0.75	1.20	0.30	12.420 m ³	
42x	0.90	1.20	0.30	13.608 m ³	
36x	1.15	1.20	0.30	14.904 m ³	
28x	1.35	1.15	0.30	13.041 m ³	
18x	1.75	1.15	0.30	10.868 m ³	
44x	0.80	1.15	0.30	12.144 m ³	
38x	1.15	1.15	0.30	16.388 m ³	
14x	1.55	1.10	0.30	7.161 m ³	
8x	2.15	1.10	0.30	5.676 m ³	
6x	2.90	1.10	0.30	5.742 m ³	
18x	1.30	1.10	0.30	12.252 m ³	
11	Limit	122	31 m ³	1.121 m ³	

② Maintenance of earthen shoulder

.....20.....20.....41					
2x	12x	6.40x	1.20	184.32 m ²	
2x	8x	9.65x	1.20	185.28 m ²	
2x	6x	11.75x	1.20	169.20 m ²	
2x	4x	15.40x	1.10	135.52 m ²	
Continuation				674.32 m ²	

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
③ Repair of Pot holes filled with Bm					
.....20.....					
	56	0.60	0.50	0.075	1.260 m ³
	48	0.75	0.60	0.075	1.620 m ³
	42	0.90	0.80	0.075	2.268 m ³
	14	1.20	0.90	0.075	1.134 m ³
	8	1.75	1.35	0.075	1.418 m ³
	2	2.50	1.95	0.075	0.731 m ³
					8.431 m ³
④ Patch Repair concrete Pot holes					
.....20.....					
	56	0.60	0.50		16.80 m ²
	48	0.75	0.60		21.60 m ²
	42	0.90	0.80		29.24 m ²
	14	1.20	0.90		15.12 m ²
	8	1.75	1.35		18.90 m ²
	2	2.50	1.95		9.75 m ²
					112.41 m ²
⑤ Maintenance of H.P Culvert					
.....20.....					
	3.00 mtrs.				3.00 mtrs.
⑥ Maintenance of Road Sign					
.....20.....					
	1.510 K.M.				1.510 K.M.
⑦ Maintenance of K.M. H. Stone					
.....20.....					
	1.510 K.M.				1.510 K.M.

Continuation

Continuation

Sch. XLV-Form No. 134

Sch. XLV-Form No. 134					Contents of area
Particulars	Details of actual measurement				
	No.	L.	B.	D.	
ABSTRACT OF COST					
① Restoration of road cuts					
.....20.....20.....61					
122.31 m ² VTMBP-53					
@ Rs 42.706/m ²					Rs 50482.00
② Maintenance of earthen shoulder					
.....20.....20.....61					
674.32 m ² VTMBP-53					
@ Rs 58.176/m ²					Rs 99229.00
③ Repair of pot holes filled with BM					
.....20.....20.....61					
8.431 m ³ VTMBP-54					
@ Rs 10276.851/m ³					Rs 86644.00
④ Patch repair for pot holes					
.....20.....20.....61					
112.41 m ² VTMBP-54					
@ Rs 256.49/m ²					Rs 28832.00
⑤ Maintenance of H.P. culvert					
.....20.....20.....61					
3.00 H.P. VTMBP-54					
@ Rs 1109667/H.P.					Rs 3328.00
⑥ Maintenance of Road bym					
.....20.....20.....61					
1.510 km. VTMBP-54					
@ Rs 1055.70/km.					Rs 1594.00
					Rs 210105.00
Continuation					

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	B.P.			13	210105=00
② Maintenance of K.M. & H. Stone					
.....20.....20.....E ₁₂					
1.510K.M. VTM P-54					
	@ 13 675.98/KM			13	1021200
③ Cutting of branches of tree					
.....20.....20.....E ₁₂					
3.00 Nos VTM P-55					
	@ 13 115.923/Nos			13	348=00
④ Cutting of shrubs from ver. Dway					
.....20.....20.....E ₁₂					
12.00 Nos VTM P-55					
	@ 13 6.434/Nos			13	38=00
⑤ Trimming of grass & weeds					
.....20.....20.....E ₁₂					
30.00 m ² VTM P-55					
	@ 13 2.16/m ²			13	65=00
⑥ White washing of Panchrat walls					
.....20.....20.....E ₁₂					
61.92 m ² VTM P-55					
	@ 13 16.36/m ²			13	1013=00
				13	212630=00
(Less 10% Boleo)				13	21263=00
				13	191367=00
c/s					
M.O.					
13/12/17					
AE					

Continuation

DAO
C.P.
13/12/17

Continuation
24/12/17
AE
Chander