

Const. of Road CD Works with 5 Years Maint.
of Athari to Runni Pmgsy Path Shivnagar
Naya Bas. Under Mmgsy-NDB Scheme.

Schedule XLV - Form No. 134 (Mmgsy-NDB)

DIVISION

BLOCK - Runnisaidpur. SUB-DIVISION

AGREEMENT No.-085BD/2023-24.

MEASUREMENT BOOK-568

Printed at - Soni Printers, Chandralok Chowk, Muz.

Name of Agency- PRASHANT BHASKAR.

Schedule XLV-FORM No. 13410

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(1/4) P.C. at road end					
at road end					
pillar at - do -					
5m					
Qty side mB, P-01, itm-01					
0.415 m ³ @ 5 92232.08/m ³ = 19638 ~					
(2/4) clearing & grubbing					
road end at - do -					
5m					
Qty side mB, P-01, itm-02					
0.163 ha @ 5 2572.39/ha = 12318 ~					
(3/4) Excavation for road					
in soil - do - do -					
5m					
Qty side mB, P-01, itm-03					
2.32 m ³ @ 5 125.85/m ³ = 3232 ~					
(4/4) Cost of subgrade					

for road way section					
at - do -					
Qty side mB, P-02, itm-04					
10.40 m ³ @ 5 51.52/m ³ = 640 ~					
(5/5) Excavation for road					
work in soil - do -					
- do - do -					
5m					
Qty side mB, P-02, itm-05					
12.32 m ³ @ 5 103.76/m ³ = 1801 ~					
(6/6) Cost of subgrade					
obtained from borrow					
pit - do - do - do -					
5m					
Qty side mB, P-02, itm-06					
151.88 m ³ @ 5 140.15/m ³ = 21286 ~					
(7/7) Cost of subgrade					
earthwork should be					
- do - do -					
5m					

Schedule XLV-FORM No. 134 11

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
22.10 m ² vide TMB, P-03, item-01					
128.02 m ² vide TMB, P-06, item-02					
250.52 m ² @ 0.222.00/m ² b					57960 m
(9/8) Cont. of 650-I-01					
- do - do -					
99.16 m ² vide TMB, P-03, item-02					
218.19 m ² vide TMB, P-03, item-01					
317.35 m ² @ 0.3919.19/m ² b					1243438 m
(9/9) P/L/S/C work - III - do -					
- do - do -					
do m					
99 vide TMB, P-05, item-01					
132.09 m ² @ 5386.50/m ² b					711503 m
(10/8) P/A prime coat					
(SS-2) - do - do -					
SL					
99 vide TMB, P-06, item-01					
120.14 m ² @ 58.01/m ² b					102163 m

(11/11) P/A Tack coat (R5-3)					
- do - do - SL					
99 vide TMB, P-06, item-01					
1261.19 m ² @ 19.88/m ² b					35012 m
(12/12) P/L/R of mass of					
200 mm thick do - do -					
SL					
99 vide TMB, P-06, item-02					
261.19 m ² @ 322.07/m ² b					567226 m
(13/13) Rec mis grade					
100 mm stone - do -					
- do -					
99 vide TMB, P-08, item-1(9)					
01 m ² @ 3196.63/m ² b					3187 m
(14/14) Rec mis grade					
200 mm stone - do -					
- do -					
99 vide TMB, P-08, item-1(6)					
02 m ² @ 871.93/m ² b					1749 m
(15/15) P/A of material					

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Sign board - do -					
- do - do -					
Qty side TMB, P-02, itn - 200					
01 no @ 5485.21/m					4165m
16/15(b) P/F net - net					
new boundary d.p.					
board - do - do -					
- do - do -					
Qty side TMB, P-02, itn - 200					
01 no @ 5537.168/m					5537m
7/18(b) P/F net - net					
Sign board - do -					
- do - do -					
Qty side TMB, P-08, itn - 200					
01 no @ 2665.323/m					2665m
18/15(b) P/F net - net					
22m board - do -					

- do - do -					
Qty side TMB, P-08, itn - 200					
01 no @ 5396.732/m					5397m
(15/16) P/L HGT of					
at 2.5m mod - net					
- do - do -					
Qty side TMB, P-05, itn - 01					
01 no @ 284.81/m					284.2m
(20/18) P/F net - net					
to place identification					
board - do - do -					
- do - do -					
Qty side TMB, P-09, itn - 10					
02 no @ 14000.23/m					2800m
(21/12) planting of trees					
by road side					
- do - do -					
- do - do -					

