

Schedule XLV-Form No. 134

1894

S.T.

Tampani aadnissi to/a should

DIVISION

border to Parish's many Road.

CHANDAN

SUB-DIVISION

Arun Kader

MEASUREMENT BOOK

~~246124 44p~~

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
3rd year maintenance					
Name of work → Construction of Road Jamtani Aadiwasi Tola Jharokhand Boudan to Puriher PMGSY Road					
Agency Name - Sri Arun Jeevan					
Ag. No - 53 SBD / 2019 - 20					
Maintenance of year					
	06-01-		2023		
	05-01-		2024		
① Restoration of drain cuts berms with soil mass					
do do					
2 x 4.00 x 1.00 x 0.300 =					2.40 m ³
3 x 8.00 x 0.750 x 0.300 =					5.04 "
2 x 5.00 x 0.800 x 0.300 =					2.40 "
2 x 6.00 x 0.900 x 0.300 =					3.24 "
2 x 5.00 x 1.00 x 0.300 =					3.00 "
3 x 8.00 x 0.90 x 0.300 =					6.48 "
2 x 4.50 x 1.10 x 0.300 =					2.97 "
2 x 5.00 x 0.80 x 0.300 =					2.40 "
2 x 9.00 x 1.00 x 0.300 =					5.40 "
3 x 3.00 x 0.80 x 0.300 =					2.16 "
2 x 4.00 x 0.80 x 0.300 =					2.16 "

Continuation

Material	Requirement	
Bitumen 3-40	=	0.610 MT
Emulsion SS-1	=	0.087 MT
Agg	=	9.844 m ³
Other work	=	62.64 m ³

Material Statement

Bitumen's 3-90	=	0.610MT
----------------	---	---------

Emulsion SS-1	=	0.087 MT
---------------	---	----------

Agg			11		9.844 m ³
-----	--	--	----	--	----------------------

~~Earthwork = 62.64 m³~~

2/2/2