

कार्यपालक अभियन्ता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमण्डल, सहरसा

पत्रांक 2287/430

सहरसा, दिनांक 24.12-2024/

प्रेषक:-

कार्यपालक अभियन्ता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, सहरसा।

सेवा में,

नोडल पदाधिकारी,
3054 (MR) कोषांग,
बिहार, पटना।

विषय:- शीर्ष 3054 नई अनुरक्षण नीति-2018 अंतर्गत Initial Rectification and Surface renewal. कराये गये कार्य हेतु अधियाचना के संबंध में।

महाशय,

उपर्युक्त विषयक कहना है कि विहित प्रपत्र में संलग्न विवरणी के अनुसार शीर्ष Mr 3054 New Maintenance Policy-2018. अन्तर्गत Smada Pakki Sadak Thakurbari Chulhai Mehta 'House To Sharma Tola Umakant'House पथ का Initial Rectification and Surface renewal कराये गये कार्य हेतु राशि Rs 18.12277/- (रूपये अठारह लाख बारह हजार दौ सौ सतहतर मात्र) की आवश्यकता है।

अतः कार्यहित में अनुरोध है कि उक्त अधियाचित Rs 18.12277/- (रूपये अठारह लाख बारह हजार दौ सौ सतहतर मात्र) उपलब्ध कराने की कृपा की जाय ताकि कराये जा रहे कार्यो का विपत्र भुगतान किया जा सके।

- अनु०:- (1) अधियाचना प्रपत्र
(2) IRI Value Report
(3) Map
(4) प्रमाण-पत्र।

विश्वासभाजन

24/12/24


कार्यपालक अभियन्ता
ग्रा०का०वि०, कार्य प्रमण्डल,
सहरसा

Rural Works Department
MIR NEW MAINTENANCE POLICY-2018 ALLOTMENT & REQUISITION

Name of Division:- RWD Works Division Saharsa

SL. No.	Year	Name of Road	Name of Contractor (In English)	Project Id	Administrative Sanction			Agreement Amount (In Laes)		Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Allotment Received (in Laes)	Total Expenditure as per MIS (in Laes)	Value of Measurement (in Laes)	Current Demand (in Laes)	Remarks
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	
12	2023-24	Smada Paki Sadak Thakurbari Chulhai Mehta House To Sharma	Anvind Kumar	20904313025	1.240	64.702	51.47285	11.99915	2860	25	5%	0.00000	0.00000	18.12277	18.12277	BT Work Complete	

[Signature]
24/12/24
DAO
RWD Works Division
Saharsa

[Signature]
24/12/24
Executive Engineer
RWD Works Division
Saharsa

**OFFICE OF THE EXECUTIVE ENGINEER
RWD WORKS DIVISION SAHARSA.**

Name of Scheme:- Smada Pakki Sadak Thakurbari Chulhai Mehta 'House To Sharma Tola Umakant' House -, PACKAGE No- RM/SA/SAH/24/0002, Project ID-20904313025.

**Certified that all item wise 100%
Measurement has been taken by me**



Junior Engineer
RWD Work section Saurbazar
Works Division Saharsa

**Certified that all item wise 50%
Measurement has been cheked by me**



Assistant Engineer
RWD Work Section Saurbazar
Works Division Saharsa

**Certified that all item wise 10%
Measurement has been cheked by me**



Executive Engineer
Rural work Department
Works Division Saharsa

Name of Road - Smada Pakki Sadak Thakurbari Chulhai Mehta 'House To Sharma Tola Umakant' House

Name of Contractor Arvind Kumar						Batch Name -RM/SA/SAH/24/0002					
Date	Time	Section	Length	Bumps	Speed	OR	IRI	CATEGOR	Latitude	Longitude	Event
		No.	in km	in mm	Rate	mm/km	mm/km	ROAD			
23.12.2024	12-05-26	88	0.100	190	10.1	1900	2380	G	25.846662	86.632671	Normal
23.12.2024	12-05-59	88	0.100	270	10.1	2700	3167	G	25.847412	86.632931	Normal
23.12.2024	12-06-17	88	0.100	190	10.1	1900	2380	G	25.850370	86.634875	Normal
23.12.2024	12-06-44	88	0.100	210	10.1	3000	3462	G	25.852019	86.636708	Normal
23.12.2024	12-07-26	88	0.100	180	10.1	2000	2478	G	25.852724	86.636943	Normal
23.12.2024	12-07-51	88	0.100	270	10.1	2700	3167	G	25.853858	86.637406	Normal
23.12.2024	12-08-23	88	0.100	210	10.1	3000	3462	G	25.854378	86.637750	Normal
23.12.2024	12-08-42	88	0.040	190	10.1	1900	2380	G	25.854479	86.347751	Normal
						Total	22876				
						Average	2860				

$$Y = 0 * X^2 + 0.984 * X + 510.7$$

$$X = 2100$$

$$Y = 2577$$

(R) RURAL ROAD

Good	Average	Poor
<4000	4001-5000	>5001


12/24
JE

24.12.24
A.C

24/12/24
CE

File :D:\STECO-USB-GPS V1_1_1\18050845.Xls, Section No. :88, Eqn : $Y = 0 * X^2 + 1.136 * X - 181$

Name of Customer :ARBIND KUMAR, Name of Work/ Road :Smada Pakki Sadak Thakurbari Chulhai Mehta 'House



1/24/12/24
JE

24.12.24
A-E

Bas
24/12/24
EE